

Scilab Textbook Companion for  
Metal Cutting Theory And Practice  
by D. A. Stephenson And J. S. Agapiou<sup>1</sup>

Created by  
Venkata Ajay Kumar G  
M Tech  
Mechanical Engineering  
Jntu Anantapur Aits Rajampet  
College Teacher  
None  
Cross-Checked by  
None

July 18, 2019

<sup>1</sup>Funded by a grant from the National Mission on Education through ICT, <http://spoken-tutorial.org/NMEICT-Intro>. This Textbook Companion and Scilab codes written in it can be downloaded from the "Textbook Companion Project" section at the website <http://scilab.in>

# Book Description

**Title:** Metal Cutting Theory And Practice

**Author:** D. A. Stephenson And J. S. Agapiou

**Publisher:** Crc Taylor & Francis.

**Edition:** 3

**Year:** 2016

**ISBN:** 978-1-4665-8754

Scilab numbering policy used in this document and the relation to the above book.

**Exa** Example (Solved example)

**Eqn** Equation (Particular equation of the above book)

**AP** Appendix to Example(Scilab Code that is an Appednix to a particular Example of the above book)

For example, Exa 3.51 means solved example 3.51 of this book. Sec 2.3 means a scilab code whose theory is explained in Section 2.3 of the book.

# Contents

List of Scilab Codes	4
2 Metal Cutting Operations	5
3 Machine Tools	18
4 Cutting Tools	19
5 Toolholders and Workholders	24
6 Mechanics of Cutting	29
9 Tool Wear and Tool life	32
10 Surface Finish Integrity and Flatness	34
13 Machining Economics and Optimization	36
16 Accuracy and Error Compensation of CNC Machining Systems	39

# List of Scilab Codes

Exa 2.1	Calculation of Material removal rate and Power and Torque required by the spindle and main cutting force . . . . .	5
Exa 2.2	Calculation of Machining Time . . . . .	6
Exa 2.3	Calculation of uncut chip thickness and Cutting Edge engagement . . . . .	6
Exa 2.4	Calculation of Taper on the sidewall of the workpiece . . . . .	7
Exa 2.5	Calculation of Material Removal Rate . . . . .	8
Exa 2.6	Calculation of Material Removal Rate . . . . .	9
Exa 2.7	Calculation of Machining Time . . . . .	10
Exa 2.8	Calculation of Maximum feed rate and Machining time . . . . .	11
Exa 2.9	Calculation of Maximum power and Cutting time and Perpendicularity of the flange . . . . .	12
Exa 2.10	Calculation of Number of teeth on the broach and length of the broach part axis and cutting time and cutting force . . . . .	13
Exa 2.11	Calculation of Machining Time . . . . .	14
Exa 2.12	Calculation of Material Removal Rate and Cutting Time and Torque on the drill . . . . .	15
Exa 2.13	Calculation of Material Removal Rate and Machining Time . . . . .	16
Exa 2.14	Calculation of Power required to Grind and the Machining Time . . . . .	17
Exa 3.1	Calculation of Stiffness of a Strut . . . . .	18
Exa 4.1	Calculation of Material Removal Rate for both the drill and the tap . . . . .	19

Exa 4.2	Calculation of Change in Machining Time for Drilling and Tapping the hole . . . . .	20
Exa 4.4	Calculation of the Deflection at the tool point for bar A and Deflection for Heavy Metal and Deflection for bar B . . . . .	21
Exa 5.3	Calculation of total balancing grade . . . . .	24
Exa 5.4	Calculation of Unbalance force reduction . . . . .	25
Exa 5.5	Calculation of allowable unbalance for a balance quality grade . . . . .	25
Exa 5.6	Determining the effect of toolholder clamping length . . . . .	26
Exa 5.8	Calculation of deflection at the tool point . . . . .	26
Exa 6.1	Calculation of mean angle of friction and mean shear stress and mean frictional stress and average strain rate and percentage of total energy estimated to go into secondary deformation zone . . . . .	29
Exa 6.2	Calculation of Tangential force and feed force . . . . .	30
Exa 9.2	Calculation of parameters for the extended Taylor tool life equation . . . . .	32
Exa 10.1	Calculation of Maximum feed . . . . .	34
Exa 10.2	Calculation of Corner Radius . . . . .	34
Exa 13.2	Calculation of Production cost for a rough turning . . . . .	36
Exa 13.3	Calculation of Minimum Production Cost . . . . .	37
Exa 16.1	Calculation of magnitude of the Abbe error . . . . .	39

## Chapter 2

# Metal Cutting Operations

Scilab code Exa 2.1 Calculation of Material removal rate and Power and Torque requ

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 2.1
4 // Given that
5 D_one = 50 //Initial diamter in mm
6 f = 0.4 // Feed for the tool in mm/rev
7 d = 4 // Depth of cut in mm
8 v = 70 // Cutting speed in m/min
9 u_s = 0.065 // Specific cutting energy is obtained
   from Table 2.1 units kW/cm3/min
10 mrr = v*f*d // Material Removal Rate and 1000 mm/m
   is for the conversion
11 P = mrr*u_s // The machining power required in the
   turning operation
12 D_two = D_one - (2*d)
13 N = (2*v*1000)/(pi*(D_one+D_two)) // The Speed (rpm
   ) - 1000 value is for the conversion 1000 mm/m
14 T = (P*1000*60)/(2*pi*N) // Spindle Torque
15 printf("\n The Material Removal Rate = %.0f cm3/min
   , \n The Machining Power = %.2f kW, \n Torque
```

```
    required by the Spindle = %.0f N m",mrr,P,T)
16 // The answers vary due to round off error
```

---

### Scilab code Exa 2.2 Calculation of Machining Time

```
1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.2
4 // Given that
5 D_one = 50 //Initial diamter in mm
6 f = 0.4 // Feed for the tool in mm/rev
7 d = 4 // Depth of cut in mm
8 v = 70 // Cutting speed in m/min
9 u_s = 0.065 // Specific cutting energy is obtained
    from Table 2.1 units kW/cm^3/min
10 L = 150 // Axial length of the outer diameter in mm
11 La = 3 // Approach distance in mm (assumption)
12 D_two = D_one - (2*d)
13 N = (2*v*1000)/(%pi*(D_one+D_two)) // The Speed (rpm
    ) - 1000 value is for the conversion 1000 mm/m
14 tm = (L+La)/(f*N) // Machining time in Minutes
15 tm_s = ((L+La)/(f*N))*60
16 printf("\nThe Machining time = %.3f min, \nThe
    Machining time in Seconds = %.1f s",tm,tm_s)
17 // The answers vary due to round off error
```

---

### Scilab code Exa 2.3 Calculation of uncut chip thickness and Cutting Edge engagement

```
1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.3
```



```

4 // Given that
5 D_one = 50 //Initial diamter in mm
6 f = 0.4 // Feed for the tool in mm/rev
7 d = 4 // Depth of cut in mm
8 v = 70 // Cutting speed in m/min
9 kappa = 20 // Lead angle of the tool in degrees
10 s = 0.053 // Specific cutting energy is obtained
    from Table 2.1 units kW/cm^3/min
11 a = f*cosd(kappa) // The uncut (nominal) chip
    thickness in mm
12 Lm = d*s*(kappa)
13 printf("\nThe uncut (nominal) chip thickness = %.3f
    mm, \n The cutting edge engagement = %.3f mm",a,
    Lm)
14 // The answers vary due to round off error

```

---

Scilab code Exa 2.4 Calculation of Taper on the sidewall of the workpiece

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.4
4 // Given that
5 V = 100 // Cutting Velocity in m/min
6 D = 75 // Diameter of the workpiece in mm
7 l = 200 // Length of the cut in mm
8 d = 5 // Depth of cut in mm
9 ad = 80 // Axial depth of cut in mm
10 rd = 5 // Radial depth of cut in mm
11 amax = 0.2 // Maximum uncut chip thickness in mm/
    rev
12 E = 400000 // Modulus of elasticity of the material
    in N/mm^2
13 us = 0.08 // Unit specific energy for work material
    from Table 2.1 in kW/cm^3/min

```

```

14 nt = 4
15 N = V*1000/(%pi*D) // Spindle rotational speed in
    rpm so with 1000 multiplying
16 vm = acosd(1-((2*d)/D))
17 ft = amax / sind(vm) // Feed per tooth in mm
18 fr = nt*ft*N // Feed rate for the cutter in mm/min
19 cs = ad*rd // Cross-sectional area of uncut chip in
    mm^2
20 mrr = cs*fr // Material removal rate in mm^3/min ,
    in Power required convert to cm^3/min divide by
    1000
21 P = (mrr/1000)*us // Power required for the
    operation
22 F = (P*1000*60)/V // Cutting force , where 1000 is
    for converting kW to Nm/s and 60 for s/min
23 Fr = 0.3*F // Radial Force, Radial component is 30%
    of the cutting (tangential) force
24 //delta = (Fr*)
25 I = (%pi*(0.8*D)^4)/64
26 deflection = (Fr*l^3)/(3*E*I)
27 taper_error = D*(deflection/(2*l))
28 printf("The taper on the sidewall of the workpiece =
    %.4f ",taper_error)
29 // The answer provided in the textbook is wrong

```

---

### Scilab code Exa 2.5 Calculation of Material Removal Rate

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.5
4 // Given that
5 D = 50 // Diameter of the cutter in mm
6 IC = 17 // IC size of the round inserts in mm
7 d = 3 // Depth of cut in mm

```

```

8 nt = 3 // Number of inserts
9 V = 150 // Cutting speed in m/min
10 amax = 0.2 // Maximum uncut chip thickness in mm/
    tooth feed
11 De = D - IC + sqrt((IC^2)-((IC-(2*d))^2)) // The
    Effective tool diameter
12 vm = acosd(1-((2*d)/IC))
13 N = V*1000/(%pi*De) // The spindle speed should be
    calculated based on the effective diameter in cut
    in rpm
14 ft = amax / sind(vm)
15 fr = nt*ft*N // The feed rate of the cutter in mm/
    min
16 b = De // Radial depth of cut in mm
17 mrr = d*b*fr // Material removal rate in mm^3/min
18 printf("\n\nThe Material removal rate = %.0f mm^3/min
    ",mrr)
19 // The answers vary due to round off error
20 // The answer provided in the textbook is wrong for
    the mrr

```

---

### Scilab code Exa 2.6 Calculation of Material Removal Rate

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.6
4 // Given that
5 d = 6 // Depth of cut in mm
6 D = 25 // Diameter of the tool in mm
7 a_max = 0.2 // Feed in mm/tooth
8 V = 150 // Cutting speed in m/min
9 nt = 2
10 b = 11 // Radial doc will be half of the effective
    diameter

```

```

11 De = 2*sqrt((d*(D-d))) // Effective tool diameter
12 // Effective tool diameter is not the actual cutter
    diameter because the axial depth of cut is
    smaller than the radius of the ballnose
13 // Since the depth of cut is significantly smaller
    than the radius of the nose chip thinning occurs
14 vm = acosd (1-((2*d)/D))
15 ft = a_max/sind(vm)
16 N = (V*1000)/(%pi*De) // Spindle speed in rpm and
    Effective tool diameter need to be considered
17 // The answers vary due to round off error
18 fr = nt * ft * N // Feed rate of the cutter
19 mrr = d*b*fr // Material removal rate in mm3/min
20 printf("\n The Material Removal Rate = %.0f mm3/min
    ",mrr)
21 // The answer provided in the textbook is wrong

```

---

### Scilab code Exa 2.7 Calculation of Machining Time

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.7
4 // Given that
5 V = 300 // Cutting speed in m/min
6 D = 200 // Diameter of the face milling cutter in mm
7 ai = 0.3 // un-cut chip thickness in mm
8 k = 45 // Lead angle of the cutter in degrees
9 b = 150 // width of the cut in mm
10 L = 700 // Length of the cut in mm
11 nt = 18 // Number of inserts on the cutting tool
12 N = V*1000/(%pi*D) // Spindle rotational speed in
    rpm
13 ft = ai/cosd(k) // Feed per tooth in mm
14 fr = nt*ft*N // Feed rate of the cutter in mm/min

```

```

15 Le_max = (D/2)+(D/2) // Maximum length the cutter
    can travel
16 Le = (D/2)-((1/2)*(sqrt((D^2)-(b^2)))) // Length of
    the approach in mm
17 tm = (L+Le)/fr // Machining time in min
18 printf("\n The Machining time = %.2f min",tm)

```

---

**Scilab code Exa 2.8** Calculation of Maximum feed rate and Machining time

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.8
4 // Given that
5 L = 400 // Length of the part in mm
6 P = 10 // Maximum available cutting power in kW
7 us = 0.07 // Specific energy for the workpiece
    material from Table 2.1 in W.min/cm^3
8 d = 15 // Radial depth of cut in mm
9 b = 10 // Width of cut in mm
10 V = 80 // Cutting speed in m/min
11 D = 200 // Diameter of the carbide brazed side
    milling cutter in mm
12 R = 100 // Radius of the carbide brazed side milling
    cutter in mm
13 nt = 16 // Number of inserts on the cutter
14 n_t = 8 // Number of inserts which are one side of
    the cutter
15 a_max = 0.2 // Maximum uncut chip thickness in mm
16 L_e = 52.7 // Approach distance in mm
17 mrr = P / us // Material removal rate in cm^3/min
18 fr = (mrr*1000) / (d*b) // Feed rate in mm/min
19 N = V*1000/(%pi*D) // Speed of the spindle in rpm
20 ft = fr / (nt*N) // Feed rate for the cutter in mm/
    rev/tooth

```

```

21 V_m = acosd((R-d)/R)
22 f_t = a_max/sind(V_m) // Maximum feed per tooth
    allowed in mm/rev/tooth
23 t_m = (L+L_e+10)/(n_t*f_t*N)
24 t_m = (L+L_e+10)/(n_t*f_t*N)
25 printf("\n Maximum feed per tooth allowed = %.3f mm
    ^/rev/tooth,\n Machining time to groove the part
    = %.3f min,\n Machining time to groove the part
    with 8 inserts = %.3f min",f_t,t_m,t_m)
26 // If the cutter has 16 inserts in total, the
    effective number of teeth is 8 because 8 inserts
    on one side of the cutter and 8 overlapping
    inserts on the other side are used to remove the
    full width of 10 mm

```

---

### Scilab code Exa 2.9 Calculation of Maximum power and Cutting time and Perpendicular

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.9
4 // Given that
5 D = 200 // Outside diameter of the flange in mm
6 Di = 100 // Inside diameter of the flange in mm
7 N = 400 // Maximum rotational speed in rpm
8 L = 500 // Length of the tube in mm
9 ft = 0.25 // Maximum feed rate in mm/rev
10 d = 8 // Depth of cut in mm
11 us = 0.025 // Specific Energy from Table 2.1 in W.
    min/cm^3
12 E = 50000 // Modulus of elasticity of the material
    in N/mm^2
13 mrr = (%pi*D*N*ft*d) // Material removal rate in mm
    ^3/min
14 P = (mrr/1000)*us // Maximum power require in kW (

```

```

    the conversion unit of 1000 to formula for mm to
    cm)
15 tm = (D-Di)/(2*ft*N)
16 // The perpendicularity error is equivalent to the
    deflection of the tube under the cutting load
17 F_c = (P*1000)/(%pi*(N/60)*(D/1000)) // Cutting
    force in N; 1000 for kW conversion, 60 for rev/s
    conversion and 1000 for mm to m
18 I = (%pi*(D^4-Di^4))/64 // Cross sectional moment
    of inertia
19 deflection = (F_c*(L^3))/(3*E*I)
20 taper_error = D*(deflection/(2*L))
21 printf("\n The Maximum power = %.1f kW,\n Cutting
    time = %.1f min,\n The taper or perpendicularity
    error is %.3f mm",P,tm,taper_error)

```

---

**Scilab code Exa 2.10** Calculation of Number of teeth on the broach and length of th

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.10
4 // Given that
5 f_t = 0.1 // Feed per tooth in mm
6 d = 3 // Deep or Depth of cut in mm
7 p = 12.5 // Thread pitch in mm
8 L_e = 80 // Length to be broach in mm
9 w = 12 // Slot Wide in mm
10 us = 0.07 // Specific energy of the material from
    Table 2.1 in kW min/cm^3
11 V = 25 // Cutting speed in m/min
12 n_t = d/f_t // Number of teeth
13 L_b = p*n_t // Length of broach
14 tm = (L_b + L_e)/(V*1000) // Machining time in min,
    1000 is for conversion unit for V

```

```

15 n_te = ceil(L_e/p) // Number of teeth engage with
    the workpiece
16 d_e = n_te*f_t // Maximum depth engage of the
    broaching tool in mm
17 mrr = d_e*w*V*1000 // Material removal rate in mm
    ^3/min
18 F_c = ((mrr/1000)*us*60)/V // Force in kN
19 printf("Number of teeth on the Broach = %.0f teeth,\
    \n Length of the broch = %.0f mm \n The Machining
    time = %.3f min \n Cutting force = %.1f kN ",n_t,
    L_b,tm,F_c)

```

---

#### Scilab code Exa 2.11 Calculation of Machining Time

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.11
4 // Given that
5 f_t = 0.1 // Feed per tooth in mm/rev
6 n_t = 4 // Number of teeth
7 V = 100 // Cutting speed in m/min
8 D = 25 // Diameter of the tool in mm
9 p = 3 // Thread pitch in mm
10 eta = 0.7 // Percentage of thread
11 D_u = 100 // Minor diameter in mm
12 L = 30 // Depth in mm
13 N = (V*1000)/(%pi*D) // Speed of the drill in rev/
    min so conversion unit 1000 multiplied
14 f_rt = n_t*f_t*N // The Feed rate at the cutting
    edge
15 D_m = eta*(1.299*p) + D_u // Major diameter in mm
16 f_r = f_rt*(D_m - D)/D_m // Centerline Feed rate in
    mm/min
17 D_x = D_m - D // Travel distance for single orbit

```



```

18 L_x = sqrt((p^2)+((%pi)^2)*((D_x)^2)) // Total
    length of travel of the tool in mm
19 n_orbit = L /(3*p)
20 tm = n_orbit*(L_x/f_r) // Time for machining in min
21 // This computed time is for cutting and does not
    including the approach and exit distances for
    each orbit
22 printf("\n The Feed rate at the cutting edge = %.0f
    mm/min \n The total travel length = %.0f mm \n
    The Machining time = %.1f min",f_rt,L_x, tm)
23 // The answers vary due to round off error

```

---

**Scilab code Exa 2.12** Calculation of Material Removal Rate and Cutting Time and Tor

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 2.12
4 // Given that
5 D = 10 // Diameter of the drill in mm
6 f = 0.3 // Feed of the drill in mm/rev
7 V = 200 // Cutting speed in m/min
8 L = 30 // Length of hole to be drilled in mm
9 row = 60 // Drill point angle in degrees, in
    question it was 120, divided by 2 is row
10 delta_L = 3 // Assume the approach and over travel
    distance for the drill as 3mm
11 us = 0.008 // For magnesium alloys specific cutting
    energy from Table 2.1 0.008 W.min/cm^3
12 N = (V*1000)/(%pi*D) // Speed of the drill in rev/
    min so conversion unit 1000 multiplied
13 fr = N*f // Feed rate
14 mrr = ((%pi*(D^2))/4)*fr // Material removal rate in
    mm^3/min, need in cm^3/min divide by 1000
15 tm = (L+(D/tand(row))+delta_L)/fr // Cutting time in

```

```

        min, if multiplied by 60 cutting time will be in
        seconds
16 P = mrr*us // Power required to drill the hole in N.
        m/s
17 T = P*60 / (2*pi*N) // Torque on the drill in N.m,
        Multiplied by 60 for conversion to s/min
18 printf("\n The Material Removal Rate = %.0f mm^3/min
        \n The Cutting time = %.2f min \n The Torque on
        the drill = %.1f N m",mrr,tm,T)

```

---

### Scilab code Exa 2.13 Calculation of Material Removal Rate and Machining Time

```

1 clear; // Remove clear, clc if you want to access
        the stored variables
2 clc
3 // Example 2.13
4 // Given that
5 D = 150 // Diameter of the wheel in mm
6 V = 2000 // Cutting speed in m/min
7 V_work = 2200 // Velocity of the work in mm/min
8 doc_total = 0.2 // Depth to be ground
9 d = 0.01 // Grinding depth in mm/pass
10 Lp = 350 // Length of the workpiece in mm
11 b = 75 // Width of the workpiece in mm
12 La = 40
13 mrr = b*d*V_work
14 tmp = (Lp+D+La)/mrr // Time to travel across the part
        length
15 tm = ((doc_total/d)*tmp)+tmp
16 printf("\nThe Material Removal Rate = %.2f mm^3/min
        ,\n The Machining time = %.2f min ",mrr,tm)
17 // The answers vary due to round off error

```

---

Scilab code Exa 2.14 Calculation of Power required to Grind and the Machining Time

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 2.14
4 // Given that
5 Dw = 75 // Diameter of the workpiece in mm
6 d = 0.015 // Grinding depth in mm/pass
7 fr = 1500 // Traverse feed rate in mm/min
8 us = 0.08 // Specific cutting energy in kW min/cm3
9 doc_total = 0.2 // Depth to be ground or Total depth
   of cut in mm
10 Lp = 200 // Length of the bar to be performed in mm
11 Wt = 25 // Wheel Thickness in mm
12 La = 8 // Overall travel distance from both ends of
   the workpiece
13 mrr = %pi*Dw*d*fr/1000 // Material removal rate in
   cm3/min divide with 1000
14 // The specific energy for grinding should be much
   larger than that give in Table 2.1 based on
   turngin test. Therefore the value of 0.08 kW min/
   cm3 for cast iron from Table 2.1 should be
   multiplied by five times for grinding operations
   for a rough estimaate.
15 P = mrr*(5*us) // Estimated power required
16 tmp = (Lp+Wt+La)/fr // Time to travel across the
   part length in min/pass
17 tm = (doc_total*tmp/d)+(2*tmp) // The machining time
   in minutes
18 tmp = (Lp+Wt+La)/fr // Time travel across the part
   length (to perform one pass) in min/pass
19 printf("\n\nThe Power required to grind = %.2f kW,\n
   The Machining time = %.2f min, \n Time travel
   across the part length (to perform one pass) = %
   .3f min/pass",P,tm,tmp)
20 // The answers vary due to round off error
```

---

# Chapter 3

## Machine Tools

Scilab code Exa 3.1 Calculation of Stiffness of a Strut

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 3.1
4 // Given that
5 k_s = 140 // Stiffness of the ball screw in N/um
6 k_g = 25 // Stiffness of the Gimbal joint in N/um
7 k_t = 1/((1/k_s)+(2*(1/k_g)))
8 printf("The Stiffness of the strut = %.1f N/um",k_t)
```

---

# Chapter 4

## Cutting Tools

Scilab code Exa 4.1 Calculation of Material Removal Rate for both the drill and th

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 4.1
4 // Given that
5 Vd = 100 // Cutting speed for uncoated carbide drill
   in m/min
6 Dm = 10 // Diameter of drill from figure 4.4
7 D = 9 // Diameter of drill for a 10mm is about 9mm
8 Vt = 30 // Cutting speed of HSS tap, Assumption
9 f = 0.15 // Feed for drilling cast iron assumed in
   mm/flute
10 L = 27 // The bottom depth of the blind hole assumed
   in mm
11 row = 120 // Drill point angle in degrees
12 p = 1 // Pitch for the M10 x 1mm tap is 1 mm
13 n_t = 2 // Number of Inserts
14 Lt = 23
15 Le = 2 // Assumed since a hole is made in mm
16 N_d = Vd*1000/(%pi*D) // Spindle speed for drilling
   in rpm ; 1000 is for the conversion unit
```

```

17 // The answer provided in the textbook is wrong for
    N_d
18 N_t = Vt*1000 / (%pi*Dm) // Spindle speed for
    tapping in rpm ; 1000 is for the conversion unit
19 f_r = n_t*f*N_d // Feedrate for drilling in mm/min
20 f_rt = p*N_t // Feedrate for tapping in mm/min
21 t_md = (L+(D/tand(row/2))+2)/f_r // Cutting time
    for drilling with 120degrees point drill in min
22 t_mt = (Lt+Le)/f_rt // Cutting time for tapping in
    min
23 mrr_d = ((%pi*(D^2))/4)*f_r // Material removal rate
    for the drill in mm^3/min
24 // The answer provided in the textbook is wrong for
    mrr
25 lambda = atand(p/(%pi*Dm))
26 mrr_t = ((p/4)+((Dm-D)/tand(row/2)))*((Dm-D)/4)*((p*
    N_t)/sind(lambda)) // Material removal rate for
    the tapping in mm^3/min
27 // The answer provided in the textbook is wrong for
    mrr
28 printf("\n The Material removal rate for drilling =
    %.0f mm^3/min, \n The Material removal rate for
    tapping = %.0f mm^3/min", mrr_d,mrr_t)

```

---

Scilab code Exa 4.2 Calculation of Change in Machining Time for Drilling and Tapping

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 4.2
4 // Given that
5 Vd = 30 // Cutting speed for uncoated HSS drill in m
    /min
6 D = 9 // Diameter of drill for a 10mm is about 9mm
7 n_t = 2

```

```

8 L = 27 // The bottom depth of the blind hole assumed
      in mm
9 f = 0.15 // Feed for drilling cast iron assumed in
      mm/flute
10 row = 120 // Drill point angle in degrees
11 N_d = Vd*1000/(%pi*D) // Spindle speed for drilling
      in rpm ; 1000 is for the conversion unit
12 // The answer provided in the textbook is wrong for
      N_d
13 f_r = n_t*f*N_d // Feedrate for drilling in mm/min
14 // The answer provided in the textbook is wrong for
      f_r
15 t_md = (L+(D/tand(row/2))+2)/f_r // Cutting time
      for drilling with 120degrees point drill in min
16 // t_T = 1.78 + 1.57 + delta_t // The total
      machining time to drill and tap the hole is the
      sum of the drilling and tapping times plus
      several other tool travel times i.e., retract the
      tool from the bottom of hole, approach time.
17 // t_T2 = 6 + 1.57 + delta_t
18 // t_Tx = t_T2 - t_T = 7.57 + delta_t - 3.35 -
      delta_t
19 t_Tx = 7.57 - 3.35
20 printf("\n The change in machining time for drilling
      and tapping = %.2f s",t_Tx)

```

---

**Scilab code Exa 4.4** Calculation of the Deflection at the tool point for bar A and

```

1 clear; // Remove clear, clc if you want to access
      the stored variables
2 clc
3 // Example 4.4
4 // Given that
5 E_steel = 206700 // Youngs modulus of steel in MPa
6 E_heavymetal = 330000 // Youngs modulus of heavy

```

```

    metal in MPa
7  D_i = 55 // Initial diameter of the bore in mm
8  D_o = 59 // Final diameter of the bore in mm
9  D_B = 50 // Diameter of the Bar B in mm
10 D_abar = 35 // Diameter of the bore in mm
11 L = 250 // Length of the bar in mm
12 V = 100 // Cutting speed of the bar in m/min
13 fr = 0.2 // Feed in mm/rev
14 us = 0.06 // Specific energy from Table 2.1
15 D_avg = (D_i + D_o)/2 // Diameter average in mm
16 N = (V*1000)/(%pi*D_avg) //
17 R = (D_i + D_o)/4
18 mrr = ((%pi*((D_o^2) - (D_i^2)))/4)*N*fr
19 F_r = (mrr*us)/(4*%pi*R*N/(60*1000)) // conversion
    unit 60 for min to seconds and 1000 for m to mm
20 I_A = ((%pi*(D_abar^4))/64) // The answer for the
    I_A was wrong in the textbook
21 // The answers vary due to round off error
22 I_B = ((%pi*(D_B^4))/64)
23 deflection_A = (F_r*(L^3))/(3*E_steel*I_A)
24 // The deflection of 0.246 mm is very large and the
    hole diameter will be smaller by 0.492 mm and
    will generate the scratch marks during tool
    retraction. Therefore, the deflection should be
    reduced by reducing the radial force, which is
    proportional to the area of cut. Hence, the doc
    or feed must be changed in order to reduce the
    force. Since a large reduction on the deflection
    is required, both doc and feed will be reduced by
    50%. However, the reduction of the DOC by 50%
    will require two passes to remove the 2 mm full
    depth from the bore. The reduction of the feed
    from 0.2 to 0.1 mm /rev is acceptable but the
    machining time will be doubled. The reduction of
    the cutting conditions results in lower
    productivity
25 F_r2 = F_r/4
26 deflection_2 = deflection_A/4

```



```

27 deflection_heavymetal = deflection_A *(E_steel/
    E_heavymetal)
28 deflection_heavymetal2 = deflection_heavymetal/4 //
    Using the 50% reduced feed and DOC, the new
    deflection
29 deflection_B = F_r*(((L^3)/(3*E_steel*I_A))+((L^3)
    /(3*E_steel*I_B))+(((L*L)/(E_steel*I_B))*(L+L)))
30 printf("The deflection at the cutting tool point for
    bar A = %.3f mm, \n The deflection at the
    cutting tool point changing the boring bar
    material from steel to heavy metal = %.3f mm,\n
    The deflection at the cutting tool point for bar
    B = %.3f mm",deflection_A,deflection_heavymetal2,
    deflection_B)
31 // The answers vary due to round off error

```

---

# Chapter 5

## Toolholders and Workholders

Scilab code Exa 5.3 Calculation of total balancing grade

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 5.3
4 // Given that
5 W_spindle = 20 // Mass of the spindle in kg
6 W_holder = 1.27 // Mass of the toolholder in kg
7 W_tool = 0.35 // Mass of the tool in kg
8 G = 1.17 // Quality grade as defined in ANSI/S2.19
9 rpm_spindle = 29250 // Maximum operating speed (r/
   min) from the graph in Fig. 5.82
10 rpm_holder = 11697 // Maximum operating speed (r/min
   ) from the graph in Fig. 5.82
11 rpm_tool = 4644 // Maximum operating speed (r/min)
   from the graph in Fig. 5.82
12 U_spindle = (9549*G*W_spindle)/rpm_spindle
13 U_holder = (9549*G*W_holder)/rpm_holder
14 U_tool = (9549*G*W_tool)/rpm_tool
15 U_total = U_spindle + U_holder + U_tool
16 printf("The total balancing grade of an assembled \n
   spinde-toolholder-tool system = %.3f g mm",
```

U\_total)

---

**Scilab code Exa 5.4** Calculation of Unbalance force reduction

```
1 clear; // Remove clear, clc if you want to access
  the stored variables
2 clc
3 // Example 5.4
4 // Given that
5 U = 30 // Unbalance in mm
6 N = 15000 // Speed of the tool holder in rpm
7 F_r = (U*((2*pi*N)/60)^2)*10e-7 // Unbalance
  force reduction in N
8 printf("The Unbalance force reduction = %.0f N", F_r
  )
9 // The radial force for 30 g mm unbalance at 15000
  rpm is 74N and for 75 g mm unbalance the force
  becomes 185 N. Hence the force reduction is
  significant if a pre-balanced tool holder is used
```

---

**Scilab code Exa 5.5** Calculation of allowable unbalance for a balance quality grade

```
1 clear; // Remove clear, clc if you want to access
  the stored variables
2 clc
3 // Example 5.5
4 // Given that
5 G = 2.5 // Quality grade as defined in ANSI/S2.19
6 W = 3.63 // Estimated total tool weight in kg
7 N = 10000 // Speed of the tool holder in rpm
8 U = (9549*G*W)/N
9 printf("The allowable Unbalance for the boring bar =
  %.2f g mm", U)
```

10 // The answers vary due to round off error

---

**Scilab code Exa 5.6** Determining the effect of toolholder clamping length

```
1 clear; // Remove clear, clc if you want to access
  the stored variables
2 clc
3 // Example 5.6
4 // Given that
5 F_1 = 80 // Cutting force on the boring bar in N
6 L_1 = 7 // Extended length of the boring bar 7XD
7 L_3 = 2 // Tool shank length A bar
8 L_3B = 4 // Tool shank length B bar
9 F_3 = (F_1*L_1)/L_3 // Force acting on the back end
  of the boring bar A in N
10 F_2 = F_1+F_3 // Force acting at the front of the
  chuck in bar A in N
11 F_3B = (F_1*L_1)/L_3B // Force acting on the back
  end of the boring bar B in N
12 F_2B = F_1+F_3B // Force acting at the front of the
  chuck in bar B in N
13 printf("The Force at the bar A = %.0f N, \n The
  Force at the bar B = %0.f N",F_2,F_2B)
14 printf("\n The reaction force acting at the free end
  of the chuck is %.0f N \n is smaller than %.0f N
  at bar A, \n This will reduce the deformation of
  the chuck at the free end",F_2B,F_2 )
```

---

**Scilab code Exa 5.8** Calculation of deflection at the tool point

```
1 clear; // Remove clear, clc if you want to access
  the stored variables
2 clc
```

```

3 // Example 5.8
4 // Given that
5 k_s = 1.375e9 // Spring constant linear for CAT40
    from Table 5.7 in n/m
6 k_h = 3e8 // Spindle stiffness in N/m (linear)
7 k_theta = 8.108e6 // Spindle stiffness in N/m (
    rotational)
8 D1 = 25 // Diameter of the tool-holder spindle in mm
    from figure 5.106
9 D2 = 44 // Major Diameter of the tool-holder spindle
    in mm from figure 5.106
10 f_r = 0.15 // Feed in mm/rev
11 Fr = 185 // Radial cutting force in N
12 V = 100 // Cutting speed in m/min
13 L1 = 170 //Length of the tool-holder in mm from
    figure 5.106
14 L2 = 40 //Length of the tool-holder chuck in mm from
    figure 5.106
15 L = L1+L2 // Total length of the tool-holder and
    chuck in mm from figure 5.106
16 La = 20 // Distance between the spindle nose and the
    rotational spring in mm
17 E1 = 206700 // Youngs modulus of steel in MPa
18 E2 = 206700 // Youngs modulus of steel in MPa
19 I1 = (%pi*D1^4)/64 // The answers vary due to round
    off error
20 I2 = (%pi*D2^4)/64
21 k = 1/((1/k_s)+(1/k_h))
22 deflection_1 = (Fr/k)*1000 // Linear deflection in
    N, 1000 is the conversion unit for m to mm
23 deflection_2 = f_r*(((L1^3)/(2*E1*I1))+((L2^3)/(2*E2
    *I2))+(((L1*L2)*(L1+L2))/(E2*I2)))*1000 //The
    deflection of the bar structure with two cross
    sections in mm, 1000 is the conversion unit for m
    to mm
24 // The answers vary due to round off error
25 theta = (Fr*(L+La))/(k_theta*1000) // Angle in
    radians

```

```
26 deflection_r = (L+La)*tan(theta) // Since the theta
    value is in radians, not inserting tand here.
27 deflection_total = deflection_1+deflection_2+
    deflection_r
28 // The answer provided in the textbook is wrong
29 printf("The total deflection = %.3f mm",
    deflection_total)
```

---

# Chapter 6

## Mechanics of Cutting

Scilab code Exa 6.1 Calculation of mean angle of friction and mean shear stress an

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 6.1
4 // Given that
5 b = 2.5 // Thickness of tube in mm
6 a = 0.3 // feed in mm/rev
7 V = 200 // cutting speed in m/min
8 ac = 0.7 // chip thickness in mm
9 lf = 0.5 // tool-chip contact length in mm
10 Fc = 900 // tangential cutting force in N
11 Fz = 600 // Axial (feed) force in N
12 alpha = 0 // Rake angle of tool is Zero
13 tsz = 0.02 // thickness of shear zone assumed as
   0.02 mm
14 // Sample Problem 6.1 on page no. 436
15 printf("\n Problem 6.1 \n")
16 beta = atand(Fz/Fc)
17 rc = a/ac // Cutting ratio
18 phi = atand((rc*cosd(alpha))/(1-(rc*sind(alpha))))
   // Mean shear angle between the direction of
```

```

    cutting speed and the shear plane
19 tow_s = (((Fc*cosd(phi))-(Fz*sind(phi)))*sind(phi))
    /(a*b)) // Mean shear stress of the workpiece
20 tow_f = ((sqrt((Fc^2)+(Fz^2))*sind(beta))/(b*lf)) //
    Mean frictional stress at the tool-chip
    interface
21 gamma = cotd(phi)+(tand(phi-alpha))
22 delta_t = (tsz*60)/(V*1000*sind(phi))
23 gamma_dot = gamma/delta_t // Strain rate in the chip
    formation if thickness of shear zone assumed as
    0.02 mm
24 FE = (((sqrt((Fc^2)+(Fz^2))*sind(beta))*rc)/Fc)*100
    // Friction energy
25 printf("\n Mean angle of friction on the tool face =
    %.1f ,\n Mean shear stress produced in cutting
    the workpiece = %.0f N/mm^2,\n Mean frictional
    stress at the tool-chip interface = %.0f N/mm^2 \
    \n Shear Strain = %.2f ,\n Strain rate in the
    chip formation = %.0f s^-1, \n Friction energy
    accounts for %.0f Percentage of the total energy
    ", beta,tow_s,tow_f,gamma,gamma_dot, FE)
26 // The answers vary due to round off error

```

---

### Scilab code Exa 6.2 Calculation of Tangential force and feed force

```

1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 6.2
4 // Given that
5 alpha = -8 // Rake angle of tool -8 from the Problem
    6.1
6 b = 2.5 // Thickness of tube in mm
7 a = 0.3 // feed in mm/rev
8 V = 200 // cutting speed in m/min

```



```

 9 ac = 0.85 // chip thickness in mm
10 lf = 0.5 // tool-chip contact length in mm
11 Fc = 900 // tangential cutting force in N
12 Fz = 600 // Axial (feed) force in N
13 tsz = 0.02 // thickness of shear zone assumed as
    0.02 mm
14 rc = a/ac // Cutting ratio
15 phi = atand ((rc*cosd(alpha))/(1-(rc*sind(alpha))))
16 // The shear angle is reduced from 23.2 to 21.8
    degrees as expected since the rake angle was
    reduced.
17 tow_s = (((Fc*cosd(phi))-(Fz*sind(phi)))*sind(phi))
    /(a*b) // Mean shear stress of the workpiece
18 F_s = (tow_s*a*b)/sind(phi)
19 beta_a = atand(Fz/Fc)+alpha // Beta angle calculated
    from Eq 6.30 using Figure 6.27
20 R = F_s/(cosd(phi+beta_a-alpha)) // Resultant force
    in N
21 F_c = R*cosd(beta_a-alpha) // Cutting force in N
22 F_z = R*sind(beta_a-alpha) // Feed force in N
23 printf("The Tangential (cutting) force = %.0f N, \n
    The Feed force = %.0f N",F_c,F_z)
24 // The answer provided in the textbook is wrong for
    mrr

```

---

# Chapter 9

## Tool Wear and Tool life

Scilab code Exa 9.2 Calculation of parameters for the extended Taylor tool life equation

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 9.2
4 // Given that
5 V_one = 70 // Cutting speed
6 V_two = 70 // Cutting speed
7 V_three = 140
8 f_1 = 0.15
9 f_3 = 0.15
10 f_2 = 0.25
11 T_1 = 120 // Mean tool life in min
12 T_2 = 105 // Mean tool life in min
13 T_3 = 24 // Mean tool life in min
14 n = log(V_three/V_one)/log(T_1/T_3) // (V_three/
   V_one = (T_1/T_3)^n)
15 a = n*(log(T_2/T_1)/log(f_1/f_2))
16 K_t = V_one*(T_1^n)*(f_1^a)
17 printf("The parameters for extended tool life = %.2f
   & %.2f, \n The tool life equation = %.0f",n,a,
   K_t)
```

18 // The answers vary due to round off error

---

# Chapter 10

## Surface Finish Integrity and Flatness

Scilab code Exa 10.1 Calculation of Maximum feed

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 10.1
4 // Given that
5 R_a = 0.003 // Surface finish in micro meter
6 K_reone = 10 // Minor cutting edge angle (ECEA) in
   degrees
7 K_re = 20 // Lead angle of the tool (SCEA) in degrees
8 alpha = K_re + K_reone
9 f = 4 * R_a * (cotd(90 - alpha) + cotd(K_reone)) // Feed
10 f_max = f / 1.4 // Maximum feed
11 printf("The Maximum feed = %.3f mm", f_max)
```

---

Scilab code Exa 10.2 Calculation of Corner Radius

```
1 clear; // Remove clear, clc if you want to access
    the stored variables
2 clc
3 // Example 10.2
4 // Given that
5 R_a = 0.001 // Surface finish in micro meter
6 f = 0.1 // Feed in mm/rev
7 r_n = (0.0321*f^2)/R_a // Average Geometric
    roughness from Eq.10.10
8 printf("The Average Geometric roughness = %.3f mm",
    r_n)
```

---

# Chapter 13

## Machining Economics and Optimization

Scilab code Exa 13.2 Calculation of Production cost for a rough turning

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 13.2
4 // Given that
5 L = 200 // Length of the bar in mm
6 L_e = 2 // Approach length in mm assumed
7 L_t = 80
8 f_rapid = 6000 // Feed in mm/min from the Table 13.1
9 C_o = 1 // it was given 60$/h from the Table 13.1,
   when convert to min
10 nt = 3 // Number of cutting edges per insert
11 cte = 9 // Tool cost in dollars per insert
12 f = 0.3 // Feed rate in mm/rev from the Table 13.1
13 N = 700 // Spindle rpm from the Table 13.1
14 D = 70 // Diameter of the bar in mm
15 t_h = 20 // Part load/unload time in seconds
16 t_l = 1 // Tool load/unload time in Minutes
17 t_cs = 8 // Tool interchange time between operations
```

```

        in seconds
18 n = 0.25 // Tool life exponent from the Table 13.1
19 ct = 500 // Tool life constant from the Table 13.1
20 t_m = (L+L_e)/(f*N) // Machining time in min
21 V = %pi*D*N/1000 // Cutting speed in m/min
22 T = ct^4*(V^-4) // Tool life in min  $VT^n = Ct$ 
23 t_x = (L+L_t)/f_rapid
24 C_te = cte/nt // Per cutting edge in dollars
25 C_u = C_o*t_m + ((t_m/T)*((C_o*t_l)+C_te))+C_o*((
        t_cs/60)+(t_h/60)+t_x))
26 printf("The Production cost = $ %.2f",C_u)

```

---

### Scilab code Exa 13.3 Calculation of Minimum Production Cost

```

1 clear; // Remove clear, clc if you want to access
        the stored variables
2 clc
3 // Example 13.3
4 // Given that
5 L = 200 // Length of the bar in mm
6 L_e = 2 // Approach length in mm assumed
7 L_t = 80
8 f_rapid = 6000 // Feed in mm/min from the Table 13.1
9 C_o = 1 // it was given 60$/h from the Table 13.1,
        when convert to min
10 nt = 3 // Number of cutting edges per insert
11 cte = 9 // Tool cost in dollars per insert
12 f = 0.3 // Feed rate in mm/rev from the Table 13.1
13 fh = 0.5 // Maximum allowable feed rate in mm/rev
        given in example 13.3
14 a = 0.5 // Exponent
15 D = 70 // Diameter of the bar in mm
16 t_h = 20 // Part load/unload time in seconds
17 t_l = 1 // Tool load/unload time in Minutes
18 t_cs = 8 // Tool interchange time between operations

```

```

        in seconds
19 n = 0.25 // Tool life exponent from the Table 13.1
20 Kt = 500 // Tool life constant from the Table 13.1
21 t_x = (L+L_t)/f_rapid
22 C_te = cte/nt // Per cutting edge in dollars
23 V_opc = Kt/(((fh^a)*((((1-n)/n)*(t_l+(C_te/C_o))))^n))
24 N = (V_opc*1000)/(%pi*D)
25 t_m = (L+L_e)/(fh*N) // Machining time in min
26 T = Kt^4*(V_opc^-4)*(fh^-2) // Tool life in min VT^n
    = Ct
27 // The answer in the textbook is wrong
28 C_u = C_o*t_m + ((t_m/T)*((C_o*t_l)+C_te))+C_o*((
    t_cs/60)+(t_h/60)+t_x))
29 printf("The Production cost = $ %.2f, \n The
    production cost is reduced from $1.51 to $ %.3f
    by using an optimum cutting speed",C_u,C_u)

```

---



# Chapter 16

## Accuracy and Error Compensation of CNC Machining Systems

Scilab code Exa 16.1 Calculation of magnitude of the Abbe error

```
1 clear; // Remove clear, clc if you want to access
   the stored variables
2 clc
3 // Example 16.1
4 // Given that
5 deflection_y = 0.01 // Curvature of the x-axis in
   the y-direction in mm
6 X = 1000
7 P = 600 // Offset of the part feature to be
   machined in mm
8 theta_x = (8*deflection_y)/X
9 delta = P*sind(theta_x/2)
10 printf("The Magnitude of the Abbe error = %.6f mm",
   delta)
11 // The answers vary due to round off error
```

---