

Scilab Textbook Companion for
Fundamentals Of Modern Manufacturing:
Materials, Processes, And Systems
by Mikell P. Groover¹

Created by
Venkata Ajay Kumar G
M.Tech - College Teacher
Mechanical Engineering
JNTU Anantapur / AITS, Rajampet
Cross-Checked by
Scilab TBC Team

April 8, 2020

¹Funded by a grant from the National Mission on Education through ICT,
<http://spoken-tutorial.org/NMEICT-Intro>. This Textbook Companion and Scilab
codes written in it can be downloaded from the "Textbook Companion Project"
section at the website <http://scilab.in>

Book Description

Title: Fundamentals Of Modern Manufacturing: Materials, Processes, And Systems

Author: Mikell P. Groover

Publisher: John Wiley & Sons, Inc. Usa

Edition: 5

Year: 2012

ISBN: 978-1-118-231463

Scilab numbering policy used in this document and the relation to the above book.

Exa Example (Solved example)

Eqn Equation (Particular equation of the above book)

AP Appendix to Example(Scilab Code that is an Appednix to a particular Example of the above book)

For example, Exa 3.51 means solved example 3.51 of this book. Sec 2.3 means a scilab code whose theory is explained in Section 2.3 of the book.

Contents

List of Scilab Codes	4
1 Introduction and Overview of Manufacturing	5
3 Mechanical Properties of Materials	9
5 Dimensions Surfaces and their Measurement	13
10 Fundamentals of Metal Casting	15
11 Metal Casting Processes	18
13 Shaping Processes for Plastics	20
18 Bulk Deformation Processes in Metalworking	23
19 Sheet Metalworking	28
20 Theory of Metal Machining	31
21 Machining Operations and Machine Tools	35
22 Cutting Tool Technology	38
23 Economic and Product Design Considerations in Machining	39

25 Nontraditional Machining and Thermal Cutting Processes	43
27 Surface Processing Operations	45
28 Fundamentals of Welding	46
29 Welding Processes	48
31 Mechanical Assembly	51
32 Rapid Prototyping and Additive Manufacturing	53
33 Processing of Integrated Circuits	56
37 Automation Technologies for Manufacturing systems	59
38 Integrated Manufacturing Systems	62
39 Process Planning and Production Control	65
40 Quality Control and Inspection	67

List of Scilab Codes

Exa 1.1	Equipment cost rate	5
Exa 1.2	Cycle time and Cost per piece	6
Exa 1.3	Scrap rate	7
Exa 1.4	Cycle time and cost per piece	7
Exa 3.1	Engineering Stress and Strain	9
Exa 3.2	True Stress and Strain	10
Exa 3.3	Flow curve parameters	11
Exa 5.1	Wear allowance on a fixed gage	13
Exa 5.2	Sine bar measurement	14
Exa 10.1	Heating metal for casting	15
Exa 10.2	Pouring Calculations	16
Exa 10.3	Riser design using Chvorinov s rule	16
Exa 11.1	Buoyancy in Sand Casting	18
Exa 11.2	Rotation speed in true centrifugal casting . .	18
Exa 13.1	Extrusion flow rates	20
Exa 13.2	Extruder and Die Characteristics	21
Exa 13.3	Shrinkage in Injection Molding	22
Exa 18.1	Flat Rolling	23
Exa 18.2	Open die forging	24
Exa 18.3	Extrusion Pressures	25
Exa 18.4	Stress and Force in Wire drawing	26
Exa 19.1	Blanking clearance and force	28
Exa 19.2	Sheet metal Bending	29
Exa 19.3	Cup Drawing	29
Exa 19.4	Forces in Deep drawing	30
Exa 20.1	Orthogonal Cutting	31
Exa 20.2	Shear stress in Machining	31
Exa 20.3	Estimating Friction Angle	32

Exa 20.4	Power Relations in machining	33
Exa 20.5	Cutting Temperature	33
Exa 21.1	Machining Time in Turning	35
Exa 21.2	Machining Time in Drilling	36
Exa 21.3	Machining Time in Peripheral Milling	36
Exa 22.1	Taylor Tool life equation	38
Exa 23.1	Machinability	39
Exa 23.2	Surface Roughness	40
Exa 23.3	Determining cutting speeds in machining economics	40
Exa 23.4	Production rate and cost in machining economics	41
Exa 25.1	Electrochemical Machining	43
Exa 25.2	Electric Discharge Machining	44
Exa 27.1	Electroplating	45
Exa 28.1	Power density in Welding	46
Exa 28.2	Welding Travel Speed	47
Exa 29.1	Power in arc welding	48
Exa 29.2	Resistance welding	49
Exa 29.3	Heat generation in oxyacetylene welding	49
Exa 31.1	Threaded Fasteners	51
Exa 31.2	Expansion fit	52
Exa 32.1	Build cycle time in stereolithography	53
Exa 32.2	Cost per piece in additive manufacturing	54
Exa 33.1	Number of Chips on Wafer	56
Exa 33.2	Rent s Rule	56
Exa 33.3	Yield in Water processing	57
Exa 37.1	Open loop Positioning	59
Exa 37.2	NC Closed loop Positioning	60
Exa 37.3	Control resolution accuracy and repeatability	60
Exa 38.1	Manual Assembly Line	62
Exa 38.2	Automated Transfer line	63
Exa 38.3	Product Proliferation	63
Exa 39.1	Make or buy cost comparison	65
Exa 40.1	X and R charts	67
Exa 40.2	Determining the Sigma level of a process	68
Exa 40.3	Taguchi Loss Function	68

Chapter 1

Introduction and Overview of Manufacturing

Scilab code Exa 1.1 Equipment cost rate

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 1.1 – Equipment cost rate
6 // Given that
7 ic = 500000 // Initial cost plus installation in $
8 n = 7 // Anticipated life in years
9 w = 50 //number of weeks per year
10 s = 2 // Number of shift
11 D = 5 // Number of days in week
12 h = 8 // Shift hours
13 Roh = 0.35 // Overhead rate on the equipment in
               Percentage
14 H = w*s*D*h // Annual number of hours of Operation
               in hr/yr
15 Ceq = (ic/(60*n*H))*(1+Roh) // Equipment cost rate
16 printf("\n The Equipment cost rate = $%.3f /min",Ceq)
```

)

Scilab code Exa 1.2 Cycle time and Cost per piece

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 1.2 – Cycle time and Cost per piece
6 // Given that
7 ic = 500000 // Initial cost plus installation in $
8 n = 7 // Anticipated life in years
9 w = 50 //number of weeks per year
10 s = 2 // Number of shift
11 D = 5 // Number of days in week
12 h = 8 // Shift hours
13 Roh = 0.35 // Overhead rate on the equipment in
        Percentage
14 H = w*s*D*h // Annual number of hours of Operation
        in hr/yr
15 Ceq = (ic/(60*n*H))*(1+Roh) // Equipment cost rate
16 To = 3.72 // Processing time in min
17 Th = 1.60 // Part handling time in min
18 p = 20 // Number of pieces changing
19 t = 2 // setup time in min
20 Q = 100 // Batch quantity , number of pieces (pc)
21 Ts = 2.5 // Machine setup time in hr
22 Rh = 16.50 // Hourly wage rate is $/hr
23 Rloh = 0.40 // labor overhead rate in percentage
24 tool_cost = 4.40 // Tool cost in Dollar
25 Cm = 2.35 // Starting material cost in dollars
26 Tt = t/p // Tool handling time in min for 20 tools
27 Tc = To + Th + Tt // Cycle time of the unit
        operation in min/pc
```

```

28 Tp = ((Ts*60)/Q)+Tc //Average production time per
    piece inculding the effect of setup time in min/
    pc
29 Rp = (60/Tp) // Hourly production rate in pc/hr
30 C1 = Rh/60 *(1+Rloh) // labor cost rate , $/min;
31 Ct = tool_cost/20 // Each tool can be used for 20
    pieces in $/pc
32 Cpc = Cm + ((C1+Ceq)*Tp) + Ct // Cost per piece in $
    /pc
33 printf("\n The Cycle time for the piece =%.2f min/
    pc \n Average production rate =%.2f min/pc \n
    Hourly production rate =%.2f pc/hr \n Cost per
    piece = $%.2f /pc",Tc,Tp,Rp,Cpc)
34 // The answers vary due to round off error

```

Scilab code Exa 1.3 Scrap rate

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
    the stored variables
4 clc
5 // Example 1.3 – Scrap rate
6 // Given that
7 Q = 1000 // Ordered batch parts
8 q = 0.04 // Scrap rate for the type of part in
    percentage
9 Qo = Q/(1-q) // Required quantity of parts to be
    delivered
10 printf('Number of parts required = %.0f \n',Qo)

```

Scilab code Exa 1.4 Cycle time and cost per piece

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 1.4 – Cycle time and cost per piece
6 // Given that
7 Cm = 1.75 // Starting Material Cost in $
8 Ceq = 42 // Equipment Cost rate in $/hour
9 Tp = 0.97 // Average production time per piece in
        percentage
10 Cl = 24 // Labor cost rate in $/hr
11 s = 0.05 // Scrap rate of parts produced in
        Percentage
12 T_p = 2.20 // Cycle time in min
13 Rp = (60*Tp)/T_p // Production rate , including
        effect of availability in pc/hr
14 average_Rp = Rp*(1-s) // Because of 5% scrap rate
        the production rate of acceptable parts
15 Cpc = (Cm/(1-s))+((Cl+Ceq)/Tp)*((T_p)/(60*(1-s))) //
        Availability of Scrap rate , the part cost per
        piece
16 s_b = 0 // Scrap rate of parts produced is Zero
        Percentage for b question
17 Tp_b = 1 // Average production time per piece in
        percentage for b question
18 Rp_b = (60*Tp_b)/T_p // Production rate , including
        effect of availability in pc/hr for b question
19 Cpc_b = (Cm)+((Cl+Ceq)/Tp_b)*((T_p)/(60*(1-s_b))) //
        Availability of Scrap rate , the part cost per
        piece for b question
20 printf('The part cost for (A) = $ %.2f /pc \n The
        part Cost for (B) = $ %.2f \n',Cpc,Cpc_b)

```

Chapter 3

Mechanical Properties of Materials

Scilab code Exa 3.1 Engineering Stress and Strain

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 3.1 – Engineering Stress and Strain
6 // Given that
7 F = 32000 // Force applied in N
8 Ao = 200 // Original area of cross of test specimen
            in MPa
9 Y = F/Ao // Yield Strength (Y) , MPa
10 L = 50.2 // Length at any point during the
            elongation in mm
11 Lo = 50 // Gage length in mm
12 Lo_max = 57.7 // Maximum length before necking
            begins in mm
13 Le = 0.002 //
14 Fmax = 65000 // Maximum load in N
15 Lf = 63.5 // Specimen length at fracture in m
```

```

16 // The input consider in the textbook was wrong
    while solving the problem
17 e = (L-Lo)/(Lo - Le) // Engineering Strain in mm/min
    , 0.2% offset
18 E = Y/e // Modulus of Elasticity , MPa
19 // the answer in the textbook was wrong
20 TS = Fmax/Ao // Tensile strength in MPa
21 e_max_load = (Lo_max-Lo)/Lo // Engineering Strain
    at maximum load in mm/min
22 EL = (Lf - Lo)/Lo // Elongation in %
23 // the answer in the textbook was wrong
24 printf('Yield Strength = %.0f MPa \n Modulus of
    Elasticity = %.0f MPa \n Tensile Strength = %.0f
    MPa\n Engineering strain at maximum load = %.3f \
    n Percentage Elongation = %.2f \n',Y,E,TS,
    e_max_load,EL)

```

Scilab code Exa 3.2 True Stress and Strain

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
    the stored variables
4 clc
5 // Example 3.2 – True Stress and Strain
6 // Given that – Some of the data are from problem
    3.1
7 F = 32000 // Force applied in N
8 Ao = 200 // Original area of cross of test specimen
    in MPa
9 s = F/Ao // Yield Strength (Y) , MPa
10 L = 50.2 // Length at any point during the
    elongation in mm
11 Lo = 50 // Gage length in mm
12 Lo_max = 57.7 // Maximum length before necking

```

```

        beigns in mm
13 Le = 0.002 //
14 Fmax = 65000 // Maximum load in N
15 Lf = 63.5 // Specimen length at fracture in m
16 A = (Ao*Lo)/Lo_max // Instantaneous area
17 sigma = Fmax/A // True Stress in MPa
18 epsilon = log(Lo_max/Lo) // True strain
19 printf('True Stress = %.0f MPa \n True Strain = %.3f
        \n',sigma,epsilon)

```

Scilab code Exa 3.3 Flow curve parameters

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 3.3 – Flow curve parameters
6 // Given that
7 // Data given from the example 3.1
8 F = 32000 // Force applied in N
9 Ao = 200 // Original area of cross of test specimen
        in MPa
10 Y = F/Ao // Yield Strength (Y) , MPa
11 L = 50.2 // Length at any point during the
        elongation in mm
12 Lo = 50 // Gage length in mm
13 Lo_max = 57.7 // Maximum length before necking
        beigns in mm
14 Le = 0.002 //
15 Fmax = 65000 // Maximum load in N
16 Lf = 63.5 // Specimen length at fracture in m
17 e = log((L/Lo)-Le ) // True strain
18 // At maximum load
19 e_2 = 0.143

```

```
20 sigma = 375
21 // The corresponding flow equation is 160 = K
   (0.001998)^n for Example 3.1
22 // the corresponding flow equation is 375 = K(0.143)
   ^n for Example 3.2
23 // Solving n
24 n = (log(sigma)-log(Y))/(log(e_2)-(log(e)))
25 K = Y/(e)^n // Substituting back into Example 3.1
   equation
26 printf ('The flow curve equation is sigma = %.1f e^
   %.4f \n',K,n)
```

Chapter 5

Dimensions Surfaces and their Measurement

Scilab code Exa 5.1 Wear allowance on a fixed gage

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 5.1 – Wear allowance on a fixed gage
6 // Given that
7 hole_diameter = 20 // hole diameter in mm
8 tolerance = 0.10
9 wear = 0.025 // 2.5% of wear allowance
10 Total_tolerance = tolerance+tolerance // Total
        Tolerance band in mm
11 wear_allowance = wear*Total_tolerance
12 acceptable_hole_diameter = hole_diameter - tolerance
        // Minimum acceptable hole diameter in mm
13 nominal_size = acceptable_hole_diameter +
        wear_allowance // Nominal size of GO gage in mm
14 // NO GO gage is used to check the maximum hole
        diameter
```

```
15 nominal_size_NOGO = hole_diameter + tolerance //  
    Nominal size of NOGO gage in mm  
16 printf('Nominal size of GO gage = %.3f mm \n Nominal  
    size of NOGO gage = %.2f mm \n',nominal_size,  
    nominal_size_NOGO)  
17 // Answer varies due to round off error
```

Scilab code Exa 5.2 Sine bar measurement

```
1 // OS – Windows 10 (64 bit)  
2 // Scilab version – 6.0.2  
3 clear; // Remove clear , clc if you want to access  
        the stored variables  
4 clc  
5 // Example 5.2 – Sine bar measurement  
6 // Given that  
7 L = 200 // Length in mm  
8 H = 40.38 // Gage blocks are stacked to a height in  
        mm  
9 A = asind(H/L) // Angle of interest in degrees  
10 printf('The Angle of interest = %.2f degrees ',A)
```

Chapter 10

Fundamentals of Metal Casting

Scilab code Exa 10.1 Heating metal for casting

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 10.1 – Heating metal for casting
6 // Given that
7 row = 7.5 // Density in g/cm^3
8 V = 1000000 // m^3 = 10^6 cm^3
9 C_s = 0.33 // Specific heat in J/gC
10 T_m = 800 // Melting point in C
11 T_o = 25 // Ambient temperature in the foundry C
12 H_f = 160 // Heat of fusion J/g
13 C_l = 0.29 // Weight specific heat of the liquid
               metal J/gC
14 T_p = 100 // pouring temperature in C
15 H = row*V*((C_s*(T_m - T_o))+H_f+(C_l*(T_p)))
16 printf('Heat energy = %.0f J',H)
```

Scilab code Exa 10.2 Pouring Calculations

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 10.2 – Pouring Calculations
6 // Given that
7 g = 981 // acceleration gravity constant
8 h = 20 // Mold sprue height in cm
9 v = sqrt(2*g*h) // Velocity of the flowing metal at
        the base of the sprue in cm/s
10 a = 2.5 // cross-sectional area of base in cm^2
11 V = 1560 // Volume of mold cavity in cm^3
12 Q = a*v // Volumetric flow rate in cm^3/s
13 T_mf = V/Q // Mold filling time in sec
14 printf('Velocity of the flowing metal at the base of
        the sprue = %.1f cm/s \n Volumetric flow rate =
        %.0f cm^3/s \n Mold filling time = %.1f sec ',v,Q,
        T_mf)
```

Scilab code Exa 10.3 Riser design using Chvorinov's rule

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 10.3 – Riser design using Chvorinov's
        rule
6 // Given that
7 l = 7.5 // Length in cm
8 w = 12.5 // width in cm
9 t = 2.0 // thickness in cm
```

```

10 n = 2 // Exponent usually taken as 2
11 T_ts = 1.6 // Total solidification time in min
12 T_tsd = 2 // Next riser must be designed so that its
               total solidification time in min
13 V = l*w*t // Volume in cm^3
14 A = (2*((l*w)+(l*t)+(w*t)))
15 C_m = T_ts/((V/A)^n) // Mold constant in min/cm^2
16 // Since D/H = 1.0 , D = H
17 // V = %pi*D^3/4
18 // Thus V/A ratio = D/6.
19 D = sqrt(n/((C_m/6^2)))
20 H = D // Since H = D
21 printf('The Dimensions of riser = %.1f cm \n The
           height of the riser = %.1f cm',D,H )

```

Chapter 11

Metal Casting Processes

Scilab code Exa 11.1 Buoyancy in Sand Casting

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 11.1 – Buoyancy in Sand Casting
6 // Given that
7 v = 1875 // Sand core volume in cm^3
8 row = 1.6 // Density in g/cm^3
9 W_c = v*row // Weight of the core
10 row_lead = 11.3 // From table 11.1
11 W_lead = row_lead * v
12 F_b = ((W_lead - W_c)*9.81)/1000 // Buoyancy Force
          in N so divided by 1000
13 printf('Buoyancy Force = %.1f N',F_b)
```

Scilab code Exa 11.2 Rotation speed in true centrifugal casting

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 11.2 – Rotation speed in true centrifugal
        casting
6 // Given that
7 D = 0.25 // Diameter of the mold in m
8 g = 9.8 // Acceleration of gravity
9 GF = 65 // G-factor
10 N = (30/%pi)*sqrt((2*g*GF)/D)
11 printf('Rotational Speed = %.1f rev/min',N)
```

Chapter 13

Shaping Processes for Plastics

Scilab code Exa 13.1 Extrusion flow rates

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 13.1 – Extrusion flow rates
6 // Given that
7 D = 75 // Diameter of the extruder barrel in mm
8 d_c = 6 // channel depth in mm
9 N = 1 // Screw rotational speed
10 A = 20 // flight angle
11 p = 7.0*10^6 // head pressure at the end of the
                  barrel in Pa
12 L = 1.9 // Length of the barrel in m
13 eta = 100 // Viscosity of the polymer in Pa-s
14 Q_d = 0.5*(%pi^2)*((D*10^-3)^2)*(d_c*(10^-3))*sind
          (A)*cosd(A)
15 Q_b = (p*%pi*(D*10^-3)*((d_c*10^-3)^3)*(sind(A)^2))
          /(12*eta*L)
16 Q_x = (Q_d - Q_b)
17 a = 53525*10^-9
```

```

18 printf('volume flow rate of the plastic in the
           barrel = %.5e m^3/s',Q_x)
19 // Answer varies due to round off error

```

Scilab code Exa 13.2 Extruder and Die Characteristics

```

1 clear; // Remove clear , clc if you want to access
          the stored variables
2 clc
3 // Example 13.2 – Extruder and Die Characteristics
4 // Given that
5 D = 75 // Diameter of the extruder barrel in mm
6 L = 1.9 // Length of the barrel in m
7 N = 1 // Screw rotational speed
8 d_c = 6 // channel depth in mm
9 A = 20 // flight angle
10 eta = 100 // Viscosity of the polymer in Pa-s
11 D_d = 6.5 // Die opening diameter in mm
12 L_d = 20 // die opening length in mm
13 Q_max = 0.5*(%pi^2)*((D*10^-3)^2)*N*(d_c*10^-3)*sind
          (A)*cosd(A)
14 P_max = (6*%pi*D*10^-3*N*eta*cotd(A))/((d_c*10^-3)
          ^2) // Answers may vary due to round off error
15 K_s = (%pi*(D_d*(10^-3))^4)/(128*eta*(L_d*(10^-3)))
16 p = (Q_max - K_s)/(Q_max/P_max) - K_s
17 //Q_x_p = Q_max - (Q_max/P_max)*p
18 Q_x = Q_max - ((Q_max/P_max)*p)
19 printf('Q_max = %f m^3/s \n P_max = %.0f Pa\nShape
          Factor = %2.2e m^5/Ns \n Q_x = %.3e\n p = %e Pa\n
          ',Q_max,P_max,K_s,Q_x,p)
20 // the answers may vary due to round off error
21 // Answer in the textbook is wrong

```

Scilab code Exa 13.3 Shrinkage in Injection Molding

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 13.3 – Shrinkage in Injection Molding
6 // Given that
7 S = 0.025 // Shrinkage from Table 13.1
8 D_p = 80 // Molded part dimension in mm
9 D_c = D_p + (D_p*S)+(D_p*S^2)
10 printf('The dimension of the mold cavity that will
           compensate = %.2f mm \n',D_c)
```

Chapter 18

Bulk Deformation Processes in Metalworking

Scilab code Exa 18.1 Flat Rolling

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 18.1 – Flat Rolling
6 // Given that
7 w = 300 //width of strip
8 t = 25 // Thickness in mm
9 t_r = 22 // reduced thickness in mm
10 K = 275 // flow curve
11 n = 0.15
12 N = 50 // Roll speed in rev/min
13 d = t - t_r // Draft attempted in the rolling
        operation in mm
14 mew = 0.12 // coefficient of friction between the
        rolls and the work
15 r = 250 // radius of the roller
16 d_max = (mew^2)*r // Maximum possible draft for the
```

```

        given coefficient of friction in mm
17 L = sqrt(r*(t-t_r)) // Contact length in mm
18 epsilon = log(t/t_r) //
19 Y_f = (K*(epsilon^n))/1.15 // Average flow stress
    in MPa
20 F = Y_f*w*L // Rolling force in N
21 T = 0.5*F*L*(10^-3) // Torque required to drive each
    roll in N-m(10^-3)
22 P = 2*pi*N*F*L*(10^-3) // Power obtained in N-m/min
23 P_watts = P* 0.01667
24 HP = P_watts/745.7 // One horsepower = 745.7 W
25 printf('Roll Force = %.0f N \nTorque = %.0f N-m \
    nHorse Power = %.0f hp ',F,T,HP)
26 // Answer in textbook is wrong

```

Scilab code Exa 18.2 Open die forging

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
    the stored variables
4 clc
5 // Example 18.2 – Open die forging
6 // Given that
7 D = 50 // diameter
8 h = 75 // height
9 h_a = 62 // Intermediate height
10 F = 0
11 epsilon = 0.002
12 mew = 0.1
13 K = 350
14 n = 0.17
15 A = %pi*((D^2)/4) // Area
16 V = h*%pi*((D^2)/4) // Workpiece volume
17 Y_f = K*epsilon^n

```

```

18 K_f = 1 + ((0.4*mew*D)/h)
19 F = K_f*Y_f*A // forging force in N
20 epsilon_a = log(h/h_a) // At height 62 mm
21 Y_fa = K*epsilon_a^n // At height 62 mm
22 A_a = V/h_a // At height 62 mm, assuming constant
    volume and neglecting barreling
23 D_a = sqrt((4*A_a)/%pi) // Diameter at height 62 mm
24 K_fa = 1 + ((0.4*mew*D_a)/h_a)
25 F_a = K_fa*Y_fa*A_a // forging force in N at 62 mm
26 h_b = 49 // Intermediate height at 49 mm
27 epsilon_b = log(h/h_b) // At height 49 mm
28 Y_fb = K*epsilon_b^n // At height 49 mm
29 A_b = V/h_b // At height 49 mm, assuming constant
    volume and neglecting barreling
30 D_b = sqrt((4*A_b)/%pi) // Diameter at height 49 mm
31 K_fb = 1 + ((0.4*mew*D_b)/h_b)
32 F_b = K_fb*Y_fb*A_b // forging force in N at 49 mm
33 h_c = 36 // Intermediate height at 36 mm
34 epsilon_c = log(h/h_c) // At height 36 mm
35 Y_fc = K*epsilon_c^n // At height 36 mm
36 A_c = V/h_c // At height 36 mm, assuming constant
    volume and neglecting barreling
37 D_c = sqrt((4*A_c)/%pi) // Diameter at height 36 mm
38 K_fc = 1 + ((0.4*mew*D_c)/h_c)
39 F_c = K_fc*Y_fc*A_c // forging force in N at 36 mm
40 printf('The Forging force at begin = %.0f N \n The
    Forging force at intermediate height 62mm = %.0f
    N \n The Forging force at intermediate height 49
    mm = %.0f N \n The Forging force at intermediate
    height 36mm = %.0f N \n ',F,F_a,F_b,F_c)
41 // Answer in textbook is wrong

```

Scilab code Exa 18.3 Extrusion Pressures

```
1 // OS – Windows 10 (64 bit)
```

```

2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
    the stored variables
4 clc
5 // Example 18.3 - Extrusion Pressures
6 // Given that
7 L = 75
8 D_o = 25
9 a = 0.8
10 b = 1.5
11 r_x = 4 // Extrusion ration
12 K = 415 // Strength Coefficient in MPa
13 n = 0.18 // Strain hardening exponent
14 epsilon = log(r_x)
15 epsilon_x = a + (b*log(r_x))
16 Y_f = (K*(epsilon^n))/(1+n)
17 p = Y_f*(epsilon_x + ((2*L)/D_o))
18 L50 = 50
19 L25 = 25
20 L0 = 0
21 p_50 = Y_f*(epsilon_x + ((2*L50)/D_o))
22 p_25 = Y_f*(epsilon_x + ((2*L25)/D_o))
23 p_0 = Y_f*(epsilon_x + ((2*L0)/D_o))
24 printf('The pressure applied at L=75 is %.0f MPa\
nThe pressure applied at L=50 is %.0f MPa\nThe
pressure applied at L=25 is %.0f MPa\nThe
pressure applied at L=0 is %.0f MPa',p,p_50,
p_25,p_0)

```

Scilab code Exa 18.4 Stress and Force in Wire drawing

```

1 // OS - Windows 10 (64 bit)
2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
    the stored variables

```

```

4 clc
5 // Example 18.4 – Stress and Force in Wire drawing
6 // Given that
7 alpha = 15
8 D_o = 2.5 // Starting diameter in mm
9 D_f = 2 // Final diameter in mm
10 K = 205 // Strength coefficient in MPa
11 n = 0.20 // Strain hardening exponent
12 mew = 0.07 // Coefficient of friction at the work
    and die interface
13 D = (D_o+D_f)/2 // Average diameter of work during
    drawing in mm
14 L_c = (D_o-D_f)/(2*sind(alpha)) // Contact length of
    the work with the draw die
15 phi = 0.88 + 0.12 *(D/L_c)
16 A_o = (%pi/4)*D_o^2
17 A_f = (%pi/4)*D_f^2
18 epsilon = log(A_o/A_f)
19 Y_f = (K*epsilon^n)/(1+n) // Average flow stress
20 sigma_d = Y_f*(1+(mew/tand(alpha)))*phi*epsilon
21 F = A_f*sigma_d
22 printf('The Draw stress = %.0f MPa\n The Draw force
    = %.1f N\n',sigma_d,F)
23 // the answers may vary due to round off error

```

Chapter 19

Sheet Metalworking

Scilab code Exa 19.1 Blanking clearance and force

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 19.1 – Blanking clearance and force
6 // Given that
7 b = 3.2
8 D_b = 150 // Die opening diameter in mm
9 A_c = 0.075 // From Table 19.1 the clearance
                allowance for half-hard cold rolled steel
10 F_s = 310 // Shear strength
11 c = A_c*b
12 d_p = D_b - 2*c // Punch Diameter in mm
13 L = %pi*D_b // Length of the cut edge
14 F = F_s*L*b
15 printf('The appropriate punch and die diameter = %.2
f & %d \n The Blanking force = %f N',d_p,D_b,F)
```

Scilab code Exa 19.2 Sheet metal Bending

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 19.2 – Sheet-metal Bending
6 // Given that
7 TS = 450 // Tensile Strength in MPa
8 D = 25 // Die opening diameter in mm
9 alpha = 60 // Bend angle
10 alpha_d = 120 // Included angle
11 K_bf = 1.33
12 w = 44.5 // width
13 R = 4.75 // Bend radius in mm
14 K_ba = 0.33
15 t = 3.2 // Stock thickness in mm
16 A_b = (2*pi*(alpha/360))*(R+(K_ba*t))
17 blank_size = 38 + A_b + 25 // 35 and 25 are shown in
        figure 19.15
18 F = (K_bf*TS*w*(t^2))/D
19 printf('The Length of the blank = %.2f mm \n Force =
        %.0f N',blank_size,F)
```

Scilab code Exa 19.3 Cup Drawing

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 19.3 – Cup Drawing
6 // Given that
7 D_b = 138 // Starting blank size in mm
```

```

8 D_p = 75 // Cup inside diameter in mm
9 t = 2.4 // Stock thickness in mm
10 DR = D_b/D_p // Drawing ratio
11 r = (D_b-D_p)/D_b // reduction
12 check = (t/D_b)*100
13 printf('The drawing ratio = %.2f \n',DR)
14 if DR <= 2 then
15     printf('The Drawing operation is Feasible')
16 else
17     printf('The Drawing operation is Not-Feasible')
18 end
19 // Answer varies due to round off error

```

Scilab code Exa 19.4 Forces in Deep drawing

```

1 clear; // Remove clear , clc if you want to access
        the stored variables
2 clc
3 // Example 19.4 – Forces in Deep drawing
4 // Given that
5 D_p = 75
6 t = 2.4 // Original blank thickness in mm
7 TS = 300 // Tensile strength in MPa
8 D_b = 138 // Blank diameter in mm
9 Y = 175 // Yield strength in MPa
10 R_d = 6 // Die corner radius
11 F = %pi*D_p*t*TS*((D_b/D_p)-0.7) // Maximum drawing
        force in N
12 F_h = 0.015*Y*%pi*((D_b^2)-(D_p +(2.2*t)+(2*R_d))^2)
13 printf('Maximum drawing force = %.0f N \nHolding
        force = %.0f N',F,F_h)

```

Chapter 20

Theory of Metal Machining

Scilab code Exa 20.1 Orthogonal Cutting

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 20.1 – Orthogonal Cutting
6 // Given that
7 alpha = 10 // Rake angle of tool
8 t_o = 0.50 // Chip thickness before cut in mm
9 t_c = 1.125 // Chip thickness after cut in mm
10 r = t_o/t_c // Chip thickness ratio
11 phi = atand(((r*cosd(alpha))/(1-(r*sind(alpha)))))
12 r = tand(phi - alpha) + cotd(phi)
13 printf('The Shear plane angle = %.1f degrees \n The
        Shear strain = %.3f',phi,r)
14 // The answers may vary due to round off error
```

Scilab code Exa 20.2 Shear stress in Machining

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
      the stored variables
4 clc
5 // Example 20.2 – Shear stress in Machining
6 // Given that
7 alpha = 10 // Rake angle of tool
8 t_o = 0.50 // Chip thickness before cut in mm
9 t_c = 1.125 // Chip thickness after cut in mm
10 r = t_o/t_c // Chip thickness ratio
11 F_c = 1559 // Cutting force in N
12 F_t = 1271 // Thrust force in N
13 w = 3 // Width of orthogonal cutting
14 phi = atand(((r*cosd(alpha))/(1-(r*sind(alpha)))))
15 F_s = (F_c*cosd(phi))-(F_t*sind(phi))
16 A_s = (t_o*w)/(sind(phi)) // Shear plane area
17 tau = F_s/A_s
18 printf('The shear strength of the work material = %
.0f MPa',tau)

```

Scilab code Exa 20.3 Estimating Friction Angle

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
      the stored variables
4 clc
5 // Example 20.3 – Estimating Friction Angle
6 // Given that
7 alpha = 10 // Rake angle of tool
8 t_o = 0.50 // Chip thickness before cut in mm
9 t_c = 1.125 // Chip thickness after cut in mm
10 r = t_o/t_c // Chip thickness ratio
11 phi = atand(((r*cosd(alpha))/(1-(r*sind(alpha)))))

```

```

12 beta = (2*(45))+alpha - (2*phi)
13 mu = tand(beta)
14 printf('The Friction angle = %.1f degrees \n The
           Coefficient of friction = %.2f \n',beta,mu)
15 // The answers vary due to round off error

```

Scilab code Exa 20.4 Power Relations in machining

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 20.4 – Power Relations in machining
6 // Given that
7 t_o = 0.50 // Data from the previous example 20.1
8 w = 3 // Data from the previous example 20.2
9 F_c = 1559 // Data from the previous example 20.2
10 v = 100 // Cutting speed
11 // In the textbook it was 1557.
12 P_c = (F_c*v)
13 U = P_c/(v*10^3*t_o*w)
14 printf('The cutting power = %.0f J/min \nThe
           specific energy = %.3f N/mm^3 \n',P_c,U)

```

Scilab code Exa 20.5 Cutting Temperature

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 20.5 – Cutting Temperature

```

```
6 // Given that
7 row = 3
8 C = 1000
9 t_o = 0.50 // Data from the previous example 20.1
10 w = 3 // Data from the previous example 20.2
11 F_c = 1559 // Data from the previous example 20.2
12 v = 100 // Cutting speed
13 // In the textbook it was 1557.
14 K = 50
15 P_c = (F_c*v)
16 U = P_c/(v*10^3*t_o*w)
17 v_c = (v*1000)/60
18 delta_T = ((0.4*U)/(row*10^-6*C))*(((v_c*t_o)/K)
    ^0.333)
19 printf('The mean temperature = %.0f C',delta_T)
20 // The answers vary due to round off error
```

Chapter 21

Machining Operations and Machine Tools

Scilab code Exa 21.1 Machining Time in Turning

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 21.1 – Machining Time in Turning
6 // Given that
7 v = 2000 // Cutting speed
8 D_o = 120 // Work Diameter
9 L = 450 // Length of the workpiece in mm
10 f = 0.25 // feed
11 d = 2.2 // Depth of cut in mm
12 T_m = (%pi*D_o*L)/(f*v) // Cutting time in min
13 R_mr = v*f*d // Material removal rate in mm^3/s
14 printf('The Cutting time = %.1f s\nMaterial Removal
        Rate = %.0f mm^3/s ',T_m,R_mr)
```

Scilab code Exa 21.2 Machining Time in Drilling

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 21.2 – Machining Time in Drilling
6 // Given that
7 v = 0.5 // Cutting speed
8 D = 20 // Diameter of twist drill
9 f = 0.22 // feed
10 theta = 118 // Point angle
11 t = 15 // thickness of plate
12 N = (v*1000)/(%pi*D)
13 f_r = N*f
14 A = v*D*tand(90 - theta/2)
15 T_m = (t+A)/f_r
16 R_mr = (%pi*(D^2)*f_r)/4
17 printf('The machining time = %.0f s\n Material
           removal rate = %.1f mm^3/s', T_m, R_mr)
18 // Answer varies due to round off error
```

Scilab code Exa 21.3 Machining Time in Peripheral Milling

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 21.3 – Machining Time in Peripheral
        Milling
6 // Given that
7 v = 0.50 // Cutting speed
8 D = 65 // Diameter of milling cutter
```

```
9 n_t = 4 // teeth on milling cutter
10 f = 0.24 // Feed per tooth
11 t_i = 56 // Thickness intial
12 t_f = 50 // Thickness final
13 w = 60 // width
14 L = 320
15 d = t_i-t_f // Depth of cut
16 N = (v*1000)/(%pi*D)
17 f_r = N*n_t*f
18 A = sqrt(d*(D-d)) // Approach distance
19 T_m = (L + A) / f_r
20 R_mr = w*d*f_r
21 printf('The machining time = %.1f s\n Material
           removal rate = %.0f mm^3/s', T_m, R_mr)
22 // The answers vary due to round off error
```

Chapter 22

Cutting Tool Technology

Scilab code Exa 22.1 Taylor Tool life equation

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 22.1 – Taylor Tool life equation
6 // Given that
7 v1 = 160
8 T1 = 5
9 v2 = 100
10 T2 = 41
11 //  $160(5)^n = 100(41)^n$ 
12 // Taking natural logarithms of each term
13 n = (log(v1)-log(v2))/(log(T2)-log(T1))
14 C = v1*(T1)^n
15 printf('The values of n and C are = %.3f & %.0f ',n,C)
```

Chapter 23

Economic and Product Design Considerations in Machining

Scilab code Exa 23.1 Machinability

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 23.1 – Machinability
6 // Given that
7 n1 = 0.28
8 n2 = 0.27
9 c1 = 350
10 c2 = 440
11 T = 60
12 V_60 = (c1/T^n1)
13 V1_60 = (c2/T^n2)
14 MR = V1_60/V_60
15 printf('The Machinability rating = %.2f ',MR)
```

Scilab code Exa 23.2 Surface Roughness

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 23.2 – Surface Roughness
6 // Given that
7 r = 1.2 // Nose radius in mm
8 v = 100 // Cutting speed
9 f = 0.25 // Feed
10 R_i = ((f^2)/(32*r))*1000 // Ideal surface roughness
        , 1000 for micron meters
11 R_a = 1.25 * R_i // Figure 23.2, the ratio of actual
        to ideal roughness for ductile material at 100
        m/min is approximately 1.25
12 printf('The Actual Surface roughness = %.f um \n',
        R_a)
```

Scilab code Exa 23.3 Determining cutting speeds in machining economics

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 23.3 – Determining cutting speeds in
        machining economics
6 // Given that
7 n= 0.125 // Taylor's tool life exponent
8 C = 70 // From Table 23.2
9 T_t = 2 // Tool change time in min
10 C_o = 30/60 // Converting $30/hr to $0.50/min
11 C_t = 3 // Tooling cost
```

```

12 v_max = C/(((1/n)-1)*T_t)^n
13 v_min = C*((n/(1-n))*(C_o/((C_o*T_t)+C_t)))^n
14 printf('Cutting speed for maximum production rate =
    %.0f m/min\nCutting Speed for minimum cost = %.0f
    m/min',v_max,v_min)

```

Scilab code Exa 23.4 Production rate and cost in machining economics

```

1 // OS - Windows 10 (64 bit)
2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 23.4 - Production rate and cost in
        machining economics
6 // Given that
7 n= 0.125 // Taylor's tool life exponent
8 C = 70 // From Table 23.2
9 T_t = 2 // Tool change time in min
10 C_o = 30/60 // Converting $30/hr to $0.50/min
11 C_t = 3 // Tooling cost
12 D = 0.1 // Diameter
13 L = 0.5 // Work part length
14 f = 0.25 // feed in mm/rev
15 T_h = 5 // Handling time per piece
16 v_max = C/(((1/n)-1)*T_t)^n // Cutting speed for
        maximum production in m/min
17 v_min = C*((n/(1-n))*(C_o/((C_o*T_t)+C_t)))^n // 
        Cutting speed for minimum production cost per
        piece in m/min
18 T_m = (%pi*D*L)/(v_max*f*10^-3) // Machining Time in
        minutes
19 T = (C/v_max)^8
20 n_p = T/T_m // Number of pieces per tool
21 T_c = T_h + T_m +(T_t/n_p) // Average production

```

```

        cycle time for the operation
22 R_p = 60/T_c // Hourly production rate
23 C_c = (C_o*T_h)+(C_o*T_m)+((C_o*T_t)/n_p)+(C_t/n_p)
24 T_m_min = (%pi*D*L)/(v_min*f*10^-3)
25 T_min = (C/v_min)^8 // Tool life in minutes
26 n_p_min = T_min/T_m_min // Number of pieces per tool
27 T_c_min = T_h + T_m_min +(T_t/n_p) // Average
    production cycle time for the operation
28 R_p_min = 60/T_c_min // Hourly production rate
29 C_c_min = (C_o*T_h)+(C_o*T_m_min)+((C_o*T_t)/n_p_min
    )+(C_t/n_p_min)
30
31 printf('Hourly Production Rate = %.1f pc/hr \n
    Average cost per piece = %.2f /pc \n Hourly
    Production Rate for min cutting speed = %.1f pc/
    hr \n Average cost per piece for minimum cutting
    speed= %.0f /pc',R_p,C_c,R_p_min,C_c_min)
32 // Answers may vary due to round of error

```

Chapter 25

Nontraditional Machining and Thermal Cutting Processes

Scilab code Exa 25.1 Electrochemical Machining

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 25.1 – Electrochemical Machining
6 // Given that
7 C = 3.44*10^-2 // Specific removal rate from Table
                    25.1
8 l = 10 // length of rectangular hole
9 b = 30 // breadth of rectangular hole
10 A = l*b // Area of electrode
11 t = 12 // thickness of plate
12 I = 1200
13 eta = 0.95 // Expected efficiency
14 f_r = (C*I)/A // Feed rate at current lvl of 1200
                    Amps
15 f_r95 = f_r*eta // Actual Feed rate at 95%
                    efficiency
```

```
16 T_m = (t/f_r95)/60
17 printf('Feed rate at 95 percentage efficiency = %.4f
           mm/s \n Time to machine through the 12-mm plate
           = %.2f min \n', f_r95, T_m)
```

Scilab code Exa 25.2 Electric Discharge Machining

```
1 // OS - Windows 10 (64 bit)
2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 25.2 - Electric Discharge Machining
6 // Given that
7 K = 664 // Constant of Proportionality
8 I = 25 // Discharge current in amps
9 T_m = 1083 // Melting temperature of copper from
          Table 4.1
10 R_mr = (K*I)/((T_m)^1.23) // Metal removal rate
11 printf('The Metal removal rate = %.2f mm^3/s ', R_mr)
```

Chapter 27

Surface Processing Operations

Scilab code Exa 27.1 Electroplating

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 27.1 – Electroplating
6 // Given that
7 A = 125*100 // Surface area of steel part in mm^2
8 C = 3.42*10^-2 // Plating constant from Table 27.1
9 E = 0.95 // Cathode efficiency for nickel from Table
        27.1
10 I = 12 // Current
11 t = 15 // time during which current is applied
12 V = E*C*I*t*60
13 d = V/A
14 printf('The average plating thickness = %.3f mm\n',d
        )
```

Chapter 28

Fundamentals of Welding

Scilab code Exa 28.1 Power density in Welding

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 28.1 – Power density in Welding
6 // Given that
7 d_i = 5 // diameter of inner circle in mm
8 d_c = 12 // Concentric circle diameter in mm
9 Q = 3000 // Heat source transfers
10 n = 0.70 // 70 percentage distribution follows
11 nc = 0.90 // 90 percentage distribution for
        concentric cirlce
12 A = (%pi*d_i^2)/4 // Area of inner circle
13 P = Q*n // Power inside the area in W
14 PD_inner = P/A
15 A_concentric = (%pi*(d_c^2 - d_i^2))/4 // Area of
        the ring outside the inner circle
16 P_concentric = Q*nc - P
17 PD_concentric = P_concentric/A_concentric
18 printf('Power density for 5mm diameter = %.0 f W/mm^2
```

```

    \nPower density for 12mm diameter = %.1f W/mm^2
    \n',PD_inner,PD_concentric)
19 // Observation: The power density seems high enough
   for melting in the inner circle , but probably not
   sufficient in the ring that lies outside this
   inner circle

```

Scilab code Exa 28.2 Welding Travel Speed

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
   the stored variables
4 clc
5 // Example 28.2 – Welding Travel Speed
6 // Given that
7 T_m = 1760 // Melting point temperature from Table
   28.2
8 K = 3.33*10^-6 // Constant when Kelvin scale is used
9 f1 = 0.7 // Heat transfer factor
10 f2 = 0.5 // Melting factor
11 R_h = 3500 // Rate of input energy generated by the
   welding power source
12 A_w = 20 // Cross-sectional area in mm^2
13 U_m = K*T_m^2
14 v = (f1*f2*R_h)/(U_m*A_w)
15 printf('The travel speed = %.2f mm/s \n',v)
16 // Answers may vary due to round off error

```

Chapter 29

Welding Processes

Scilab code Exa 29.1 Power in arc welding

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 29.1 – Power in arc welding
6 // Given that
7 I = 300 // Current in Amperes
8 E = 20 // Voltage in V
9 f1 = 0.7 // Heat transfer factor from Table 29.1
10 f2 = 0.5 // Melting factor
11 Um = 10 // melting energy for the metal in J/mm^3
12 P = I*E // Power in the arc-welding operation in W
13 R_HW = f1*f2*I*E // Rate of heat used for welding in
        J/s
14 R_VW = R_HW/Um // Volume of rate of metal welded in
        mm^3/s
15 printf('Power in the arc-welding operation = %.0f W
        \n Rate of heat used for welding = %.0f J/s \n
        Volume of rate of metal welded = %.0f mm^3/s \n',
        P,R_HW,R_VW)
```

```
16 // the answer in the textbook was wrong
```

Scilab code Exa 29.2 Resistance welding

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 29.2 – Resistance welding
6 // Given that
7 I = 12000 // Current in Amps
8 R = 0.0001 // Resistance in ohms
9 t = 0.2 // time in seconds
10 d = 6 // electrodes diameter in mm
11 T = 3 // thickness in mm
12 Um = 12 // Melting energy of the metal in J/mm^3
13 H = (I^2)*R*t // Heat generated in the operation
14 v = T*((%pi*(d^2))/4) // Volume of the weld nugget (
        assumed disc-shaped)
15 Hw = v*Um // Heat required to melt this volume of
        metal in J
16 Remaining_heat = H - Hw
17 printf('The remaining heat = %.0f J \n ',  

        Remaining_heat)
```

Scilab code Exa 29.3 Heat generation in oxyacetylene welding

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
```

```

5 // Example 29.3 – Heat generation in oxy-acetylene
   welding
6 // Given that
7 Um = 0.3 // Unit energy required to melt the metal
8 f1 = 0.20 // Heat transfer factor
9 D = 9 // Work surface diameter
10 R_H = Um*55*10^6
11 R_Hj = R_H/3600 // Rate of heat generated in Joules/
   sec
12 p = 0.75 // 75% heat from the flame
13 Q = f1*R_Hj // Heat received at the work surface
14 A = (%pi*(D)^2)/4
15 PD = (p*Q)/A
16 printf('The rate of heat generated by the torch = %
   .0f J/s \nThe rate of heat received at the work =
   %.0f J/s\n Power density in the circle = %.1f W/
   mm^2 ',R_Hj,Q,PD)

```

Chapter 31

Mechanical Assembly

Scilab code Exa 31.1 Threaded Fasteners

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 31.1 – Threaded Fasteners
6 // Given that
7 C_t = 0.22 // Torque coefficient whose value
        typically ranges between 0.15 and 0.25
8 D = 8 // Nominal bolt diameter
9 F = 275 // Specified preloaded tension force in N
10 p = 1.25
11 T = C_t*D*F // Required Torque
12 A_s = (%pi/4)*((D - (0.9382*p))^2) // Area of the
        minor diameter
13 sigma = F/A_s
14 printf('The required torque = %.0 f N-mm\n The stress
        on the bolt = %.2 f MPa \n',T,sigma)
```

Scilab code Exa 31.2 Expansion fit

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 31.2 – Expansion fit
6 // Given that
7 alpha = 12*10^-6 // Thermal expansion for steel from
        Table 4.1
8 D_2 = 30 // Inner diameter in mm
9 D_1 = 30.015 // Shaft diameter in mm
10 T_1 = 20 // Room Temperature in C
11 c = 0.03 // Clearance
12 T_2 = (((D_2-c) - D_1)/(alpha*D_1))+T_1
13 E = 209*10^3 // Modulus of elasticity in MPa from
        Table 3.1
14 D_c = 50 // Outer diameter of the collar
15 D_p = 30.025 // Pin diameter
16 i = 0.015
17 P_f = (E*i*(D_c^2 - D_p^2))/(D_p*D_c^2)
18 Max_sigma_e = (2*P_f*D_c^2)/(D_c^2 - D_p^2)
19 printf('The Temperature to which the shaft must be
        cooled for assembly = %.1f C \n The radial
        pressure at room temperature after assembly = %.1
        f MPa \n The maximum effective stress on the
        collar = %.0f MPa',T_2,P_f,Max_sigma_e)
```

Chapter 32

Rapid Prototyping and Additive Manufacturing

Scilab code Exa 32.1 Build cycle time in stereolithography

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 32.1 – Build cycle time in
        stereolithography
6 // Given that
7 b = 40
8 A1 = b^2 // Cross-sectional area of the base
9 t = 5
10 H = 52 // Height of cup
11 tl = 0.10 // Layer thickness
12 T_su = 20 // Setup time
13 A2 = 40^2 - 32^2
14 v = 950 // Speed
15 TH = H - t // Total height
16 n_l = t/tl // Number of layers to build base
17 n_b = TH/tl // Number of layers to build the walls
```

```

18 DE_p = 0.25 //Spot diameter
19 T_r = 21 // Repositioning and recoating time for
   each layer
20 //A2 =
21 T_i = (A1/(v*DE_p))+T_r
22 T_i_wall = (A2/(v*DE_p)) + T_r
23 T_c = (T_su*60) + (n_l*T_i) + (n_b*T_i_wall)
24 printf('Total build cycle time = %.0f s', T_c)

```

Scilab code Exa 32.2 Cost per piece in additive manufacturing

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
   the stored variables
4 clc
5 // Example 32.2 – Cost per piece in additive
   manufacturing
6 // Given that
7 w = 50 // Weeks
8 d = 5 // days
9 h = 8 // hours per day
10 y = 4 // years
11 C_l = 24 // Labor rate
12 U_l = 0.25 // labor build cycle
13 T_c = 3.777 // Cycle time
14 T_pp = 6/60 // 6 min/part post processing time , 60
   is divided for minutes
15 h1 = 52
16 t = 5
17 H = h1-t // height of wall
18 b = 40
19 A1 = b^2 // Cross-sectional area of the base
20 A2 = b^2 - 32^2
21 C = 100000 // Cost of Stereolithography machine

```

```
22 NH = w*d*h // Numbers of hours of operation per year
23 MC = 120
24 C_eq = C/(y*NH) // Hourly equipment cost
25 V1 = d*A1
26 V2 = H*A2
27 V = V1+V2
28 C_m = (MC*10^-6)*(V)
29 C_pc = C_m + (((C_l*U_l)+C_eq)*T_c)+(C_l*T_pp)
30 printf('Cost per piece = $ %.2f /pc \n', C_pc)
```

Chapter 33

Processing of Integrated Circuits

Scilab code Exa 33.1 Number of Chips on Water

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 33.1 – Number of Chips on Water
6 // Given that
7 D_w = 190 // Diameter of the processable area of the
               wafer
8 L_c = 18 // Side dimension of the chip
9 n_c = 0.34*(D_w/L_c)^2.25
10 printf('IC chips = %.0f chips ',n_c)
```

Scilab code Exa 33.2 Rent s Rule

```
1 // OS – Windows 10 (64 bit)
```

```

2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
      the stored variables
4 clc
5 // Example 33.2 - Rent's Rule
6 // Given that
7 A = 17^2 // Processable area of the chip
8 n = 500
9 C = 0.89 // rents rule parameters
10 m = 0.45
11 n_ic = A*n
12 n_io = C*n_ic^m
13 C1 = 6.9 // rents rule parameters for 1
14 m1 = 0.12
15 n_iol1 = C1*n_ic^m1
16 printf('Number of Circuits = %.0f \n Rents Rule with
          C=0.89 and m = 0.45 = %.0f input/output
          terminals \n Rents Rule with C=6.9 and m = 0.12 =
          %.0f input/output terminals \n',n_ic,n_io,n_iol1)

```

Scilab code Exa 33.3 Yield in Water processing

```

1 // OS - Windows 10 (64 bit)
2 // Scilab version - 6.0.2
3 clear; // Remove clear , clc if you want to access
      the stored variables
4 clc
5 // Example 33.3 - Yield in Water processing
6 // Given that
7 D_w = 190 // Diameter of the processable area of the
      wafer
8 L_c = 10 // Side dimension of the chip
9 D = 0.002
10 n_c = 0.34*(D_w/L_c)^2.25
11 A = (%pi*D_w^2)/4

```

```
12 Y_m = 1/(1+((A/100)*D)) // Converting A in to Cm^2
13 number_good_chips = Y_m*n_c
14 printf('Number of Good Chips = %.2f chips',
    number_good_chips)
```

Chapter 37

Automation Technologies for Manufacturing systems

Scilab code Exa 37.1 Open loop Positioning

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 37.1 – Open-loop Positioning
6 // Given that
7 x = 75
8 p = 5 // Leadscrew pitch
9 A_ls = (360*x)/p // Lead screw rotation angle
10 r_g = 4
11 n_s = 48
12 V_t = 400
13 n_p = (r_g*n_s*A_ls)/360
14 N_ls = V_t/p
15 N_m = r_g*N_ls
16 f_p = (N_m*n_s)/60
17 printf('pulses required to move the table the
        specified distance = %.0f pulses\n Motor Speed =
```

```
% .0 f rev/min \n Pulse frequency required = % .0 f  
Hz\n ', n_p, N_m, f_p)
```

Scilab code Exa 37.2 NC Closed loop Positioning

```
1 // OS – Windows 10 (64 bit)  
2 // Scilab version – 6.0.2  
3 clear; // Remove clear , clc if you want to access  
        the stored variables  
4 clc  
5 // Example 37.2 – NC Closed-loop Positioning  
6 // Given that  
7 x = 75 // Table distance  
8 n_s = 100 // Pulses generated by Optical encoder  
9 p = 5 // Pitch  
10 f_r = 400 // feed rate  
11 r_g = 4 // Gear ratio  
12 n_p = (x*n_s)/p  
13 f_p = (f_r*n_s)/(60*p)  
14 N_ls = f_r/p  
15 N = r_g*N_ls  
16 printf('Pulses received = % .0 f pulses \n Pulse rate =  
% .2 f Hz \n Motor speed = % .f rev/min ', n_p, f_p, N)
```

Scilab code Exa 37.3 Control resolution accuracy and repeatability

```
1 // OS – Windows 10 (64 bit)  
2 // Scilab version – 6.0.2  
3 clear; // Remove clear , clc if you want to access  
        the stored variables  
4 clc  
5 // Example 37.3 – Control resolution accuracy and  
        repeatability
```

```
6 // Given that
7 p = 5 // Pitch
8 r_g = 4 // Gear ratio
9 n_s = 48
10 L = 550
11 B = 16
12 sigma = 0.005
13 CR_1 = p/(n_s*r_g)
14 CR_2 = L/(2^B - 1)
15 CR = max(CR_1,CR_2)
16 accuracy = 0.5*CR + 3*sigma
17 repeatability = 3*sigma
18 printf('Control resolution = %.4f mm\nAccuracy = %.4
          f mm\nRepeatability = %.3f mm\n',CR,accuracy,
          repeatability)
```

Chapter 38

Integrated Manufacturing Systems

Scilab code Exa 38.1 Manual Assembly Line

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 38.1 – Manual Assembly Line
6 // Given that
7 D_a = 90000 // Annual Demand
8 S_w = 5 // Number of Shifts/wk
9 H_sh = 8 // Hours/shift
10 T_r = 0.150 // In question given repositioning time
    as 9 sec , converted to min
11 R_p = D_a/(50*S_w*H_sh)
12 E = 0.95
13 T_wc = 55 // Work content time
14 E_b = 0.93 // Balancing Efficiency
15 T_c = (60*E)/R_p
16 T_s = T_c - T_r
17 w = T_wc/(T_s*E_b)
```

```
18 w_min = T_wc/T_c //Minimum possible number of  
    workers  
19 printf('Hourly Production rate to meet demand = %.0f  
        units/hr \n Number of workers and Workstations  
        required = %.0f Workers and %.0f Workstations \n  
        nIdeal minimum value = %.2f Workers\n',R_p,w,w,  
    w_min)
```

Scilab code Exa 38.2 Automated Transfer line

```
1 // OS – Windows 10 (64 bit)  
2 // Scilab version – 6.0.2  
3 clear; // Remove clear , clc if you want to access  
        the stored variables  
4 clc  
5 // Example 38.2 – Automated Transfer line  
6 // Given that  
7 p = 0.01 // Probability of station failure  
8 n = 20 // Number of stations  
9 T_c = 1  
10 T_b = 10 // Breakdown time  
11 F = p*n  
12 T_p= T_c + F*T_b  
13 R_p = 60/T_p  
14 R_c = 60/T_c  
15 E = (T_c/T_p)*100  
16 printf('Average Production rate = %.0f pc/hr \n  
        Efficiency = %.1f \n',R_p,E)
```

Scilab code Exa 38.3 Product Proliferation

```
1 // OS – Windows 10 (64 bit)  
2 // Scilab version – 6.0.2
```

```
3 clear; // Remove clear , clc if you want to access  
        the stored variables  
4 clc  
5 // Example 38.3 – Product Proliferation  
6 // Given that  
7 truck_models = 100  
8 wheel_base = 7  
9 basic_engine = 42  
10 axles = 43  
11 transmissions = 62  
12 rear_axles = 162  
13 annual_production = 130000 // Trucks  
14 Possible_combinations = truck_models*wheel_base*  
        basic_engine*axles*transmissions*rear_axles  
15 company_produce_trucks = Possible_combinations/  
        annual_production  
16 printf( '%d years without ever producing the same  
        truck twice ',company_produce_trucks)  
17 // Answers may vary due to round off error
```

Chapter 39

Process Planning and Production Control

Scilab code Exa 39.1 Make or buy cost comparison

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 39.1 – Make or buy cost comparison
6 // Given that
7 UC = 2.25 // Unit material cost in $ per unit
8 DL = 2 // Direct labor cost in $ per unit
9 LO = 3 // Labor overhead at 150% cost in $ per unit
10 EO = 1.75 // Equipment fixed cost in $ per unit
11 VC = 8 // Component vendor cost in $ per unit
12 TC = 9 // Home factory cost in $ per unit
13 CC = VC+EO+LO // Company cost
14 printf('The Cost to the company = %.2f in $\n',CC)
15 // If the equipment can be used to produce other
       components for which the internal prices are less
       than the corresponding external quotes , then a
       buy decision makes good economic sense.
```


Chapter 40

Quality Control and Inspection

Scilab code Exa 40.1 X and R charts

```
1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
          the stored variables
4 clc
5 // Example 40.1 – X and R charts
6 // Given that
7 m = 8
8 n = 4
9 A2 = 0.729 // Data from Table 40.2
10 D3 = 0 // Data from Table 40.2
11 D4 = 2.282 // Data from Table 40.2
12 x = [2.008 1.998 1.993 2.002 2.001 1.995 2.004
       1.999]
13 R = [0.027 0.011 0.017 0.009 0.014 0.020 0.024
       0.018]
14 s = [1 2 3 4 5 6 7 8] // Sample size
15 x_bar = mean(x)
16 R_bar = mean(R)
17 LCL = x_bar - (A2*R_bar)
18 UCL = x_bar + (A2*R_bar)
```

```

19 LCL = D3*R_bar
20 UCL = D4*R_bar
21 plot(s,x)
22 plot(s,R)
23 xtitle("Control Chart","Sample number , s","X-chart R
    -chart")

```

Scilab code Exa 40.2 Determining the Sigma level of a process

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 40.2 – Determining the Sigma level of a
        process
6 // Given that
7 N_u = 9056
8 N_o = 23
9 N_d = 479
10 N_du = 226
11 DPMO = 1000000*(N_d/(N_u*N_o))
12 DPM = 1000000*(N_d/N_u)
13 DUPM = 1000000*(N_du/N_u)
14 sigma = 3.4 // From table 40.3
15 printf('The Defects per Million Opportunities (DPMO)
        = %.0d \n The Defects per Million (DPM) = %d \n
        The Defective units per million (DUPM) = %d \nThe
        corresponding sigma level is about = %.1f ',DPMO,
        DPM,DUPM,sigma)
16 // Answer varies due to round off error

```

Scilab code Exa 40.3 Taguchi Loss Function

```

1 // OS – Windows 10 (64 bit)
2 // Scilab version – 6.0.2
3 clear; // Remove clear , clc if you want to access
        the stored variables
4 clc
5 // Example 40.3 – Taguchi Loss Function
6 // Given that
7 tolerance = 0.04 // (x-N) is the tolerance
8 M_c = 80 // Manufacturer cost in $
9 Product_prob = 0.75 // Product probability
10 replace_prob = 1 - Product_prob
11 E_L_x = Product_prob*M_c + replace_prob*0 // 
        Excepted cost of replacement and shipping
12 k = E_L_x/(tolerance)^2 // Constant of
        proportionality
13 tolerance1 = 0.01
14 L_x = k*(tolerance1)^2
15 printf('Constant of proportionality = %.0f in $\n
        The Significant reduction = %.2f ',k,L_x)

```
