

Scilab Textbook Companion for
Electrical Machines
by M. V. Despande¹

Created by
Vivek Kumar Thakur
B.Tech
Electrical Engineering
College Of Engineering Roorkee
College Teacher
Divya Arora
Cross-Checked by
Madhu N Belur

May 24, 2016

¹Funded by a grant from the National Mission on Education through ICT,
<http://spoken-tutorial.org/NMEICT-Intro>. This Textbook Companion and Scilab
codes written in it can be downloaded from the "Textbook Companion Project"
section at the website <http://scilab.in>

Book Description

Title: Electrical Machines

Author: M. V. Despande

Publisher: PHI Learning Pvt. Ltd., New Delhi

Edition: 1

Year: 2011

ISBN: 9788120340268

Scilab numbering policy used in this document and the relation to the above book.

Exa Example (Solved example)

Eqn Equation (Particular equation of the above book)

AP Appendix to Example(Scilab Code that is an Appednix to a particular Example of the above book)

For example, Exa 3.51 means solved example 3.51 of this book. Sec 2.3 means a scilab code whose theory is explained in Section 2.3 of the book.

Contents

List of Scilab Codes	4
1 Single phase transformer Principle and Constructions	5
2 Single phase transformer Operation and Testings	12
3 Three Phase Transformer Operation And Testing	22
4 Elements of Transformer Design	26
7 Principle And Construction of DC Machines	30
8 DC Machines Operations and Testing	40
9 Elements of DC Machine Design	48
11 Three Phase Induction Motors Principle and Characteristics	51
12 Three Phase Induction Motor Operation And Testing	65
13 Synchronous Machines	72
14 Synchronous Machines Generators	78
15 Synchronous Motors	85
16 Single Phase Induction Motors	89
17 AC Commutator Motors	92

List of Scilab Codes

Exa 1.1	Find the n ratio and load current referred to high voltage side and load impedance on low voltage side for full load and impedance referred to high voltage side	5
Exa 1.2	Find Power factor on no load and active current and magnetising current and copper loss in the primary winding and core loss	6
Exa 1.3	Find number of turns per limb on the high voltage and low voltage sides	7
Exa 1.4	Calculate equivalent resistance and reactance of lv side in terms of hv side And equivalent resistance and reactance of hv side in terms of lv side And total resistance and reactance of transformer in terms of hv side And total r and x in terms of lv side	8
Exa 1.5	Find terminal voltage on load and voltage on load at high voltage terminals and efficiency of transformer . .	9
Exa 1.6	Find impedance and percentage resistance and reactance	10
Exa 2.1	Find all day efficiency and commercial efficiency on full load and efficiency on half load	12
Exa 2.2	Find Efficiency of transformer at half load at and At what load will the efficiency be maximum and maximum	13
Exa 2.3	Find Percentage resistance and Regulation for power factors unity lagging and leading	14
Exa 2.4	Find Regulation on full load and at power factor lagging	15
Exa 2.5	Find Ro and Xo and Resistance reffered to lv side and Reactance reffered to lv side	16
Exa 2.6	Find voltage for hv voltage side on full load and at power factor lagging when secondary terminal voltage is 240 volts	17

Exa 2.7	Calculate ZXR referred to hv side and Regulation on full load at power factor lagging and Terminal voltage on lv side on full load at pf lagging and Efficiency of transformer when current 250A pf lagging is load connected to lv side and voltage at hv side	18
Exa 2.8	Determine Efficiency and Regulation at loading conditions	19
Exa 2.9	Find how they will share 750KVA load at power factor lagging	20
Exa 3.1	Find Secondary line voltage Line Current and output power for deltadelta and starstar and deltastar and stardelta	22
Exa 3.2	Calculate Phase and Line currents in High voltage and Low voltage windings of transformer	23
Exa 3.3	Find possible voltage ratio and output for connections BC11500V and AC2300V and BC2300V and AC11500V	24
Exa 4.1	Find Voltage per turn and area of core and area of conductor for lv and area of conductor for hv and Number of turns in lv and Number of turns in hv and Window area and Yoke and approx frame size and Copper used in windings	26
Exa 4.2	Find Voltage per turn and Area of core and Area of conductor for hv and Number of turns per phase in hv winding and Area of conductor in lv winding and Number of turns in lv winding and Window area and Yoke and frame size and copper used	27
Exa 7.3	Find effect of change in connection on voltage and current and output	30
Exa 7.6	Select a two circuit armature winding for a dc machine	31
Exa 7.7	Find Emf generated at 750rpm for lap wound And emf generated at 600rpm for wave wound And Speed to be driven for 400V for same flux per pole	32
Exa 7.8	Calculate Total armature current And Current per armature path And Generated emf	33
Exa 7.9	Find the speed at which it will run as a motor	34
Exa 7.10	Calculate the speed of the motor when it is loaded and takes 60A from the mains	34
Exa 7.11	Calculate Power and torque developed	35

Exa 7.12	Determine per pole Number of cross magnetising ampereturns and Demagnetising ampereturns	36
Exa 7.13	Find the time of Commutation	37
Exa 7.14	Find average reactance voltage produce due to commutation	37
Exa 7.15	Calculate the number of turns needed on each commutating pole	38
Exa 8.2	Find the current and voltage required	40
Exa 8.3	Find the resistance required	41
Exa 8.5	Find Speed at full load torque And Speed at double full load torque And Stalling torque	41
Exa 8.6	Find Input to generator from prime mover on full load and Efficiency on full load and Load current at which generator efficiency is maximum	42
Exa 8.7	Calculate Efficiency on full load and Efficiency on 40A input and Efficiency on 25A input and Full load speed regulation	43
Exa 8.10	Calculate efficiency of motor and generator	45
Exa 8.11	Calculate efficiency of motor	46
Exa 8.12	Find efficiency of motor	46
Exa 9.1	Find the dimensions of D and L	48
Exa 9.2	Find values of the 5 steps in a 6 stud starter for a dc shunt motor	49
Exa 11.1	Find Number of poles and Percentage slip	51
Exa 11.2	Find Speed of motor And Percentage Slip	52
Exa 11.3	Calculate Number of poles And Slip And Slip for full load torque if total resistance in rotor circuit is doubled	52
Exa 11.4	Calculate Mechanical power output And Torque And Maximum Torque And Speed at maximum torque And Power output when torque is maximum	53
Exa 11.5	Find Speed of the motor And Speed at which torque will be maximum And Ratio of maximum to full load torque	54
Exa 11.6	Calculate Speed at which mechanical power from rotor will be maximum And Maximum power	55

Exa 11.7	Find Current per phase in the rotor when rotor is at standstill and star connected impedance per phase is connected in series with rotor And when rotor runs at 3 percentage slip with short circuit at the slip rings	56
Exa 11.8	Find Percentage reduction in stator voltage and the power factor of the rotor circuit	57
Exa 11.9	Find the rotor copper loss per phase if motor is running at slip of 4 percent Mechanical power developed	58
Exa 11.10	Calculate Percentage slip And Rotor copper loss And Output from the rotor And Efficiency	59
Exa 11.11	Find Equivalent rotor current per phase And Stator current per phase And Power factor And Rotor input And Rotor copper losses And Torque And Mechanical power output from rotor And Stator input And Efficiency	60
Exa 11.12	Find Equivalent rotor current per phase And Stator current per phase And Power factor And Rotor input And copper losses And Torque And Mechanical power output from rotor And Stator input And Efficiency Solve it by APPROXIMATE equivalent circuit method	61
Exa 11.13	Find Equivalent rotor current And Stator current And Power factor And Stator input And Rotor input And Efficiency	63
Exa 12.1	Calculate No load power factor And Core friction loss And rm And power factor on short circuit And Equivalent impedance in series circuit And Rotor resistance referred to stator And Stator leakage reactance And Rotor leakage reactance referred to stator	65
Exa 12.2	Find Starting current And Starting torque	66
Exa 12.5	Find starting current in terms of full load current	67
Exa 12.7	Find starting torque in terms of full load torque	68
Exa 12.8	Find the Percentage tappings required	69
Exa 12.9	Find the line current at start	69
Exa 12.11	Calculate external resistance per phase	70
Exa 12.12	Find the dimensions of D and L	71
Exa 13.1	Find the frequency of voltage generated	72
Exa 13.2	Find Speed And number of poles	72
Exa 13.3	Find distribution factor of winding	73
Exa 13.4	Find coil span factor	74

Exa 13.5	Find frequency And Phase emf And Line emf	74
Exa 13.6	Find number of armature conductors in series per phase	75
Exa 13.12	Calculate synchronous reactance and synchronous impedance per phase	76
Exa 13.13	Estimate terminal voltage for Same excitation And Load current at power factor lagging	77
Exa 14.1	Find the excitation voltage in per unit	78
Exa 14.2	Find regulation by Two reaction method and Synchronous impedance method	79
Exa 14.3	Find Regulation and resultant excitation	80
Exa 14.5	Find the regulation of the machine	80
Exa 14.6	Find Synchronising power on full load And Synchronising torque	81
Exa 14.9	Find Armature current of second machine And Power factor of each machine	82
Exa 14.10	Find Load supplied by second machine and its power factor And Power factor of total load	83
Exa 15.6	Find Input power in KVA And Power factor	85
Exa 15.7	Find how much KVA should be supplied by synchronous motor And Power factor of synchronous motor	86
Exa 15.8	Find Power alternator can supply And Power factor of synchronous motor And Load taken by motor	87
Exa 15.9	Find efficiency of machine	87
Exa 16.1	Find Input Current And Power factor And Input power And Torque due to forward revolving field And Torque due to backward revolving field And Net torque and Output And Efficiency	89
Exa 16.2	Find equivalent circuit resistance	91
Exa 17.1	Find Speed And Power factor of motor	92

Chapter 1

Single phase transformer Principle and Constructions

Scilab code Exa 1.1 Find the n ratio and load current referred to high voltage side and load impedance on low voltage side for full load and impedance referred to high voltage side

```
1 //Caption:Find the (a) n ratio (b) load current
    referred to high voltage side (c) load impedance
    on low voltage side for full load (d) and
    impedance referred to high voltage side
2 //Exa:1.1
3 clc;
4 clear;
5 close;
6 P_s=25000 //Supplied power (in VA)
7 V_1=1910 //Voltage on primary side (in volt)
8 V_2=240 //Voltage on secondary side (in volt)
9 f=50 //frequency in hertz
10 n=V_1/V_2
11 disp(n, '(a)n-ratio=')
12 I_1=P_s/V_1
13 disp(I_1, '(b)load current referred to high voltage
    side (in A)=')
```

```

14 I_2=P_s/V_2
15 Z_2=V_2/I_2
16 disp(Z_2, '(c) load impedance on low voltage side for
      full load (in ohm)=')
17 Z_1=Z_2*(n^2)
18 disp(Z_1, '(d) impedance referred to high voltage side
      (in ohm)=')

```

Scilab code Exa 1.2 Find Power factor on no load and active current and magnetising current and copper loss in the primary winding and core loss

```

1 //Caption:Find (a) Power factor on no load (b)
      active current (c) magnetising current (d) copper
      loss in the primary winding (e) core loss
2 //Exa:1.2
3 clc;
4 clear;
5 close;
6 V_1=3300//Primary voltage (in volt)
7 V_2=240//Secondary voltage (in volt)
8 I_0=2//No load current (in A)
9 P=60//Power (in watt)
10 R=0.8//Resistance of the low voltage winding (in ohm
     )
11 Pf=P/(V_2*I_0)
12 disp(Pf, '(a) Power factor on no load=')
13 I_c=I_0*Pf
14 disp(I_c, '(b) Active current (in A]=')
15 theta=(acosd(Pf))
16 I_m=I_0*sin(theta)
17 disp(I_m, '(c) magnetising current is (in A]=')

```

```
18 Culoss=(I_0^2)*R
19 disp(Culoss, '(d) copper loss in the primary winding
      is (in watt)=')
20 Coreloss=P-Culoss
21 disp(Coreloss, '(e) core loss (in watt)=')
```

Scilab code Exa 1.3 Find number of turns per limb on the high voltage and low voltage sides

```
1 //Caption:Find number of turns per limb on the (a)
      high voltage and (b) low voltage sides
2 //Exa:1.3
3 clc;
4 clear;
5 close;
6 A=0.0386//cross sectional area of core(in m^2)
7 B=1//maximum flux density (in weber/m^2)
8 f=50//frequency (in hertz)
9 V_1=3300//voltage on primary side (in volt)
10 V_2=240//voltage on secondary side (in volt)
11 C=B*A
12 n_2=V_2/(4.44*C*f)
13 T_2=n_2/2
14 disp(T_2, '(a) number of turns on low voltage side is=
      ')
15 T_1=T_2*V_1/V_2
16 disp(T_1, '(b) number of turns on high voltage side is
      =')
```

Scilab code Exa 1.4 Calculate equivalent resistance and reactance of lv side in terms of hv side And equivalent resistance and reactance of hv side in terms of lv side And total resistance and reactance of transformer in terms of hv side And total r and x in terms of lv side

```
1 //Caption : Calculate (a) equivalent resistance and
    reactance of low voltage side in terms of high
    voltage side (b) equivalent resistance and
    reactance of high voltage side in terms of low
    voltage side (c) total resistance and reactance
    of transformer in terms of high voltage side (d)
    total resistance and reactance of transformer in
    terms of low voltage side
2 //Exa:1.4
3 clc;
4 clear;
5 close;
6 V_1=2200//Primary side voltage(in volt)
7 V_2=220//secondary side voltage(in volt)
8 f=50//frequency(in hertz)
9 r_1=1.25//Primary side resistance(in ohm)
10 x_1=4//Primary side reactance(in ohm)
11 r_2=0.04//Secondary side resistance(in ohm)
12 x_2=0.15//Secondary side reactance(in ohm)
13 n=V_1/V_2
14 R_2=(n^2)*r_2
15 disp(R_2,'(a) equivalent resistance of low voltage
    side in terms of high voltage side=')
16 X_2=(n^2)*x_2
17 disp(X_2,'equivalent reactance of low voltage side')
```

```

        in terms of high voltage side=')
18 R_1=r_1/(n^2)
19 disp(R_1, '(b) equivalent resistance of high voltage
      side in terms of low voltage side =')
20 X_1=x_1/(n^2)
21 disp(X_1, 'equivalent reactance of high voltage side
      in terms of low voltage side =')
22 R_t=r_1+R_2
23 disp(R_t, '(c) total resistance of transformer in
      terms of high voltage side=')
24 X_t=x_1+X_2
25 disp(X_t, 'total reactance of transformer in terms of
      high voltage side=')
26 R_e=r_2+R_1
27 disp(R_e, '(d) total resistance of transformer in
      terms of low voltage side=')
28 X_e=x_2+X_1
29 disp(X_e, 'total reactance of transformer in terms of
      low voltage side=')

```

Scilab code Exa 1.5 Find terminal voltage on load and voltage on load at high voltage terminals and efficiency of transformer

```

1 //Caption: (a) terminal voltage on load (b) voltage
      on load at high voltage terminals (c) efficiency
      of transformer
2 //Exa:1.5
3 clc;
4 clear;
5 close;
6 n=10//ratio of high voltage to low voltage

```

```

7 V_1=200 //Voltage on low voltage side(in volt)
8 x_m=231 //Magnetising resistance(in ohms)
9 r_c=400 //Core loss resistance(in ohms)
10 r_e=0.1 //Equivalent resistance referred to low
    voltage side(in ohms)
11 x_e=0.5 //Equivalent reactance referred to low
    voltage side(in ohms)
12 r_l=7.9 //Load resistance(in ohms)
13 x_l=5.5 //Load reactance(in ohms)
14 I_m=V_1/x_m
15 I_c=V_1/r_c
16 I_0=I_c+(%i*I_m)
17 R_l=r_l+r_e
18 X_l=x_l+x_e
19 I=V_1/(R_l+(%i*X_l))
20 I_1=I+I_0
21 V_2=V_1-I*(r_e+(%i*x_e))
22 v=sqrt(V_2*conj(V_2))
23 disp(v, '(a) terminal voltage on load(in volt)=')
24 V=v*n
25 disp(V, '(b) voltage on load at hgh voltage terminals
    (in volt)=')
26 P_o=v*real(I)
27 P_i=V_1*real(I_1)
28 eff=(P_o/P_i)*100
29 disp(eff, '(c) efficiency of transformer is (in %)=')

```

Scilab code Exa 1.6 Find impedance and percentage resistance and reactance

1 //Caption : Find (a) impedance (b) % resistance and

```

        reactance
2 //Exa:1.6
3 clc;
4 clear;
5 close;
6 P_s=500000 //Power supplied (in VA)
7 V_1=2200 //Voltage on primary side (in volt)
8 V_2=500 //Voltage on secondary side (in volt)
9 f=50 //frequency (in hertz)
10 r=0.01 //Resistance of transformer (in ohms)
11 z=0.1 //impedance of transformer (in %)
12 I=P_s/V_2
13 Z=z*V_2/I
14 disp(Z, '(a) Impedance (in ohms)=')
15 R=(I*r/V_2)*100
16 disp(R, '(b) Resistance (in %)=')
17 x=sqrt(Z^2-r^2)
18 X=(x*I/V_2)*100
19 disp(X, 'Reactance (in %)=')

```

Chapter 2

Single phase transformer Operation and Testings

Scilab code Exa 2.1 Find all day efficiency and commercial efficiency on full load and efficiency on half load

```
1 //Caption:Find (a)all day efficiency (b)commercial  
efficiency on full load (c)efficiency on half  
load  
2 //Exa:2_1  
3 clc;  
4 clear;  
5 close;  
6 P_s=50 //Power supplied (in kVA)  
7 V_1=440 //Primary side voltage (in volt)  
8 V_2=220 //Secondary side voltage (in volt)  
9 t_1=6 //Full load (in hours)  
10 t_2=2 //50% load (in hours)  
11 Cu_1=2 //Copper loss on full load (in KW)  
12 Fe=1 //Iron losses (in KW)  
13 E_1=P_s*t_1 //Energy used on full load (in watt-hours)  
14 E_2=0.5*P_s*t_2 //Energy used on half load (in watt-  
hours)  
15 Cu_2=Cu_1*0.25 //Copper losses on half load (in watts)
```

```

16 E=(Cu_1*t_1)+(Cu_2*t_2)+(Fe*24) //Energy lost on
    losses (in watt-hours)
17 eff_1=(E_1+E_2)/(E_1+E_2+E)*100
18 disp(eff_1 , '(a) All day efficiency (in%)=')
19 eff_2=(E_2)/(E_2+Cu_1+Fe)*100
20 disp(eff_2 , '(b) commercial efficiency on full load (
    in%)=')
21 eff_3=(0.5*E_2)/(0.5*E_2+Cu_2+Fe)*100
22 disp(eff_3 , '(c) efficiency on half load (in%)=')

```

Scilab code Exa 2.2 Find Efficiency of transformer at half load at and At what load will the efficiency be maximum and maximum

```

1 //Caption :Find (a) Efficiency of transformer at half
    load at 0.8 power factor lagging (b)At what load
    will the efficiency be maximum and maximum
    efficiency ?
2 //Exa:2.2
3 clc;
4 clear;
5 close;
6 P_s=25000 //Power supplied (in VA)
7 V_1=3300 //Voltage on primary side (in volts)
8 V_2=230 //Voltage on secondary side (in volts)
9 f=50 //frequency (in hertz)
10 P_i=300 //Iron loss (in watt)
11 P_c=400 //Copper loss (in watt)
12 pf=0.8 //Power factor
13 Cu=P_c*(0.5^2) //Copper loss on half load
14 P_o=P_s*0.5*pf //Output of transformer on half load
15 eff=(P_o)/(P_o+Cu+P_i)*100

```

```

16 disp(eff, '(a) Efficiency of transformer at half load(
    in %)=')
17 x=sqrt(P_i/P_c)*20000
18 disp(x, '(b) Load for maximum efficiency (in watt)=')
19 eff_max=(x)/(x+P_i+P_i)*100
20 disp(eff_max, 'Maximum efficiency (in%)=')

```

Scilab code Exa 2.3 Find Percentage resistance and Regulation for power factors unity lagging and leading

```

1 //Caption : Find (a)% resistance (b) Regulation for
    power factors – unity , 0.8 lagging and 0.8 leading
2 //Exa:2_3
3 clc;
4 clear;
5 close;
6 L_o=1//Ohmic loss(%)
7 X=6//Reactance(in %)
8 pf_1=0.8//lagging power factor
9 pf_2=0.8//leading power factor
10 R=L_o
11 disp(R, '(a)% resistance (in %)=')
12 Re_1=L_o
13 disp(Re_1, '(b) Regulation at unity power factor (in%)=')
14 theta=(acosd(pf_1))
15 a=sind(theta)
16 Re_2=L_o*pf_1+X*a
17 disp(Re_2, 'Regulation at 0.8 lagging power factor (
    in%)=')
18 Re_3=L_o*pf_2-X*a

```

```
19 disp(Re_3, 'Regulation at leading power factor (in%)=')


---


```

Scilab code Exa 2.4 Find Regulation on full load and at power factor lagging

```
1 //Caption:Find Regulation on full load at 0.8 power
   factor lagging
2 //Exa:2_4
3 clc;
4 clear;
5 close;
6 P_s=500000//Power supplied (in VA)
7 V_1=2200//Voltage on primary side (in volt)
8 V_2=500//Voltage on secondary side (in volt)
9 f=50//frequency (in hertz)
10 Eff=97//Efficiency of transformer (in %)
11 Eff_m=75//Maximum efficiency (in %) of its full load
12 Z_1=10//Impedance (in %)
13 pf_1=1//Power factor for maximum efficiency
14 pf_2=0.8//Power factor lagging
15 I_f1=P_s/V_2
16 I=(Eff_m*I_f1)/100
17 Losses=(100-Eff)/100
18 Cu=Losses/2
19 Fe=Losses/2
20 C=(Cu*P_s*Eff_m)/100
21 R=C/(I^2)
22 V=(Z_1*V_2)/100
23 Z=V/I_f1
24 X=sqrt(Z^2-R^2)
```

```

25 theta=(acosd(pf_2))
26 Re=(I_f1*R*pf_2)+(I_f1*X*sind(theta))
27 disp(Re , 'Regulation on full load at 0.8 power factor
    lagging (in volt)=')
28 Reg=(Re/V_2)*100
29 disp(Reg , 'Percentage Regulation (in%)=')

```

Scilab code Exa 2.5 Find Ro and Xo and Resistance reffered to lv side and Reactance reffered to lv side

```

1 //Caption: Find : (a) R_o (b)X_o (c) Resistance
    reffered to l.v side (d)Reactance reffered to l.v
    side
2 //Exa:2.5
3 clc;
4 clear;
5 close;
6 P_s=5000//Power Supplied(in VA)
7 V_1=220//Primary side voltage(in volt)
8 V_2=440//Secondary side voltage(in volt)
9 f=50//frequency(in hertz)
10 I_o=0.75//Open circuit test current(in A)
11 P_o=75//Open circuit test power(in watt)
12 V_s=16//Short circuit test voltage(in volt)
13 P_c=80//Short circuit test power(in watt)
14 pf=(P_o)/(V_1*I_o)
15 a=sind(acosd(pf))
16 R_o=(V_1)/(I_o*pf)
17 disp(R_o , '(a)R_o(in ohms)=')
18 X_o=(V_1)/(I_o*a)
19 disp(X_o , '(b)X_o(in ohms)=')

```

```

20 I_1=P_s/V_2
21 Z=V_s/I_1
22 R=(P_c)/(I_1^2)
23 X=sqrt(Z^2-R^2)
24 n=V_2/V_1
25 r=(R)/(n^2)
26 disp(r,'(c) resistance referred to low voltage side(
    in ohms)=')
27 x=(X)/(n^2)
28 disp(x,'(d) reactance referred to low voltage side(in
    ohms)=')

```

Scilab code Exa 2.6 Find voltage for hv voltage side on full load and at power factor lagging when secondary terminal voltage is 240 volts

```

1 //Caption:Find voltage for h.v voltage side on full
load at 0.8 power factor lagging when secondary
terminal voltage is 240 volts
2 //Exa:2.6
3 clc;
4 clear;
5 close;
6 P_s=100000//Supplied power(in VA)
7 V_1=6600//Primary side voltage(in volt)
8 V_2=240//Secondary side voltage(in volt)
9 f=50//frequency(in hertz)
10 I_sh=5//short circuit test current(in A)
11 P_sh=109//short circuit test power(in watt)
12 V_sh=50//short circuit test voltage(in volt)
13 pf=0.8//Power factor
14 Z=V_sh/I_sh

```

```

15 R=P_sh/(I_sh^2)
16 X=sqrt(Z^2-R^2)
17 I_l=P_s/V_1
18 Re=(I_l*R*pf)+(I_l*X*sind(acosd(pf)))
19 V_r=Re+V_1
20 disp(V_r, 'Voltage for high voltage side on full load
           at 0.8 power factor lagging when secondary
           terminal voltage is 240 volts (in volt)=')

```

Scilab code Exa 2.7 Calculate ZXR referred to hv side and Regulation on full load at power factor lagging and Terminal voltage on lv side on full load at pf lagging and Efficiency of transformer when current 250A pf lagging is load connected to lv side and voltage at hv side

```

1 //Caption: Calculate (a)Z,X,R referred to h.v side (
   b)Regulation on full load at 0.8 power factor
   lagging (c)Terminal voltage on l.v side on full
   load at pf=0.8 lagging (d)Efficiency of
   transformer when current=250A, pf=0.8 lagging is
   load connected to l.v side and voltage at h.v
   side is 11000 volts
2 //Exa:2.7
3 clc;
4 clear;
5 close;
6 P_s=220000 //Supplied power (in VA)
7 V_1=11000 //Primary side voltage(in volt)
8 V_2=440 //Secondary side voltage(in volt)
9 P_i=2200 //Iron losses(in watt)
10 V=500 //voltage applied to high voltage side for open
       circuit test(in volt)

```

```

11 P=2000 //Wattmeter reading for open circuit test (in
      watt)
12 pf=0.8 //Power factor
13 I=250 //Load current (in A)
14 I_f1=P_s/V_1
15 r=P/(I_f1^2)
16 z=V/I_f1
17 x=sqrt(z^2-r^2)
18 disp(r,x,z,'(a)Z,X,R(in ohms)=')
19 Re=(I_f1*r*pf)+(I_f1*x*sindacosd(pf)))
20 disp(Re,'(b) Regulation on full load on high voltage
      side(in volts)=')
21 Re_1=(Re*V_2)/V_1
22 disp(Re_1,'Regulation on full load on low volrage
      side(in volts)=')
23 V_t=V_2-Re_1
24 disp(V_t,'(c) Terminal voltage on low voltage side on
      full load (in volts)=')
25 I_c=I*V_2/(V_1)
26 W_c=P/(2^2)
27 Eff=(V_1*I_c*pf)/((V_1*I_c*pf)+(P_i)+(W_c))*100
28 disp(Eff,'(d) Efficiency of transformer (in%)=')

```

Scilab code Exa 2.8 Determine Efficiency and Regulation at loading conditions

```

1 //Caption: Determine (a) Efficiency (b) Regulation at
      loading conditions
2 //Exa:2.8
3 clc;
4 clear;

```

```

5 close;
6 P_s=10000 // Supplied power (in VA)
7 V_1=440 // Primary voltage (in volts)
8 V_2=240 // Secondary voltage (in volts)
9 f=50 // frequency (in hertz)
10 I_1=35 // Load current (in A)
11 V_l=234 // Load voltage (in volts)
12 W=8500 // Wattmeter reading (in watts) connected on 440
    V side
13 P_o=I_1*V_l
14 P_i=W
15 Eff=P_o/(P_i)*100
16 disp(Eff, '(a) Efficiency (in %)=')
17 V_d=V_2-V_1
18 Re=V_d/(V_2)*100
19 disp(Re, '(b) Regulation (in%)=')

```

Scilab code Exa 2.9 Find how they will share 750KVA load at power factor lagging

```

1 //Caption: Find how they will share 750KVA load at
    0.8 power factor lagging
2 //Exa:2.9
3 clc;
4 clear;
5 close;
6 P_s1=500000 // Supplied power (in VA) to first
    transformer
7 r_1=0.01 // Per unit resistance of first transformer
8 x_1=0.05 // Per unit reactance of first transformer
9 P_s2=250000 // Supplied power (in VA) to second

```

```

    transformer
10 r_2=0.015 //Per unit resistance of second transformer
11 x_2=0.04 //Per unit reactance of second transformer
12 P_l=750000 //Load(in VA)
13 pf=0.8 //Powerfactor lagging
14 V_2=400 //Secondary voltage of each transformer(in
    volts)
15 Z_1=r_1+(%i*x_1)
16 Z_2=((2*r_2)+(2*%i*x_2))
17 Z=Z_1+Z_2
18 S=P_l*(pf-(%i*(sind(acosd(pf)))))
19 S_1=(S*Z_2)/(Z)
20 s_1=sqrt(((real(S_1))^2)+((imag(S_1))^2))
21 disp(s_1,'Load on first transformer(in VA)=')
22 S_2=(S*Z_1)/(Z)
23 s_2=sqrt(((real(S_2))^2)+((imag(S_2))^2))
24 disp(s_2,'Load on second transformer(inVA)=')

```

Chapter 3

Three Phase Transformer Operation And Testing

Scilab code Exa 3.1 Find Secondary line voltage Line Current and output power for deltadelta and starstar and deltastar and stardelta

```
1 //Caption: Find Secondary line voltage ,Line Current ,  
    and output power for (a)delta/delta (b)star/star  
    (c)delta/star (d)star/delta  
2 //Exa:3.1  
3 clc;  
4 clear;  
5 close;  
6 V=6600 //Supplied voltage(in volts)  
7 I=20 //Supplied current(in A)  
8 n=15 //Number of turns per phase  
9 V_la=V/n  
10 I_la=n*I  
11 disp(V_la,I_la,'(a)(in A),(in volts)=')  
12 V_lb=V/n  
13 I_lb=I*n  
14 disp(V_lb,I_lb,'(b)(in A),(in volts)=')  
15 V_lc=(V*(3^0.5))/(n)  
16 I_lc=(n*I)/(3^0.5)
```

```

17 disp(V_1c,I_1c,'(c)(in A),(in volts)=')
18 V_1d=V/(n*(3^0.5))
19 I_1d=(3^0.5)*I*n
20 disp(V_1d,I_1d,'(d)(in A),(in volts)=')
21 P=(3^0.5)*V*I/1000
22 disp(P,'(d)Output Power (in KVA)=')

```

Scilab code Exa 3.2 Calculate Phase and Line currents in High voltage and Low voltage windings of transformer

```

1 //Caption: Calculate Phase and Line currents in (a)
           High voltage (b)Low voltage windings of
           transformer
2 //Exa:3.2
3 clc;
4 clear;
5 close;
6 P=50000//Power of induction motor(in watts)
7 V=440//Voltage of induction motor(in volts)
8 eff=90//Efficiency (in%)
9 pf=0.85//power factor
10 V_1=11000//Primary side voltage of transformer(in
            volts)
11 V_2=440//Secondary side voltage of transformer(in
            volts)
12 I_f1=P/((3^0.5)*V*pf*(eff/100))
13 v=V/(3^0.5)
14 n=V_1/v
15 I_ph=I_f1/(n)
16 I_l=(3^0.5)*I_ph
17 disp(I_ph,I_l,'(a) High Voltage side line and phase

```

```
    currents (inA)=')
18 disp(I_f1,I_f1,'(b)Low voltage side phase and line
    currents (inA)=')
```

Scilab code Exa 3.3 Find possible voltage ratio and output for connections BC11500V and AC2300V and BC2300V and AC11500V

```
1 //Caption: Find possible voltage ratio and output
    for connections (a)BC=11500V,AC=2300V (b)BC=2300V
        ,AC=11500V
2 //Exa:3.3
3 clc;
4 clear;
5 close;
6 V_1=11500//Voltage on primary side(in volts)
7 V_2=2300//Voltage on secondary side(in volts)
8 P_o=100000//Rated output(in VA)
9 V=V_1+V_2
10 v=V/V_1
11 I_1=P_o/V_1
12 I_2=P_o/V_2
13 I=I_1+I_2
14 W_o=(V_1*I)/1000
15 Cu=1-(V_1/V)//(a) Ratio of weight of copper
16 disp(W_o,v,'(a)Voltage ratio and output(in KVA)=')
17 w_o=(V_2*I)/(1000)
18 cu=1-(V_2/v)//(b) Ratio of weight of copper
19 disp(w_o,v,'(b)Voltage ratio and output(in KVA)=')
```

Chapter 4

Elements of Transformer Design

Scilab code Exa 4.1 Find Voltage per turn and area of core and area of conductor for lv and area of conductor for hv and Number of turns in lv and Number of turns in hv and Window area and Yoke and approx frame size and Copper used in windings

```
1 //Caption: Find (a)Voltage per turn (b)Cross  
    sectional area of core (c)Cross sectional area of  
    conductor for l.v (d)Cross sectional area of  
    conductor for h.v (e)Number of turns in l.v (f)  
    Number of turns in h.v (g)Window area (h)Yoke and  
    approx. frame size (i)Copper used in windings  
2 //Exa:4.1  
3 clc;  
4 clear;  
5 close;  
6 P=5000 //Power supplied to transformer(in VA)  
7 f=50 //frequency(in Hertz)  
8 V_1=415 //Primary side voltage(in volts)  
9 V_2=240 //Secondary side voltage(in volts)  
10 k=0.75  
11 B=1.6 //Maximum flux density (in weber/m^2)
```

```

12 i_d=2 // Current density (in A/mm^2)
13 k_w=0.3
14 E=k*sqrt(P/1000)
15 disp(E, '(a) Voltage per turn (in volts)=')
16 A_1=(E*(10^6))/(4.44*B*f)
17 disp(A_1, '(b) Cross sectional area of core (in mm^2)='
    )
18 i_2=P/V_2
19 A_2=i_2/i_d
20 disp(A_2, '(c) Cross sectional area of conductor for
    low voltage side (in mm^2)=')
21 i_1=P/V_1
22 A_1=i_1/i_d
23 disp(A_1, '(d) Cross sectional area of conductor for
    high voltage side (in mm^2)=')
24 n_2=V_2/E
25 disp(n_2, '(e) Number of turns in low voltage winding='
    )
26 n_1=V_1/E
27 disp(n_1, '(f) Number of turns in high voltage winding
    =')
28 A_w=(P*(10^(9))/1000)/(2.22*A_1*k_w*i_d*B)
29 disp(A_w, '(g) Window area (in mm^2)=')
30 cu=(A_1*n_1)+(A_2*n_2)
31 disp(cu, '(i) Copper used in windings (in mm^2)=')

```

Scilab code Exa 4.2 Find Voltage per turn and Area of core and Area of conductor for hv and Number of turns per phase in hv winding and Area of conductor in lv winding and Number of turns in lv winding and Window area and Yoke and frame size and copper used

```

1 //Caption:Find (a)Voltage per turn (b)Cross
    sectional area of core (c)Cross sectional area of
    conductor for h.v (d)Number of turns per phase
    in h.v winding (e)Cross sectional area of
    conductor in l.v winding (f)Number of turns in l.
    v winding (g)Window area (h)Yoke and approx frame
    size ,and (i)Copper used in window area
2 //Exa:4.2
3 clc;
4 clear;
5 close;
6 P=100000 //Power supplied to transformer(in VA)
7 f=50 //Frequency(in hertz)
8 V_1=11000 //Primary side voltage(in volts)
9 V_2=433 //Secondary side voltage(in volts)
10 k=0.45
11 B=1.65 //Maximum flux density(in tesla)
12 k_w=0.28
13 i_d=2.5 //Current density(in A/mm^2)
14 E=k*sqrt(P/1000)
15 disp(E, '(a)Voltage per turn(in volts)=')
16 A_1=E*(10^6)/(4.44*f*B)
17 disp(A_1, '(b)Cross sectional area of core(in mm^2)='
    )
18 I_1=P/(3*V_1)
19 a_1=I_1/i_d
20 disp(a_1, '(c)Cross sectional area of conductor in h.
    v winding(in mm^2)=')
21 n_1=V_1/E
22 disp(n_1, '(d)Number of turns per phase in h.v
    winding(in mm^2)=')
23 I_2=P/((3^0.5)*V_2)
24 a_2=I_2/i_d
25 disp(a_2, '(e)Cross sectional area of conductor in l.
    v winding(in mm^2)=')
26 v=V_2/(3^0.5)
27 n_2=v/E
28 disp(n_2, '(f)Number of turns in l.v winding=')

```

```
29 A_w=(P*(10^6))/(3.33*f*A_1*k_w*i_d*B)
30 disp(A_w, '(g) Window Area (in mm^2)=')
31 Cu=2*((a_1*n_1)+(a_2*n_2))
32 disp(Cu, 'Copper used in window area (in mm^2)=')
```

Chapter 7

Principle And Construction of DC Machines

Scilab code Exa 7.3 Find effect of change in connection on voltage and current and output

```
1 //Caption:Find effect of change in connection on  
    voltage ,current and output  
2 //Exa:7.3  
3 clc;  
4 clear;  
5 close;  
6 P=50000//Power of generator(in watt)  
7 V_b1=230//Voltage of generator(in volts)  
8 p=4//Number of poles  
9 a=4//Number of parallel paths for lap winding  
10 b=2//Number of parallel paths for wave winding  
11 C=268//Number of conductors with LAP winding  
12 t=2//Two turns coils are used  
13 c=t*2//Conductors per slot  
14 n=C/c  
15 I_1=P/(V_b1)  
16 V_b2=V_b1*b  
17 I_2=P/(V_b2)
```

```

18 disp(V_b1,I_1,'Current (in A) and voltage (in volts)
      for LAP winding=')
19 disp(V_b2,I_2,'Current (in A) and voltage (in volts)
      for WAVE winding=')
20 disp(P,'Output is same for both connections (in watts
      )=')

```

Scilab code Exa 7.6 Select a two circuit armature winding for a dc machine

```

1 //Caption: Select a two circuit armature winding for
      a d.c machine
2 //Exa:7.6
3 clc;
4 clear;
5 close;
6 p=4 //Number of poles
7 n=1000 //Speed of d.c. machine (in r.p.m)
8 V=400 //Voltage of d.cmachine (in volts)
9 B=0.04 //Flux per pole (in weber)
10 s_1=41 //Slot 1
11 s_2=45 //Slot 2
12 s_3=51 //Slot 3
13 a=2 //Number of parallel paths
14 Z=(V*60*a)/(B*n*p)
15 Z_c=Z/a
16 Y=(s_3+1)/(p/2)
17 t=3 //turns per coil
18 c=t*a
19 z=s_3*c
20 disp(z,c,t,s_3,'slots ,turn coils ,coils sides per

```

slot and total number of conductors=')

Scilab code Exa 7.7 Find Emf generated at 750rpm for lap wound And emf generated at 600rpm for wave wound And Speed to be driven for 400V for same flux per pole

```
1 //Caption: Find (a)e.m.f generated at 750r.p.m for
  lap wound (b)e.m.f generated at 600r.p.m for wave
  wound (c)Speed to be driven for 400V for same
  flux per pole
2 //Exa:7.7
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 B=0.04//Flux per pole(in weber)
8 c=740//Number of conductors for lap connection
9 n_1=750//Speed of machine(in r.p.m)
10 n_2=600//Speed of machine(in r.p.m)
11 V=400//Voltage of machine(in volts)
12 a=4//Number of parallel paths for lap winding
13 b=2//Number of parallel paths for wave winding
14 E=(B*c*n_1*p)/(60*a)
15 disp(E, '(a)E.M.F generated at 750r.p.m for lap wound
  (in volts)=')
16 E_1=(B*c*n_2*p)/(60*b)
17 disp(E_1, '(b)E.M.F generated at 600r.p.m for
  wavewound (in volts)=')
18 n=(V*60*b)/(B*c*p)
19 disp(n, '(c)Speed of machine (in r.p.m)=')
```

Scilab code Exa 7.8 Calculate Total armature current And Current per armature path And Generated emf

```
1 //Caption: Calculate (a)Total armature current (b)
             Current per armature path (c)Generated e.m.f
2 //Exa:7.8
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 P=4000//Power of generator(in watts)
8 V=230//Voltage of generator(in volts)
9 r_f=115//Field resistance(in ohms)
10 r_a=0.1//Armature resistance(in ohms)
11 a=p//number of parallel paths
12 i_f=V/r_f
13 i_l=P/V
14 I_a=i_l+i_f
15 disp(I_a,'(a) Armature current (in A)=')
16 i=I_a/p
17 disp(i,'(b) Current per armature path (in A)=')
18 E=V+(I_a*r_a)
19 disp(E,'(c)E.M.F generated (in volts)=')
```

Scilab code Exa 7.9 Find the speed at which it will run as a motor

```
1 //Caption:Find the speed at which it will run as a
   motor
2 //Exa:7.9
3 clc;
4 clear;
5 close;
6 P_g=110000//Power of generator(in watts)
7 n=400//Speed of generator(in r.p.m)
8 V=220//Voltage of busbars(in volts)
9 P_m=10900//Power of motor(in watt)
10 r_a=0.025//Armature resistance(in ohms)
11 r_f=55//Field resistance(in ohms)
12 v_b=1//Voltage drop at each brush(in volt)
13 i_l=P_g/V
14 i_f=V/r_f
15 I_a=i_l+i_f
16 V_a=I_a*r_a
17 E=V+V_a+(2*v_b)
18 I_1=P_m/V
19 i_a=I_1-i_f
20 v_a=i_a*r_a
21 E_b=V-(i_a*r_a)-(2*v_b)
22 N_m=(n*E_b)/E
23 disp(N_m,'Speed at which generator will run as motor
   is (in r.p.m)=')
```

Scilab code Exa 7.10 Calculate the speed of the motor when it is loaded and takes 60A from the mains

```

1 //Caption: Calculate the speed of the motor when it
   is loaded and takes 60A from the mains
2 //Exa:7.10
3 clc;
4 clear;
5 close;
6 V=230//Voltage of motor(in volts)
7 n=800//Speed of motor(in r.p.m)
8 i=5//Current taken by motor(in A)
9 r_a=0.25//Armature resistance(in ohms)
10 r_f=230//field resistance(in ohms)
11 i_l=60//Load current(in A)
12 i_f=V/r_f
13 i_a=i-i_f
14 E_b1=V-(i_a*r_a)
15 i_al=i_l-i_f
16 E_b2=V-(i_al*r_a)
17 N=(n*E_b2)/E_b1
18 disp(N, 'Required speed of motor(in r.p.m) is=')

```

Scilab code Exa 7.11 Calculate Power and torque developed

```

1 //Caption: Calculate Power and torque developed
2 //Exa:7.11
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 d=20//Diameter of armature(in cm)
8 l=25//Core length(in cm)
9 c=300//Number of conductors

```

```

10 i_a=50 //Armature current (in A)
11 B=0.3 //Average flux density (in weber/m^2)
12 n=1000 //Speedofmotor (in r.p.m)
13 T=(B*(1/100)*(i_a/p)*c*(d/100)*(1/2))
14 s=(2*pi*n)/(60)
15 P=(T*s)/1000
16 disp(T,P,'Power (in KW) and Torque (in Nm) developed
is=')

```

Scilab code Exa 7.12 Determine per pole Number of cross magnetising ampereturns and Demagnetising ampereturns

```

1 //Caption: Determine per pole (a) Number of cross
    magnetising ampereturns , and (b) Demagnetising
    ampereturns
2 //Exa:7.12
3 clc;
4 clear;
5 close;
6 I=100 //Current (in A)
7 c=500 //Armature conductors
8 p=6 //Poles
9 t=10 //Angle of lead (in degree)
10 a=2 //Wave wound
11 e=(10*p)/2
12 F_d=(c*I*2*e)/(2*a*p*180)
13 disp(F_d,'(a) Number of cross magnetising ampereturns
    =')
14 F_c=(c*I)*(1-((2*e)/180))/(2*a*p)
15 disp(F_c,'(b) Demagnetising ampereturns=')

```

Scilab code Exa 7.13 Find the time of Commutation

```
1 //Caption :Find the time of Commutation
2 //Exa:7.13
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 n=600//Speed of generator(in r.p.m)
8 d=0.4//Diameter of commutator(in m)
9 c=243//Number of commutator segments
10 c_s=3//Coil sides per layer
11 w=12.5//Width of brush(in mm)
12 W=0.6//Width of mica between commutator segments
13 W_c=(%pi*d*1000)/(c)
14 D=w-W+(2*W_c)
15 V_c=(%pi*d*n)/60
16 T=D/V_c*(10^(-3))
17 disp(T, 'Time of commutation (in sec)=')
```

Scilab code Exa 7.14 Find average reactance voltage produce due to commutation

```

1 //Caption: Find average reactance voltage produce
    due to commutation
2 //Exa:7.14
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 I=300//Current delivered by generator on full load(
    in A)
8 L=0.02*(10^(-3))//Inductance of each coil(in mH)
9 a=2//Wavw wound
10 i=I/2//Current in conductors in each path(in A)
11 T_c=0.00174//Time of commutation(in sec)
12 E_r=(2*L*i)/T_c
13 disp(E_r, 'Average reactance voltage(in volts)=')

```

Scilab code Exa 7.15 Calculate the number of turns needed on each commutating pole

```

1 //Caption: Calculate the number of turns needed on
    each commutating pole
2 //Exa:7.15
3 clc;
4 clear;
5 close;
6 p=4//Number of poles
7 P=125000//Power delivered by generator(in watts)
8 V=230//Voltage of generator(in volts)
9 z=240//Armature conductors
10 B=0.3//Flux density under the interpolar gap(in
    weber/m^2)

```

```
11 g=0.01 // Interpolar airgap (in m)
12 a=p//LAP connection
13 I_a=P/V
14 F_a=(z*I_a)/(2*a*p)
15 A=(B*g)/(4*pi*(10^(-7)))
16 A_t=A+F_a
17 T=A_t/I_a
18 disp(T, 'The number of turns on each commutating pole
=')
```

Chapter 8

DC Machines Operations and Testing

Scilab code Exa 8.2 Find the current and voltage required

```
1 //Caption: Find the (a)current (b)voltage required
2 //Exa:8.2
3 clc;
4 clear;
5 close;
6 r=1//Resistance of series motor(in ohms)
7 V=230//Voltage of series motor(in volts)
8 n_1=300//Speed of motor(in r.p.m)
9 i_1=15//Current taken by motor(in A)
10 n_2=375//Speed of motor(in r.p.m)
11 i_2=sqrt(((i_1^2)*(n_2^2))/(n_1^2))
12 disp(i_2,'(a) Current(in A)=')
13 V_2=((V-(i_1*r))*(i_2*n_2))/(i_1*n_1)+(i_2*r)
14 disp(V_2,'(b) Voltage(in volts)=')
```

Scilab code Exa 8.3 Find the resistance required

```
1 //Caption: Find the resistance required
2 //Exa:8.3
3 clc;
4 clear;
5 close;
6 I_1=40 //Current taken by series motor (in A)
7 V=500 //Supplied voltage (in volts)
8 n_1=100 //Initial speed (in%)
9 n_2=80 //final speed (in%)
10 I_2=sqrt(((I_1^2)*(n_2^2))/(n_1^2))
11 a=(I_1*(n_1/100))/(I_2*(n_2/100))
12 R=((a*V)-V)/(a*I_2)
13 disp(R, 'Resistance required (in ohms) is =')
```

Scilab code Exa 8.5 Find Speed at full load torque And Speed at double full load torque And Stalling torque

```
1 //Caption: Find (a)Speed at full load torque (b)
    Speed at double full load torque (c)Stalling
    torque
2 //Exa:8.5
3 clc;
```

```

4 clear;
5 close;
6 V=250 //Voltage of motor(in volts)
7 R_a=0.5 //Armature resistance(in ohms)
8 n=400 //Speed of motor at full load(in r.p.m)
9 i=30 //Current taken by motor(in A)
10 R=1 //Series resistance with armature(in ohms)
11 E_b1=V-(i*R_a)
12 E_b2=V-((R_a+R)*i)
13 N=n*(E_b2/E_b1)
14 disp(N, '(a) Speed at full load torque(in r.p.m)=')
15 I=2*i
16 E_b=V-(I*(R+R_a))
17 N_1=n*(E_b/E_b1)
18 disp(N_1, '(b) Speed at double full load torque(in r.p.m)=')
19 I_ft=V/(R+R_a)
20 T_stalling=I_ft/i
21 disp(T_stalling, '(c) Stalling torque=times the full load torque')

```

Scilab code Exa 8.6 Find Input to generator from prime mover on full load and Efficiency on full load and Load current at which generator efficiency is maximum

```

1 //Caption: Find (a)Input to generator from prime
    mover on full load (b)Efficiency on full load (c)
    Load current at which generator efficiency is
    maximum
2 //Exa:8.6
3 clc;

```

```

4 clear;
5 close;
6 V=230 //Voltage of generator (in volts)
7 I=150 //Full load current (in A)
8 R_a=0.1 //Armature resistance (in ohms)
9 R_f=230 //Field resistance (in ohms)
10 P_s=1500 //Stray losses (in watt)
11 I_f=V/R_f
12 I_a=I_f+I
13 W_ac=(I_a^2)*R_a
14 W_fc=(I_f^2)*R_f
15 P_c=W_fc+P_s
16 L_t=W_ac+P_c
17 P_o=V*I
18 P_i=P_o+L_t
19 disp(P_i, '(a) Input to generator from prime mover on
      full load (in watt)=')
20 Eff=(P_o/P_i)*100
21 disp(Eff, '(b) Efficiency on full load (in %)=')
22 I_l=sqrt(P_c/R_a)
23 disp(I_l, '(c) Load current at which generator
      efficiency is maximum (in A)=')

```

Scilab code Exa 8.7 Calculate Efficiency on full load and Efficiency on 40A input and Efficiency on 25A input and Full load speed regulation

```

1 //Caption: Calculate (a) Efficiency on full load (b)
      Efficiency on 40A input (c) Efficiency on 25A
      input (d) Full load speed regulation
2 //Exa:8.7
3 clc;

```

```

4 clear;
5 close;
6 V=230 //Voltage of motor(in volts)
7 i_l=50 //Full load current(in A)
8 r_a=0.25 //Armature resistance(in ohms)
9 r_f=230 //Field resistance(in ohms)
10 i_o=3 //No load current(in A)
11 i_1=40 //Input current(in A)
12 i_2=25 //Input current(in A)
13 P_c=V*i_o
14 P_i1=V*i_l
15 i_f=V/r_f
16 i_a1=i_l-i_f
17 L_f1=((i_a1^2)*r_a)+P_c
18 Eff_1=((P_i1-L_f1)/P_i1)*100
19 disp(Eff_1, '(a) Efficiency on full load (in%)=')
20 P_i2=V*i_1
21 i_a2=i_1-i_f
22 L=((i_a2^2)*r_a)+P_c
23 Eff_2=((P_i2-L)/P_i2)*100
24 disp(Eff_2, '(b) Efficiency on 40A input (in%)=')
25 P_i3=V*i_2
26 i_a3=i_2-i_f
27 L_1=((i_a3^2)*r_a)+P_c
28 Eff_3=((P_i3-L_1)/P_i3)*100
29 disp(Eff_3, '(c) Efficiency on 25A input (in%)=')
30 I_ao=i_o-i_f
31 E_bo=V-(I_ao*r_a)
32 E_bl=V-(r_a*i_a1)
33 Re=((E_bo-E_bl)/E_bo)*100
34 disp(Re, '(d) Full load speed regulation (in%)=')

```

Scilab code Exa 8.10 Calculate efficiency of motor and generator

```
1 //Caption: Calculate efficiency of (a) motor and (b)
   generator
2 //Exa:8.10
3 clc;
4 clear;
5 close;
6 V=230//Line voltage for both shunt machines(in volts
   )
7 I=70//Line current excluding field currents of both
   machines(in A)
8 i_a=400//Armature current(in A)
9 i_f1=4//Field current of first machine(in A)
10 i_f2=3//Field current of second machine(in A)
11 r_a=0.03//Resistance of armature of each machine(in
   ohms)
12 P_acm=(i_a^2)*r_a
13 P_i=V*I
14 I_g=i_a-I
15 P_acg=(I_g^2)*r_a
16 P_f=(P_i-P_acm-P_acg)/2
17 P_m=(V*i_a)+(V*i_f2)
18 P_fc=V*i_f2
19 L_t=P_fc+P_acm+P_f
20 P_o=P_m-L_t
21 n_m=(P_o/P_m)*100
22 disp(n_m, '(a) Efficiency of motor (in%)=')
23 P_og=V*I_g
24 P_fcu=V*i_f1
25 L_t1=P_f+P_fcu+P_acg
26 P_ig=P_og+L_t1
27 n_g=(P_og/P_ig)*100
28 disp(n_g, '(b) Efficiency of generator (in%)=')
```

Scilab code Exa 8.11 Calculate efficiency of motor

```
1 //Caption: Calculate efficiency of motor
2 //Exa:8.11
3 clc;
4 clear;
5 close;
6 W=25 //Effective load on break drum(in kgf)
7 d=50 //Diameter of drum(in cm)
8 n=750 //Speed of the motor(in r.p.m)
9 I=25 //Current taken by motor(in A)
10 V=230 //Voltage of motor(in volts)
11 P_o=(2*pi*n*W*9.81*(d/2))/(60*100)
12 P_i=V*I
13 Eff=(P_o/P_i)*100
14 disp(Eff, 'Efficiency of motor(in %)=')
```

Scilab code Exa 8.12 Find efficiency of motor

```
1 //Caption:Find efficiency of motor
2 //Exa:8.12
3 clc;
4 clear;
5 close;
```

```

6 V=500 //Voltage of shunt motor(in volts)
7 I=10 //Current taken by motor on no load(inA)
8 I_f=3 //Field Current(inA)
9 r_a=0.1 //Armature resistance(in ohms)
10 P_i=100000 //Input power to motor(in watt)
11 P_nl=V*I
12 I_ao=I-I_f
13 P_acn=(I_ao^2)*r_a
14 P_fcn=I_f*V
15 P_c=(P_nl)-P_acn-P_fcn
16 I_l=P_i/V
17 I_al=I_l-I_f
18 P_acl=(I_al^2)*r_a
19 P_fcl=V*I_f
20 L_t=P_acl+P_fcl+P_c
21 Eff=((P_i-L_t)/P_i)*100
22 disp(Eff,'Efficiency of motor(in%) is=')

```

Chapter 9

Elements of DC Machine Design

Scilab code Exa 9.1 Find the dimensions of D and L

```
1 //Caption :Find the dimensions of D and L
2 //Exa:9.1
3 clc;
4 clear;
5 close;
6 P=15000 //Power of shunt motor(in watt)
7 V=440 //Supplied voltage to motor(in volts)
8 n=1500 //Speed of motor(in r.p.m)
9 e=88 //Efficiency (in %)
10 B=0.65 //Average flux density (in webers/m^2)
11 q=30000 //Specific electric loading(ampere conductors
           /m)
12 p=4 //Number of poles
13 R_f=220 //Field resistance (in ohms)
14 P_i=P/(e/100)
15 I=P_i/V
16 I_f=V/R_f
17 D=170 //Choosing the diameter (in mm)
18 L=(P_i)/((%pi^2)*((D^2)*(10^(-6)))*B*q*(n/60)
```

```
*(10^(-3)))
19 disp(D,L,'Required dimensions of L and D(in mm) are=
')
```

Scilab code Exa 9.2 Find values of the 5 steps in a 6 stud starter for a dc shunt motor

```
1 //Caption: Find values of the 5 steps in a 6 stud
    starter for a d.c. shunt motor
2 //Exa:9.2
3 clc;
4 clear;
5 close;
6 P_o=3730//Output power(in watt)
7 V=200//Voltage supplied to motor(in volts)
8 e=88//Efficiency(in%)
9 P_i=P_o/(e/100)
10 I=P_i/V//Full load current
11 I_a=I//Neglecting field current
12 L=P_i-P_o
13 Cu=(1/2)*L//Copper loss is half the total loss(Given
    )
14 R_a=Cu/(I^2)
15 I_m=(2*I)//Maximum current is twice full load
    current(Given)
16 R_1=V/I_m
17 g=(R_1/R_a)^(1/5)
18 R_2=R_1/g
19 r1=R_1-R_2
20 R_3=R_2/g
21 r2=R_2-R_3
```

```
22 R_4=R_3/g
23 r3=R_3-R_4
24 R_5=R_4/g
25 r4=R_4-R_5
26 R_6=R_5/g
27 r5=R_5-R_6
28 disp(r5,r4,r3,r2,r1,'Required resistances r1,r2,r3,
r4,r5(in ohms)=')
```

Chapter 11

Three Phase Induction Motors Principle and Characteristics

Scilab code Exa 11.1 Find Number of poles and Percentage slip

```
1 //Caption: Find (a)Number of poles and (b)% slip
2 //Exa:11.1
3 clc;
4 clear;
5 close;
6 f=50//Frequency(in hertz)
7 n=960//Speed of induction motor on full load(in r.p.m)
8 n_s=1000//Synchronous speed(in r.p.m)
9 p=(f*120)/(n_s)
10 disp(p,'(a)Number of poles is=')
11 s=n_s-n
12 S=(s/n_s)*100
13 disp(S,'(b)%Slip is (in%)=')
```

Scilab code Exa 11.2 Find Speed of motor And Percentage Slip

```
1 //Caption: Find (a)Speed of motor (b)%Slip
2 //Exa:11.2
3 clc;
4 clear;
5 close;
6 p=6//Number of poles
7 f_s=50//Stator frequency(in c/s)
8 f_r=2//Rotor frequency(in c/s)
9 n_s=(120*f_s)/p
10 n=(f_r*120)/p
11 s=n_s-n
12 disp(s, '(a) Speed of motor(in r.p.m)=')
13 S=(n/n_s)*100
14 disp(S, '(b) %Slip (in %)=')
```

Scilab code Exa 11.3 Calculate Number of poles And Slip And Slip for full load torque if total resistance in rotor circuit is doubled

```
1 //Caption: Calculate (a)Number of poles (b)Slip (c)
           Slip for full load torque if total resistance in
           rotor circuit is doubled
2 //Exa:11.3
```

```

3 clc;
4 clear;
5 close;
6 n=970 //Speed of induction motor(in r.p.m)
7 f=50 //Frequency(in hertz)
8 n_s=1000 //Synchronous speed(in r.p.m)
9 p=(f*120)/n_s
10 disp(p, '(a) Number of poles=')
11 s=((n_s-n)/n_s)*100
12 disp(s, '(b) Slip (in%)=')
13 S=((s/100)*2)*100
14 disp(S, '(c) Required slip (in%)=')

```

Scilab code Exa 11.4 Calculate Mechanical power output And Torque And Maximum Torque And Speed at maximum torque And Power output when torque is maximum

```

1 //Caption: Calculate (a)Mechanical power output (b)
           Torque (c)Maximum Torque (d)Speed at maximum
           torque (e)Power output when torque is maximum
2 //Exa:11.4
3 clc;
4 clear;
5 close;
6 p=4 //Number of poles
7 V=440 //Voltage of motor(in volts)
8 f=50 //Frequency(in hertz)
9 n_s=1500 //Synchronous speed(r.p.m)
10 sp=1440 //Speed of motor at load(in r.p.m)
11 s=4 //Slip at full load(in %)
12 t=1.8 //Stator to rotor turns ratio

```

```

13 R_r=0.1 // Resistance of rotor per phase(in ohms)
14 X_r=0.8 //Reactance of rotor per phase at standstill(
    in ohms)
15 r_r=R_r*(t^2) //Rotor resistance referred to stator(
    in ohms)
16 x_r=X_r*(t^2) //Reactance of rotor at stanstill
    referred to stator(in ohms)
17 E=V/(sqrt(3))
18 P=((s/100)*(E^2)*r_r)/((r_r^2)+((s/100)^2)*(x_r^2))
19 T=(3*P)/(2*(%pi)*(n_s/60))
20 P_M=(3*P*sp)/n_s
21 disp(P_M, '(a) Mechanical power output(in watt)=')
22 disp(T, '(b) Torque(in N-m)=')
23 s_m=R_r/X_r
24 N=n_s*(1-s_m)
25 P_1=((s_m)*(E^2)*(r_r))/((r_r^2)+((s_m^2)*(x_r^2)))
26 T_m=(3*P_1)/(2*(%pi)*(n_s/60))
27 disp(T_m, '(c) Maximum torque(in N-m)=')
28 disp(N, '(d) Speed at maximum torque(in r.p.m)=')
29 P_o=(3*P_1*N)/n_s
30 disp(P_o, '(e) Output power at maximum torque(in watt)
    =')

```

Scilab code Exa 11.5 Find Speed of the motor And Speed at which torque will be maximum And Ratio of maximum to full load torque

```

1 //Caption:Find (a)Speed of the motor (b)Speed at
    which torque will be maximum (c)Ratio of maximum
    to full load torque
2 //Exa:11.5
3 clc;

```

```

4 clear;
5 close;
6 V=3300 //Voltage supplied to induction motor(in volts
    )
7 p=10 //Number of poles
8 f=50 //frequency(in hertz)
9 R_r=0.015 //Rotor resistance per phase(in ohms)
10 X_r=0.25 //Standstill reactance per phase(in ohms)
11 s=2.5 //Slip(in %)
12 n_s=(f*120)/p
13 n=n_s*(1-(s/100))
14 disp(n, '(a) Speed of the motor(in r.p.m)=')
15 S=R_r/X_r
16 N=n_s*(1-S)
17 disp(N, '(b) Speed at which torque will be maximum(in
    r.p.m)=')
18 T_f=(s/100)*R_r/((R_r^2)+(((s/100)^2)*(X_r^2)))
19 T_m=S*R_r/((R_r^2)+((S^2)*(X_r^2)))
20 R=T_m/T_f
21 disp(R, '(c) Ratio of maximum to full load torque=')

```

Scilab code Exa 11.6 Calculate Speed at which mechanical power from rotor will be maximum And Maximum power

```

1 //Caption: Calculate (a) Speed at which mechanical
    power from rotor will be maximum (b)Maximum power
2 //Exa:11.6
3 clc;
4 clear;
5 close;
6 p=4 //Number of poles

```

```

7 f=50 //Frequency (in hertz)
8 V=440 //Supplied voltage to induction motor (in volts)
9 R_r=0.1 //Rotor resistance per phase (in ohm)
10 X_r=0.8 //Rotor reactance at standstill per phase (in
    ohm)
11 t=1.3 //Ratio of stator turns per phase to rotor
    turns per phase
12 a=R_r/X_r
13 s=(-(a^2))+sqrt(1+(a^2))
14 n_s=120*f/p
15 N=n_s*(1-s)
16 disp(N, '(a) Required speed (in r.p.m)=')
17 r=R_r*t
18 x=X_r*t
19 E=V/sqrt(3)
20 P_m=(3*s*(E^2)*r*(1-s))/((r^2)+((s^2)+(x^2)))
21 disp(P_m, '(b) Maximum power (in watts)=')

```

Scilab code Exa 11.7 Find Current per phase in the rotor when rotor is at standstill and star connected impedance per phase is connected in series with rotor And when rotor runs at 3 percentage slip with short circuit at the slip rings

```

1 //Caption: Find Current per phase in the rotor (a)
    when rotor is at standstill and star connected
    impedance of 4.1+%i2 per phase is connected in
    series with rotor (b)when rotor runs at 3% slip
    with short circuit at the slip rings
2 //Exa:11.7
3 clc;
4 clear;

```

```

5 close;
6 V=69.28 //Induced e.m.f (in volts)
7 r=0.9 //Resistance of rotor per phase (in ohm)
8 x=6 //Standstill reactance of rotor per phase (in ohm)
9 z=4.1+(%i*2)
10 s=3 //Slip (in%)
11 V_r=V/sqrt(3)
12 R_r=r+real(z)
13 X_r=(%i*2)+(%i*x)
14 Z=R_r+X_r
15 I_r=V_r/Z
16 disp(I_r, '(a) Current when rotor is at standstill=')
17 E=(s/100)*V_r
18 Imp=r+(%i*(s/100)*x)
19 i_r=E/Imp
20 disp(i_r, '(b) Current when rotor runs at 3% slip=')

```

Scilab code Exa 11.8 Find Percentage reduction in stator voltage and the power factor of the rotor circuit

```

1 //Caption :Find (a)% reduction in stator voltage and
             (b) the power factor of the rotor circuit
2 //Exa:11.8
3 clc;
4 clear;
5 close;
6 R_r=0.02 //Rotor resistance per phase (in ohm)
7 X_r=0.1 //Rotor reactance per phase (in ohm)
8 s=4 //Slip (in%)
9 S=100-s
10 T_f=((s/100)*R_r)/((R_r^2)+(((s/100)^2)*(X_r^2)))

```

```

11 S_r=1-(.5*(S/100))
12 T=(S_r*R_r)/((R_r^2)+((S_r^2)*(X_r^2)))
13 Re=(1-sqrt(T_f/T))*100
14 disp(Re,'(a)% reduction in stator voltage(in %)=')
15 pf=R_r/(sqrt((R_r^2)+((S_r^2)*(X_r^2))))
16 disp(pf,'(b) Power factor=')

```

Scilab code Exa 11.9 Find the rotor copper loss per phase if motor is running at slip of 4 percent Mechanical power developed

```

1 //Caption :Find (a)the rotor copper loss per phase if
           motor is running at slip of 4% (b) Mechanical
           power developed
2 //Exa:11.9
3 clc;
4 clear;
5 close;
6 P_i=100000//Input power(in watt)
7 P_sc=2000//Stator copper loss(in watt)
8 s=4//slip (in %)
9 P_r=P_i-P_sc
10 P_rc=((s/100)*P_r)/3
11 disp(P_rc,'(a) Rotor copper lossper phase(in watt)=')
12 P_m=P_r-(P_rc*3)
13 disp(P_m,'(b) Mechanical power developed (in watt)=')

```

Scilab code Exa 11.10 Calculate Percentage slip And Rotor copper loss
And Output from the rotor And Efficiency

```
1 //Caption: Calculate (a)% slip (b)Rotor copper loss  
    (c)Output from the rotor (d)Efficiency  
2 //Exa:11.10  
3 clc;  
4 clear;  
5 close;  
6 V=440//Supplied voltage(in volts)  
7 f=50//frequency(in hertz)  
8 p=6//Number of poles  
9 n=960//Speed of motor(in r.p.m)  
10 P_i=50000//Input power(in watt)  
11 P_wf=1800//Winding and friction losses(in watt)  
12 P_s=1200//Stator losses(in watt)  
13 n_s=(120*f)/p  
14 S=((n_s-n)/n_s)*100  
15 disp(S, '(a)% slip=')  
16 P_r=P_i-P_s  
17 P_rc=(S/100)*P_r  
18 disp(P_rc, '(b)Rotor copper loss(in watt)=')  
19 P_o=P_r-P_rc-P_wf  
20 disp(P_o, '(c)Output of rotor(in watt)=')  
21 eff=(P_o/P_i)*100  
22 disp(eff, '(d)Efficiency (in%)=')
```

Scilab code Exa 11.11 Find Equivalent rotor current per phase And Stator current per phase And Power factor And Rotor input And Rotor copper losses And Torque And Mechanical power output from rotor And Stator input And Efficiency

```
1 //Caption :Find (a)Equivalent rotor current per phase  
           (b)Stator current per phase (c)Power factor (d)  
           Rotor input (e)Rotor copper losses (f)Torque (g)  
           Mechanical power output from rotor (h)Stator  
           input (i)Efficiency  
2 //Exa:11.11  
3 clc;  
4 clear;  
5 close;  
6 V=440 //Voltage supplied(in volts)  
7 p=8 //Number of poles  
8 f=50 //Frequency(in hertz)  
9 r1=0.2 //Stator resistance(in ohm)  
10 x1=1.2 //Stator reactance(in ohm)  
11 r2=0.3 //Equivalent resistance of rotor referred to  
           stator (in ohm)  
12 x2=1.2 //Equivalent reactance of rotor referred to  
           stator (in ohm)  
13 r_m=150 //Magnetising resistance(in ohms)  
14 x_m=18 //Magnetising reactance(in ohms)  
15 P_wf=750 //Winding and friction losses (in watt)  
16 s=0.04 //Slip  
17 n_s=(f*120)/(p*60)  
18 y1=1/r_m  
19 y2=1/(%i*x_m)
```

```

20 y3=1/((r2/s)+(%i*x2))
21 Y=y1+y2+y3
22 Z=1/Y
23 Z_t=Z+(r1+(%i*x1))
24 E=V*Z/(Z_t)
25 z3=1/y3
26 i2=E/z3
27 disp(i2, '(a) Rotor current per phase (in A)=')
28 i1=V/Z_t
29 disp(i1, '(b) Stator current per phase (in A)=')
30 pf=cosd(atand(-(imag(Z_t))/real(Z_t)))
31 disp(pf, '(c) Power factor=')
32 P_r=(i2*(conj(i2)))*(r2/s)
33 disp(P_r, '(d) Rotor input (in watt)=')
34 P_rc=(i2*(conj(i2)))*r2
35 disp(P_rc, '(e) Rotor copper loss (in watt)=')
36 T=3*P_r/(2*%pi*n_s)
37 disp(T, '(f) Torque (in N-m)=')
38 P_me=P_r-P_rc-(P_wf/3)
39 disp(P_me, '(g) Mechanical output from rotor (in watts
per phase)=')
40 P_st=V*(sqrt(i1*(conj(i1)))*pf
41 disp(P_st, '(h) Stator input (watts per phase)=')
42 eff=(P_me/P_st)*100
43 disp(eff, '(i) Efficiency (in %)=')

```

Scilab code Exa 11.12 Find Equivalent rotor current per phase And Stator current per phase And Power factor And Rotor input And copper losses And Torque And Mechanical power output from rotor And Stator input And Efficiency Solve it by APPROXIMATE equivalent circuit method

```

1 //Caption:Find (a)Equivalent rotor current per phase
    (b)Stator current per phase (c)Power factor (d)
    Rotor input (e)Rotor copper losses (f)Torque (g)
    Mechanical power output from rotor (h)Stator
    input (i)Efficiency .Solve it by APPROXIMATE
    equivalent circuit method
2 //Exa:11.12
3 clc;
4 clear;
5 close;
6 V=440 //Voltage supplied (in volts)
7 p=8 //Number of poles
8 f=50 //Frequency (in hertz)
9 r1=0.2 //Stator resistance (in ohm)
10 x1=1.2 //Stator reactance (in ohm)
11 r2=0.3 //Equivalent resistance of rotor referred to
    stator (in ohm)
12 x2=1.2 //Equivalent reactance of rotor referred to
    stator (in ohm)
13 r_m=150 //Magnetising resistance (in ohms)
14 x_m=18 //Magnetising reactance (in ohms)
15 P_wf=750 //Winding and friction losses (in watt)
16 s=0.04 //Slip
17 I2=V/((r1+(r2/s))+(%i*x1)+(%i*x2))
18 disp(I2, '(a) Equivalent rotor current per phase (in A)
    =')
19 y1=1/r_m
20 y2=1/(%i*x_m)
21 I_o=V*(y1+y2)
22 I_1=I2+I_o
23 disp(I_1, '(b) Stator current per phase (in A)=')
24 pf=cosd(atand(imag(I_1)/real(I_1)))
25 disp(pf, '(c) Power factor=')
26 P_r=(I2*conj(I2))*(r2/s)
27 disp(P_r, '(d) Rotor input (in watt)=')
28 P_rc=(I2*conj(I2))*r2
29 disp(P_rc, '(e) Rotor copper losses (in watts)=')
30 T=P_r/(2*%pi*((f*120)/(p*60)))

```

```

31 disp(T, '(f) Torque (in N-m)=')
32 P_me=P_r-P_rc-(P_wf/3)
33 disp(P_me, '(g) Mechanical power output from rotor (in
    watts per phase)=')
34 P_si=V*pf*(sqrt(I_1*conj(I_1)))
35 disp(P_si, '(h) Stator input (in watts per phase)=')
36 e=(P_me/P_si)*100
37 disp(e, '(i) Efficiency (in %)=')

```

Scilab code Exa 11.13 Find Equivalent rotor current And Stator current And Power factor And Stator input And Rotor input And Efficiency

```

1 //Caption :Find (a)Equivalent rotor current (b)Stator
    current (c)Power factor (d)Stator input (e)Rotor
    input (f)Efficiency
2 //Exa:11.13
3 clc;
4 clear;
5 close;
6 V=440 //Voltage supplied (in volts)
7 f=50 //frequency (in hertz)
8 Z_s=1.5+(%i*3) //Stator impedance per phase (in ohms)
9 Z_r=1.6+(%i*1) //Rotor impedance per phase (in ohms)
10 Z_m=3+(%i*40) //Magnetising impedance per phase (in
    ohms)
11 P_wf=300 //Friction and winding loss (in watt)
12 s=0.04 //Slip
13 Z=40+(%i*1)
14 z=Z*Z_m/(Z+Z_m)
15 Zt=z+Z_s
16 I1=(V/sqrt(3))/Zt

```

```

17 E=(V/sqrt(3))-(I1*Z_s)
18 I2=E/Z
19 disp(I2, '(a) Equivalent Rotor current (in A)=')
20 disp(I1, '(b) Stator current (in A)=')
21 pf=cosd(atand(imag(Zt)/real(Zt)))
22 disp(pf, '(c) Power factor=')
23 P_s=sqrt(3)*V*sqrt(I1*conj(I1))*pf
24 disp(P_s, '(d) Stator input (in watt)=')
25 P_r=3*(I2*conj(I2))*(real(Z_r)/s)
26 disp(P_r, '(e) Rotor input (in watt)=')
27 P_ro=P_r*(1-s)
28 P_me=P_ro-P_wf
29 e=(P_me/P_s)*100
30 disp(e, '(e) Efficiency (in%)=')

```

Chapter 12

Three Phase Induction Motor Operation And Testing

Scilab code Exa 12.1 Calculate No load power factor And Core friction loss And rm And power factor on short circuit And Equivalent impedance in series circuit And Rotor resistance referred to stator And Stator leakage reactance And Rotor leakage reactance referred to stator

```
1 //Caption : Calculate (a)No load power factor (b)Core  
and friction loss (c)r_m (d)power factor on short  
circuit (e)Equivalent impedance in series  
circuit (f)Rotor resistance referred to stator (g)  
(g)Stator leakage reactance (h)Rotor leakage  
reactance referred to stator  
2 //Exa:12.1  
3 clc;  
4 clear;  
5 close;  
6 P=3000 //Power of motor(in watt)  
7 V=415 //Voltage supplied(in volts)  
8 f=50 //Frequency(in hertz)  
9 p=6 //Number of poles  
10 pf=0.8 //Power factor  
11 I_n=3.5 //No load current(in A)
```

```

12 P_n=250 //Power input on no load test(in watt)
13 r_s=1.5 //Stator resistance per phase(in ohm)
14 V_r=115 //Reduced voltage applied at short circuit
    test(in volts)
15 I_s=13 //Current supplied on short circuit test(in A)
16 P_s=1660 //Voltage applied at short circuit test(in
    watt)
17 pfn=P_n/(sqrt(3)*V*I_n)
18 disp(pfn, '(a) Noload power factor=')
19 P_wf=P_n-(3*(I_n^2)*r_s)
20 disp(P_wf, '(b) Core and friction loss(in watt]=')
21 r_m=(V/sqrt(3))/(I_n*pfn)
22 disp(r_m, '(c) Resistance(in ohms]=')
23 pfs=P_s/(sqrt(3)*V_r*I_s)
24 disp(pfs, '(d) Power factor on short circuit=')
25 Ze=(V/sqrt(3))/((I_s*V)/V_r)
26 disp(Ze, '(e) Equivalent impedance in series circuit(
    in ohms]=')
27 R=(Ze*pfs)-r_s
28 disp(R, '(f) Rotor resistance referred to stator(in
    ohm]=')
29 X=(sqrt((Ze^2)-((Ze*pfs)^2)))
30 disp(X, '(g) Stator leakage reactance(in ohms]=')
31 x=X/2
32 disp(x, '(h) Rotor leakage reactance referred to
    stator(in ohms]=')

```

Scilab code Exa 12.2 Find Starting current And Starting torque

```

1 //Caption : Find (a) Starting current (b) Starting
    torque

```

```

2 //Exa:12.2
3 clc;
4 clear;
5 close;
6 P=3000 //Power of motor(in watt)
7 V=415 //Voltage supplied(in volts)
8 f=50 //Frequency(in hertz)
9 p=6 //Number of poles
10 pf=0.8 //Power factor
11 pfs=0.64 //Power factor on short circuit
12 pfn=0.1 //No load power factor
13 I_n=3.5 //No load current(in A)
14 P_n=250 //Power input on no load test(in watt)
15 r_s=1.5 //Stator resistance per phase(in ohm)
16 V_r=115 //Reduced voltage applied at short circuit
    test(in volts)
17 I_s=13 //Current supplied on short circuit test(in A)
18 P_s=1660 //Voltage applied at short circuit test(in
    watt)
19 n_s=1000 //Synchronous speed(in r.p.m)
20 R2=1.77 //Rotor resistance referred to stator(in ohms
    )
21 I_st=I_s*V/(V_r)
22 disp(I_st, '(a) Starting current(in A)=')
23 I_i=I_st*(cosd(pfs)+(%i*(sind(pfs))))
24 I_o=I_n*(cosd(pfn)+(%i*(sind(pfn))))
25 I_2=I_i-I_o
26 P_ri=3*(I_2*conj(I_2))*R2
27 T=P_ri/(2*%pi*(n_s/60))
28 disp(T, '(b) Starting torque(in N-m)=')

```

Scilab code Exa 12.5 Find starting current in terms of full load current

```
1 //Caption:Find starting current in terms of full  
    load current  
2 //Exa:12.5  
3 clc;  
4 clear;  
5 close;  
6 s=0.04 //Slip  
7 a=1 //Starting torque T_st/Full load torque(T_fl) are  
    equal  
8 I_s=sqrt(a/s)  
9 disp(I_s,'Starting current is (below)times the full  
    load current=')
```

Scilab code Exa 12.7 Find starting torque in terms of full load torque

```
1 //Caption:Find starting torque in terms of full load  
    torque  
2 //Exa:12.7  
3 clc;  
4 clear;  
5 close;  
6 s=0.03 //slip  
7 a=2.5 //Ratio of supply current to full load current  
8 b=5 //Ratio of short circuit current to full load  
    current  
9 x=sqrt(a/b)  
10 T=(x^2)*(b^2)*s  
11 disp(T,'Starting torque is (below) times the full  
    load torque=')
```

Scilab code Exa 12.8 Find the Percentage tappings required

```
1 //Caption :Find the % tappings required
2 //Exa:12.8
3 clc;
4 clear;
5 close;
6 s=0.04 //Slip
7 a=4 //Ratio of short circuit current to full load
      current
8 b=40 //Starting torque to full load torque(in%)
9 x=sqrt((b/100)/(s*(a^2)))*100
10 disp(x, '% tappings required is (in%)=')
```

Scilab code Exa 12.9 Find the line current at start

```
1 //Caption :Find the line current at start
2 //Exa:12.9
3 clc;
4 clear;
5 close;
6 P=5000 //Power supplied to induction motor(in watts)
7 V=415 //Voltage supplied to motor(in volts)
8 f=50 //frequency(in hertz)
```

```
9 e=0.85 //Efficiency
10 pf=0.8 //Power factor lagging
11 b=5 //Ratio of short circuit current to full load
      current
12 P_i=P/e
13 I_fl=P_i/(sqrt(3)*V*pf)
14 I_l=(1/3)*b*I_fl
15 disp(I_l,'Line current (in A)=')
```

Scilab code Exa 12.11 Calculate external resistance per phase

```
1 //Caption : Calculate external resistance per phase
2 //Exa:12.11
3 clc;
4 clear;
5 close;
6 p=6 //Number of poles
7 f=50 //Frequency (in hertz)
8 r=0.25 //Resistance per phase (in ohms)
9 n_1=965 //Speed on full load (in r.p.m)
10 n_2=800 //Reduced speed (in r.p.m)
11 n_s=(120*f)/p
12 s_1=(n_s-n_1)/n_s
13 s_2=(n_s-n_2)/n_s
14 R=((s_2*r)/s_1)-r
15 disp(R,'Required external resistance per phase (in
      ohms)=')
```

Scilab code Exa 12.12 Find the dimensions of D and L

```
1 //Caption :Find the dimensions of D and L
2 //Exa:12.12
3 clc;
4 clear;
5 close;
6 P=7.5 //Power of induction motor(in KW)
7 p=4 //Number of poles
8 f=50 //frequency(in hertz)
9 V=415 //Voltage applied of motor(in volts)
10 e=0.88 //Efficiency
11 pf=0.87 //Power factor
12 b=2.5 //Ratio of pull out torque to full load torque
13 c=1.75 //Ratio of starting to full load torque
14 n=1440 //Speed of motor(in r.p.m)
15 ac=23000 //Ampere conductors per meter
16 k=0.955
17 B=0.45 //flux per pole(in wb/m^2)
18 n_s=(120*f)/(60*p)
19 S=P/(e*pf)
20 D=165 //Choosing (in mm)
21 L=(S*(10^3))/(1.11*k*(%pi^2)*B*ac*n_s*(10^(-3))*(D
    ^2)*(10^(-6)))
22 disp(L,D,'D and L(in mm) are=')
```

Chapter 13

Synchronous Machines

Scilab code Exa 13.1 Find the frequency of voltage generated

```
1 //Caption :Find the frequency of voltage generated
2 //Exa:13.1
3 clc;
4 clear;
5 close;
6 p=16 //Number of poles
7 n=375 //Speed of alternator (in r.p.m)
8 f=(p*n)/120
9 disp(f, 'Frequency of voltage generated (in c/s)=')
```

Scilab code Exa 13.2 Find Speed And number of poles

```
1 //Caption: Find (a) speed (b) number of poles
2 //Exa:13.2
3 clc;
```

```
4 clear;
5 close;
6 f1=25 //Frequency of motor(in hertz)
7 f2=60 //Frequency of generator(in hertz)
8 p=10 //Number of poles
9 N=(120*f1)/p
10 disp(N, '(a) Speed(in r.p.m)=')
11 P=(f2*120)/(N)
12 disp(P, '(b) Number of poles=')
```

Scilab code Exa 13.3 Find distribution factor of winding

```
1 //Caption:Find distribution factor of winding
2 //Exa:13.3
3 clc;
4 clear;
5 close;
6 ns=18 //Number of slots
7 ph=3 //Number of phases
8 p=2 //Number of poles
9 m=ns/(ph*p)
10 P_p=ns/p
11 theta=180/P_p
12 k_b=sind(m*(theta/2))/(m*sind(theta/2))
13 disp(k_b, 'Distribution factor=')
```

Scilab code Exa 13.4 Find coil span factor

```
1 //Caption :Find coil span factor
2 //Exa:13.4
3 clc;
4 clear;
5 close;
6 s=9//Number of slots
7 theta=180/s
8 k_p=cosd(theta/2)
9 disp(k_p , 'Coil span factor=')
```

Scilab code Exa 13.5 Find frequency And Phase emf And Line emf

```
1 //Caption :Find (a)frequency (b)Phase e.m.f (c)Line e
     .m.f
2 //Exa:13.5
3 clc;
4 clear;
5 close;
6 ph=3//Number of phases
7 p=16//Number of poles
8 sl=144//Number of slots
9 cs=10//Number of conductors per slot
```

```

10 B=0.04 //Flux per pole(in wb)
11 n=375 //Speed of alternator(in r.p.m)
12 C_s=160 //Coil Span(in degrees)
13 f=(p*n)/120
14 disp(f, '(a) Frequency (in hertz)=')
15 ct=(sl*cs)/2
16 nt=ct/ph
17 m=sl/(p*ph)
18 P_p=sl/p
19 theta=180/P_p
20 k_b=sind(m*(theta/2))/(m*sind(theta/2))
21 k_p=cosd(theta/2)
22 E_ph=4.44*B*f*nt*k_b*k_p
23 disp(E_ph, '(b) Phase e.m.f (in volts)=')
24 E_l=sqrt(3)*E_ph
25 disp(E_l, '(c) Line e.m.f (in volts)=')

```

Scilab code Exa 13.6 Find number of armature conductors in series per phase

```

1 //Caption :Find number of armature conductors in
           series per phase
2 //Exa:13.6
3 clc;
4 clear;
5 close;
6 p=10 //Number of poles
7 ph=3 //Number of phases
8 n=600 //Speed of alternator(in r.p.m)
9 sl=90 //Number of slots
10 Vl=6600 //Line voltage(in volts)

```

```

11 B=0.1 //Flux per pole(in wb)
12 cs=160 //Coil span(in degrees)
13 kb=0.9597 //Distribution factor
14 kp=0.9848 //Pitch factor
15 v_ph=V1/sqrt(3)
16 f=(p*n)/120
17 m=s1/(p*ph)
18 T=2*v_ph/(4.44*kb*kp*B*f)
19 disp(T,'Number of armature conductors in series per
phase=')

```

Scilab code Exa 13.12 Calculate synchronous reactance and synchronous impedance per phase

```

1 //Caption : Calculate synchronous reactance and
           synchronous impedance per phase
2 //Exa:13.12
3 clc;
4 clear;
5 close;
6 V=3300 //Voltage of alternator(in volts)
7 f=50 //Frequency(in hertz)
8 r=0.4 //Effective resistance per phase(in ohm)
9 I_f=20 //Field current(in ohms)
10 I_f1=300 //Full load current(in A)
11 e=1905 //Voltage induced on open circuit(in volts)
12 Zs=e/I_f1
13 Xs=sqrt((Zs^2)-(r^2))
14 disp(Zs,Xs,'Synchronous reactance and impedance(in
ohms)=')

```

Scilab code Exa 13.13 Estimate terminal voltage for Same excitation And Load current at power factor lagging

```
1 //Caption:Estimate terminal voltage for (a) same
   excitation (b)Load current at 0.8 power factor
   lagging
2 //Exa:13.13
3 clc;
4 clear;
5 close;
6 P=1000 //Power of alternator (in KVA)
7 V=3300 //Voltage of alternator (in volts)
8 ph=3 //Phase of alternator
9 pf=0.8 //Power factor lagging
10 r=0.5 //Resistance per phase(in ohms)
11 x=6.5 //Reactance per phase(in ohms)
12 V_ph=V/sqrt(3)
13 I=(P*1000)/(\sqrt(3)*V)
14 Eo=\sqrt(((V_ph+(I*r*pf)+(I*x*sind(acosd(pf))))^2)
           +(((I*x*pf)-(I*r*sind(acosd(pf))))^2))
15 disp(Eo, '(a) Required terminal voltage (in volts)=')
16 v=\sqrt((Eo^2)-(((I*r*sind(acosd(pf)))+(I*x*pf))^2)
           +((I*x*sind(acosd(pf)))-(I*r*pf)))
17 disp(v, '(b) Required voltage at given load current (in
   volts)=')
```

Chapter 14

Synchronous Machines Generators

Scilab code Exa 14.1 Find the excitation voltage in per unit

```
1 //Caption :Find the excitation voltage in per unit
2 //Exa:14.1
3 clc;
4 clear;
5 close;
6 pf=0.9 //Power factor
7 Xd=1 //Direct axis synchronous reactance (in per unit)
8 Xq=0.6 //Quadrature axis synchronous reactance (in per
unit)
9 V=1 //Terminal voltage (in volts)
10 ang=49 //Phase angle between Ia and excitation
voltage (in degrees)
11 Ia=0.9-(%i*0.436) //Armature current (in A)
12 v=(%i)*Ia*Xq
13 E=V+v
14 Id=sqrt(Ia*conj(Ia))*sind(ang)
15 Iq=sqrt(Ia*conj(Ia))*cosd(ang)
16 Ef=sqrt(E*conj(E))+(Id*(Xd-Xq))
17 disp(Ef , ' Excitation voltage (in per unit)=')
```

Scilab code Exa 14.2 Find regulation by Two reaction method and Synchronous impedance method

```
1 //Caption :Find regulation by (a)Two reaction method ,  
    and (b)Synchronous impedance method  
2 //Exa:14.2  
3 clc;  
4 clear;  
5 close;  
6 pf=0.9 //Power factor  
7 Xd=1 //Direct axis synchronous reactance(in per unit)  
8 Xq=0.6 //Quadrature axis synchronous reactance(in per  
    unit)  
9 V=1 //Terminal voltage(in volts)  
10 ang=49 //Phase angle between Ia and excitation  
    voltage(in degrees)  
11 Ia=0.9-(%i*0.436) //Armature current(in A)  
12 E=1.6742083 //Excitation voltage(in per unit)  
13 re=(E-V)*100/V  
14 disp(re , '(a) Regulation by two reaction method (in%)='  
    )  
15 Ef=V+(%i*Ia*Xd)  
16 RE=((sqrt(Ef*conj(Ef)))-V)*100/V  
17 disp(RE , '(b) Regulation by Synchronous impedance  
    method (in%)=')
```

Scilab code Exa 14.3 Find Regulation and resultant excitation

```
1 //Caption :Find Regulation and resultant excitation
2 //Exa:14.3
3 clc;
4 clear;
5 close;
6 pf=0.8 //Power factor lagging
7 P=1000 //Power of Synchronous generator (in KVA)
8 Eo=1.25 //No load voltage (in per unit)
9 V=6600 //Voltage of Synchronous generator (in volts)
10 f=50 //Frequency (in hertz)
11 Fe=1 //Field excitation to produce terminal voltage (
    in per unit)
12 Fa=1 //Field excitation to produce full load current (
    in per unit)
13 Ft=sqrt(((Fe+(Fa*sind(acosd(pf))))^2)+((Fa*pf)^2))
14 Re=(Eo-Fa)*100/Fa
15 disp(Re,Ft,'Resultant excitation (in per unit) and
regulation (in %)=')
```

Scilab code Exa 14.5 Find the regulation of the machine

```
1 //Caption :Find the regulation of the machine
```

```

2 //Exa:14.5
3 clc;
4 clear;
5 close;
6 Vf=400 //Full load voltage(in volts)
7 Vr=480 //No load voltage(in volts)
8 Re=(Vr-Vf)*100/Vf
9 disp(Re , 'Regulation of the machine(in %)=')

```

Scilab code Exa 14.6 Find Synchronising power on full load And Synchronising torque

```

1 //Caption :Find (a) Synchronising power on full load (
2 //Exa:14.6
3 clc;
4 clear;
5 close;
6 P=5000 //Power of an alternator (in KVA)
7 f=50 //Frequency (in hertz)
8 p=6 //Number of poles
9 V=11000 //Voltage of alternator (in volts)
10 pf=0.8 //Power factor
11 c=3 //Mechanical degree of displacement (in degrees)
12 Xs=5 //Synchronous reactance per phase (in ohms)
13 Vph=V/sqrt(3)
14 ns=(120*f)/p
15 If=(P*1000)/(sqrt(3)*V)
16 E=sqrt(((Vph*pf)^2)+(((Vph*sind(acosd(pf)))+(If*Xs))^2))
17 a=atand(((Vph*sind(acosd(pf)))+(If*Xs))/(Vph*pf))

```

```

18 b=a-acosd(pf)
19 Ps=(E*Vph*cosd(b)*sind(c))/Xs
20 disp(Ps , '(a) Synchronising Poweron full load (in watt/
    phase)=')
21 Ts=(Ps*3)/(2*pi*(ns/60))
22 disp(Ts , '(b) Synchronising Torque (in Nm)=')

```

Scilab code Exa 14.9 Find Armature current of second machine And Power factor of each machine

```

1 //Caption :Find (a)Armature current of second machine
            (b)Power factor of each machine
2 //Exa:14.9
3 clc;
4 clear;
5 close;
6 L=1000 //Total load(in KW)
7 V=6600 //Total voltage(in volts)
8 pf=0.8 //Power factor
9 Ia=50 //Armature current(in A)
10 L1=L/2
11 Ia1=(L1*1000)/(sqrt(3)*V)
12 pf1=Ia1/Ia
13 a1=acosd(pf1)
14 b=tand(a1)
15 P1=L1*b
16 P1=L*tand(acosd(pf))
17 P2=P1-P1
18 pf2=cosd(atand(P2/L1))
19 Ia2=Ia1/pf2
20 disp(Ia2 , '(a) Armature current of second machine(in A

```

```
        )=')  
21 disp(pf1, pf2, '(b) Power factor of both machines=')
```

Scilab code Exa 14.10 Find Load supplied by second machine and its power factor And Power factor of total load

```
1 //Caption:Find (a)Load supplied by second machine  
    and its power factor (b)Power factor of total  
    load  
2 //Exa:14.10  
3 clc;  
4 clear;  
5 close;  
6 P1=300 //Lighting load (in KW)  
7 P2=500 //Industrial load (in KW)  
8 P3=200 //Industrial load (in KW)  
9 P4=100 //Load (in KW)  
10 Pa=500 //Power supplied by first machine (in KW)  
11 pf1=0.8  
12 pf2=0.707  
13 pf3=0.9  
14 pfa=0.8  
15 La=P1+P2+P3+P4  
16 Lr=(P2*tand(acosd(pf1)))+(P3*tand(acosd(pf2)))+(P4*  
      tand(acosd(pf3)))  
17 Pb=La-Pa  
18 Pr1=Pa*(tand(acosd(pfa)))  
19 Pc=Lr-Pr1  
20 pfb=cosd(atand(Pc/Pb))  
21 pfl=cosd(atand(Lr/La))  
22 disp(pfb,Pb, '(a) Load supplied by second machine (in
```

KW) and its power factor=')
23 **disp**(pf1 , '(b) Power factor of load=')

Chapter 15

Synchronous Motors

Scilab code Exa 15.6 Find Input power in KVA And Power factor

```
1 //Caption :Find (a)Input power(in KVA) (b)Power  
    factor  
2 //Exa:15.6  
3 clc;  
4 clear;  
5 close;  
6 V=440 //Voltage of circuit(in volts)  
7 f=50 //Frequency(in hertz)  
8 I=30 //Current taken by circuit(in A)  
9 pf=0.8 //Power factor  
10 P1=10 //Load supplied(in KW)  
11 e=0.85 //Efficiency  
12 Pi=P1/e  
13 Ii=Pi*1000/(sqrt(3)*V)  
14 Ia=I*pf  
15 Ir=I*sind(acosd(pf))  
16 i=Ii+Ia  
17 It=sqrt((Ii^2)+(Ir^2))  
18 pfm=Ii/It  
19 Wi=sqrt(3)*V*It/(1000)  
20 disp(Wi , '(a) Input power(in KVA)=')
```

```
21 disp(pf, '(b) Power factor=')
```

Scilab code Exa 15.7 Find how much KVA should be supplied by synchronous motor And Power factor of synchronous motor

```
1 //Caption:(a)How much KVA should be supplied by
    synchronous motor (b)Power factor of synchronous
    motor
2 //Exa:15.7
3 clc;
4 clear;
5 close;
6 Pm=40 //Power absorb by motor(in Kw)
7 Pl=300 //Load connected in parallel with motor(in KW)
8 pf=0.85 //Power factor of motor
9 pfl=0.9 //Power factor on load
10 Pt=Pl+Pm
11 Pr=Pt*tand(acosd(pfl))
12 Pri=Pl*tand(acosd(pf))
13 Ps=Pri-Pr
14 pf=cosd(atand(Ps/Pm))
15 disp(Ps, '(a) Power supplied by synchronous motor(in
    KVA)=')
16 disp(pf, '(b) Power factor of synchronous machine=')
```

Scilab code Exa 15.8 Find Power alternator can supply And Power factor of synchronous motor And Load taken by motor

```
1 //Caption: (a)Power alternator can supply (b)Power  
    factor of synchronous motor (c)Load taken by  
    motor  
2 //Exa:15.8  
3 clc;  
4 clear;  
5 close;  
6 P=500 //Load supplied by alternator (inKW)  
7 pf=0.8 //Power factor  
8 e=0.9  
9 L=P/pf  
10 Ps=L-P  
11 disp(Ps, '(a)Power alternator can supply (in KW)=')  
12 Pr=P*tand(acosd(pf))  
13 pfm=cosd(atand(Pr/Ps))  
14 disp(pfm, '(b)Power factor of synchronous motor=')  
15 l=Ps*e  
16 disp(l, '(c)Load taken by motor (in Kw)=')
```

Scilab code Exa 15.9 Find efficiency of machine

```
1 //Caption:Find efficiency of machine  
2 //Exa:15.9  
3 clc;  
4 clear;  
5 close;  
6 P=50000 //Power of alternator (in KVA)  
7 V=11 //Voltage of alternator (in Kv)
```

```
8 pf=0.8 //Power factor
9 r=0.01 //Resistance of stator winding per phase (in
    ohms)
10 Wc=150 //Copper loss (in KW)
11 Wf=100 //Friction loss (in KW)
12 Ww=250 //Winding loss (in KW)
13 Wco=200 //Core loss (in KW)
14 We=15 //Excitor loss (in KW)
15 Is=(P*1000)/(\sqrt(3)*V*1000)
16 Ps=(Is^2)*3*(r/1000)
17 Ws=(0.5*Ps)
18 Lt=Ps+Ws+Wc+Wf+Ww+Wco+We
19 Po=P*pf
20 Pi=Po+Lt
21 e=Po*100/Pi
22 disp(e, 'Efficieny of machine (in %)=')
```

Chapter 16

Single Phase Induction Motors

Scilab code Exa 16.1 Find Input Current And Power factor And Input power And Torque due to forward revolving field And Torque due to backward revovlving field And Net torque and Output And Efficiency

```
1 //Caption:Find (a)Input Current (b)Power factor (c)
    Input power (d)Torque due to forward revolving
    field (e)Torque due to backward revovlving field
    (f)Net torque (g)Output And (h)Efficiency
2 //Exa:16.1
3 clc;
4 clear;
5 close;
6 Pi=750 //Power of Single phase induction motor(in
    Watts)
7 p=4 //Number of poles
8 f=50 //Frequency(in hertz)
9 V=230 //Voltage supplied to motor(in volts)
10 R1=2 //Resistance of stator(in ohm)
11 X1=2.6 //Reactance of stator(in ohm)
12 Wf=25 //Friction and winding loss(in Watts)
13 R2=3.8 //Resistance of rotor(in ohm)
14 X2=2.6 //Reactance of rotor(in ohm)
15 Xm=56 //Magnetising Reactance(in ohms)
```

```

16 r2=1.9 //Imaginary resistance of rotor (in ohm)
17 x2=1.3 //Imaginary reactance of rotor (in ohm)
18 xm=28 //Imaginary magnetising reactance (in ohm)
19 s=0.05 //Slip
20 Z1=R1+(%i*X1)
21 Z2=((%i*xm)*((r2/s)+(%i*x2)))/((r2/s)+(%i*(x2+xm)))
22 Z3=((%i*xm)*((r2/(2-s))+(%i*x2)))/((r2/(2-s))+(%i*(x2+xm)))
23 Z=Z1+Z2+Z3
24 I=V/Z
25 disp(I, '(a) Input Current (in A)=')
26 pf=cosd(atand(imag(Z)/real(Z)))
27 disp(pf, '(b) Power factor=')
28 Wp=V*pf*sqrt(I*conj(I))
29 disp(Wp, '(c) Input power (in watts)=')
30 z2=sqrt(((r2/s)^2)+((x2)^2))
31 v2=sqrt(I*conj(I))*sqrt(Z2*conj(Z2))
32 i2=v2/z2
33 z3=sqrt(((r2/(2-s))^2)+((x2)^2))
34 v3=sqrt(I*conj(I))*sqrt(Z3*conj(Z3))
35 i3=v3/z3
36 Tf=((i2)^2)*(r2/s)
37 disp(Tf, '(d) Torque due to forward field (in Nm)=')
38 Tb=(i3^2)*(r2)/(2-s)
39 disp(Tb, '(e) Torque due to backward field (in Nm)=')
40 T=Tf-Tb
41 disp(T, '(f) Torque (in Nm)=')
42 Wo=(T*(1-s))-Wf
43 disp(Wo, '(g) Output (in Watts)=')
44 e=(Wo/Wp)*100
45 disp(e, '(h) Efficiency (in %)=')

```

Scilab code Exa 16.2 Find equivalent circuit resistance

```
1 //Caption:Find equivalent circuit resistance
2 //Exa:16.2
3 clc;
4 clear;
5 close;
6 Wc=60//Core loss (in watts)
7 a=90//Voltage across first rotor is 90% of applied
   voltage (in %)
8 V=230//Voltage applied to motor (in volts)
9 v=V*(a/100)
10 Ic=Wc/v
11 rc=v/Ic
12 disp(rc,'Equivalent circuit resistance (in ohms)=')
```

Chapter 17

AC Commutator Motors

Scilab code Exa 17.1 Find Speed And Power factor of motor

```
1 //Caption :Find ( a ) Speed ( b ) Power factor of motor
2 //Exa:17.1
3 clc;
4 clear;
5 close;
6 r=25 //Resistance of motor(in ohms)
7 P=2 //Number of poles
8 l=0.4 //Inductance of motor(in henry)
9 n=1800 //Speed of motor(in r.p.m)
10 V=230 //Voltage supplied(in volts)
11 I1=1 //Load current(in A)
12 f=50 //Frequency(in hertz)
13 fr=(P*n)/120
14 Eb=V-(r*I1)
15 Er=Eb/fr
16 fac=(sqrt((V^2)-((I1*2*(%pi)*f*l)^2)-(I1*r))/Er
17 n=fac*(120/P)
18 disp(n, '(a) Speed (in rpm)=')
19 pf=sqrt((V^2)-((I1*2*(%pi)*f*l)^2))/V
20 disp(pf, '(b) Power factor=')
```
