

Vane Angle =9.0430611 degrees

Work Done =1559.046 KW/sec

Manometric Efficiency =60.044917 Percentage